



TECHNICAL SERVICE BULLETIN

FHEV/PHEV - Intermittent 12V Battery Drain When The Ignition Is Turned Off

24-2288

12 September
2024

Model:

Ford 2023 Escape	Engine: 2.5L FHEV Engine: 2.5L PHEV
Lincoln 2023 Corsair	Engine: 2.5L PHEV

Markets: North American markets only

Issue: Some 2023 Escape/Corsair equipped with 2.5L FHEV or 2.5L PHEV powertrain may exhibit an intermittent 12V battery drain condition when the ignition is turned off. This may be due to the HVAC control module that keeps the CAN bus active. To correct this condition, follow the Service Procedure to reprogram the GWM.

Action: Follow the Service Procedure to correct the condition on vehicles that meet all of the following criteria:

- 2023 Escape/Corsair equipped with a FHEV/ PHEV powertrain
- Intermittent 12V battery drain condition when the ignition is turned off

Parts - Parts To Inspect And Replace Only If Necessary

Service Part Number	Claim Quantity	Package Order Quantity	Number in Package	Description
BXT-99RT4-A	Only If Necessary	Only If Necessary	1	12V Battery (Escape 2.5L FHEV/PHEV)
BAGM-48H6-760	Only If Necessary	Only If Necessary	1	12V Battery (Corsair 2.5L PHEV)

Warranty Status: Eligible under provisions of New Vehicle Limited Warranty (NVLW)/Emissions Warranty/Service Part Warranty (SPW)/Service Part New Vehicle (SPNV)/Extended Service Plan (ESP) coverage. Limits/policies/prior approvals are not altered by a TSB. NVLW/Emissions Warranty/SPW/SPNV/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2023 Escape/Corsair 2.5L FHEV/PHEV: Check Battery State Of Charge And Reprogram The Appropriate Modules As Required By The Software Update And Service Procedure (Do Not Use With Any Other Labor Operations)	MT242288	Actual Time

Repair/Claim Coding

Causal Part:	14G490
Condition Code:	04

Service Procedure

NOTE: The time required to complete this procedure varies depending on several factors including the number of module software updates required, available internet bandwidth, USB flash drive variability, and the potential that CAN flashing (software update via the DLC with FDRS) may be required. Connect to the internet with an ethernet cable, use a USB 3.2 Gen 2 or higher flash drive. When performing USB software updates, using high speed USB ports on the laptop is recommended for faster file transfer.

1. Start an FDRS session and navigate to Toolbox tab > Datalogger > body control module (BCM) and select the BATT_SOC_PID. Verify the PID reads 50% or higher.

NOTE: Connecting the battery charger negative clamp directly to the battery negative terminal might result in the SOC_PID not immediately reflecting the improvement from charging.

(1). If SOC is less than 50%, charge the battery by attaching the battery charger's negative clamp to the engine or chassis ground and not the negative battery terminal. Refer to WSM, Section 414-01.

(2). If the battery is unable to achieve a 50% SOC, use the Rotunda GRX-3590 or DCA-8000 testers to verify if replacement is required.

- If the battery does not need to be replaced, disconnect the Rotunda charger and perform a BMS reset using the FDRS scan tool.
- If the battery is replaced, fully charge the new battery, disconnect the Rotunda charger and perform a BMS reset using the FDRS scan tool.

2. Reconnect the battery charger and set it to maintain a vehicle voltage of 12.6-13.6 volts. A low battery SOC while performing a software update to any module may result in a repeat "Restart Required" message in the vehicle's center display screen or a message on the FDRS saying "Part Number Validation Failed" or "DID Validation Failed".

3. Is there a software update available for any of the following modules?

- GWM
- APIM
- TCU

(1). Yes - proceed to Step 4.

(2). No - this article does not apply.

4. Prepare to update the software for the GWM, APIM and TCU.

(1). A 32GB or larger USB flash drive is required for GWM, APIM and TCU software updates. USB 3.2 Gen 2 or higher is recommended for faster file transfer on both the computer port and the USB drive.

(2). Make sure the USB flash drive being used is formatted correctly. To see the available drives, hold down the Windows icon keyboard key and press the E keyboard key. Right click on the USB flash drive and select Properties. If File System under the General tab is not exFAT, the drive must be formatted.

(3). To format the USB flash drive:

- Right click on the USB flash drive.
- Select Format, select exFAT for the File System
- Select Default Allocation Size for the Allocation Unit Size.

(4). De-selecting Quick Format is not necessary and results in a lengthier operation.

5. Using the FDRS, begin module programming by selecting the "SW Updates" tab. Follow all on-screen instructions carefully.

6. When prompted, connect the USB flash drive to the FDRS.

7. When prompted by the FDRS, safely remove/eject the USB flash drive from the FDRS. Start the vehicle (KOER) then connect the USB flash drive to the USB media hub to install the software into the module. When the USB software update begins, the center display screen displays a message stating "Do Not Remove USB". The update may take 10 minutes or longer to complete.

NOTE: It may take up to 5 minutes for the vehicle to recognize the USB flash drive with software update.

8. When the vehicle's center display screen prompts to restart the vehicle:

(1). Turn the vehicle OFF.

(2). Wait 10 minutes.

(3). Restart the vehicle (KOER). The update is still in process at this time.

9. Follow FDRS on-screen prompts to complete the update.

NOTE: It may take up to 5 minutes before "Update Successful" appears in the vehicle's center display screen. After 5 minutes if "Update Successful" pop-up is not shown on the center display screen, remove the

USB flash drive and select YES on the FDRS prompt stating “Was The USB Update Successful” (FDRS verifies if the module software update was successfully installed on the module).

10. Perform the software update for the GWM. Follow all update screens. If there is no GWM software update available, proceed to Step 11.

(1). Follow the center display screen prompts.

(2). Follow FDRS prompts to complete the GWM programming.

- Once the pop up stating "Update Successful" appears in the center display screen, select Close, remove the USB flash drive from the USB media hub, and select Yes on FDRS indicating the update installed successfully. This initiates the remaining automated configuration steps and reports the module software part numbers and application software levels to the Ford online database. Failure to follow this step results in an inaccurate database as well as omitted, improperly installed, or improperly configured applications (features) such as navigation (if equipped). It is normal for the module to reset during this step.

(3). Perform a network test using the FDRS scan tool.

(4). Proceed to Step 11.

11. Perform the software update for the APIM. Follow all update screens. If there is no APIM software update available, proceed to Step 12.

(1). Follow the center display screen prompts.

(2). Follow FDRS prompts to complete the APIM programming.

- Once the pop up stating "Update Successful" appears in the center display screen, select Close, remove the USB flash drive from the USB media hub, and select Yes on FDRS indicating the update installed successfully. This initiates the remaining automated configuration steps and reports the module software part numbers and application software levels to the Ford online database. Failure to follow this step results in an inaccurate database as well as omitted, improperly installed, or improperly configured applications (features) such as navigation (if equipped). It is normal for the module to reset during this step.

(3). Perform a network test using the FDRS scan tool.

(4). Proceed to Step 12.

12. Perform the software update for the TCU. Follow all update screens. If there is no TCU software update available, proceed to Step 13.

(1). Follow the center display screen prompts.

(2). Follow FDRS prompts to complete the TCU programming.

- Once the pop up stating "Update Successful" appears in the center display screen, select Close, remove the USB flash drive from the USB media hub, and select Yes on FDRS indicating the update installed successfully. This initiates the remaining automated configuration steps and reports the module software part numbers and application software levels to the Ford online database. Failure to follow this step results in an inaccurate database as well as omitted, improperly installed, or improperly configured applications (features) such as navigation (if equipped). It is normal for the module to reset during this step.

13. Perform a network test using the FDRS scan tool.

14. Are there any updates available for the GWM, APIM, and/or TCU?

(1). Yes - proceed to Step 10.

(2). No - repair is complete.