

Service Engineering Operations Customer Service Division Ford Motor Company PO Box 1904 Dearborn, Michigan 48121

September 11, 2024

TO: All U.S. Ford and Lincoln Dealers

SUBJECT: NEW VEHICLE RECOMMENDED DELIVERY HOLD

Customer Satisfaction Program 24B27 - Supplement #3

Certain 2021-2024 Super Duty and 2021-2025 Model Year Econoline Ambulance and

Shuttle Bus Package Equipped With a 6.8L or 7.3L Gasoline Engine

Powertrain Control Module (PCM) Software Update

REF: NEW VEHICLE RECOMMENDED DELIVERY HOLD

Customer Satisfaction Program 24B27 - Supplement #2

Dated June 22, 2024

New! REASON FOR THIS SUPPLEMENT

- **Software Availability Update:** Software is now available to repair 2021-2022 Model Year Super Duty vehicles. The service action has been updated accordingly.
- **Technical Information:** IDS level for the software update has been corrected.

PROGRAM TERMS

This program will be in effect through September 30, 2025. There is no mileage limit for this program.

URGENCY / EXPIRATION DATE

This Customer Satisfaction Program has an expiration date of September 30, 2025, to encourage dealers and customers to have this service performed as soon as possible.

We recommend dealers utilize their FSA VIN Lists' names and address to contact customers with affected vehicles. This will help minimize the number of vehicles that may require a more extensive repair. FSA VIN Lists were made available on May 13, 2024.

AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Dates
Super Duty	2020-2024	Kentucky Truck	November 13, 2019 through April 17, 2024
Super Duty	2020-2024	Ohio	November 21, 2019 through April 12, 2024
Econoline	2021-2025	Ohio	May 30, 2019 through April 15, 2024

US population of affected vehicles: 36,323. Affected vehicles are identified in OASIS and FSA VIN Lists.

REASON FOR THIS PROGRAM

In affected vehicles, the Variable Displacement Oil Pump (VDOP) delivers oil to the engine at low pressure/capacity during idle conditions. Routine occurrences of prolonged idle time may result in excess wear to the engine camshaft lobes and valve tappet surfaces due to reduced lubrication. Over time, the engine may progressively run rough due to cylinder misfire. Additionally, customers may hear engine tapping noises and the Check Engine Light (CEL) may illuminate.

New! SERVICE ACTION

Ford recommends before delivering any new in-stock vehicles involved in this program, dealers are to update the PCM calibration on 2021-2024 Super Duty and 2021-2025 Econoline vehicles. This service must be performed on all affected vehicles at no charge to the vehicle owner. For new vehicle storage guidelines, refer to EFC13033, Storage Guidelines for New Vehicles.

Vehicle	Model Year	Software Availability	Projected Availability
Super Duty	2020	Unavailable	October 1, 2024
	2021	Available	
	2022	Available	
	2023	Available	
	2024	Available	
Econoline	2021	Available	
	2022	Available	
	2023	Available	
	2024	Available	
	2025	Available	

<u>NOTE:</u> Software is not currently available for 2020 Model Year Super Duty vehicles. This FSA will be updated and VINs will be added to the program as software becomes available based on the software availability chart shown above.

For new vehicle storage guidelines, refer to EFC13033, Storage Guidelines for New Vehicles.

IMPORTANT: Dealers should open a Repair Order (RO) only when a full dealer bulletin is published. Opening an RO against an Awareness or Advance Notice will result in warranty rejections against a recall.

To assist vehicle owners to have this repair completed when parts are available, dealers should:

- Arrange for a mobile repair at the owner's location, or:
- Arrange to pick up the owner's vehicle and drive it to the dealership for repairs.
 - o Re-deliver the owner's vehicle after repairs have been completed.
- Pick-Up & Delivery and mobile service should be made available for all customers. Refer to the Rental and Claiming sections for further details.

New! OWNER NOTIFICATION MAILING SCHEDULE

For owners of 2021-2022 Super Duty, letters are expected to be mailed by September 20, 2024. Owners of 2023 Econoline vehicles were mailed letters the week of July 8, 2024. Owners of 2023-2024 Super Duty and Econoline vehicles were mailed letters the week of May 16, 2024. Dealers should repair any affected vehicles that arrive at their dealerships, whether or not the customer has received a letter.

New! ATTACHMENTS

- Administrative Information
- Labor Allowances and Parts Ordering Information
- Technical Instructions
- Mobile Service Repair Assessment
- Mobile Repair/Vehicle Pick-Up & Delivery Record
- Owner Notification Letter

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician System (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Customer Service Division

Customer Satisfaction Program 24B27 – Supplement #3

MOBILE SERVICE REPAIR ASSESSMENT LEVEL

- All repairs in this program have the following assessment level.
 - Mobile Reprogramming

MOBILE REPAIR RECOMMENDATIONS

- Confirm with the customer a mobile repair is feasible.
- Check OASIS before going to the customer's home or business to confirm if any other outstanding FSA needs to be completed.
- Transportation due to the simplicity of this repair, a specialty vehicle is not required.

MOBILE REPAIR ADDITIONAL INFORMATION

Please ensure the technician brings the following to the mobile repair destination:

- Printed Technical Instructions.
- Printed Repair/Work Order or any other necessary documentation as customer copy(s)
 - o Documents could also be emailed to the customer.
- Shirt/uniform and vehicle graphic with the dealership or Ford logos are recommended.

MOBILE REPAIR QUESTIONS AND ASSISTANCE

- For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. Work with Dealership warranty administrator to create a SSSC contact ID#.
- Once an SSSC agent responds to the new contact ID#, you may opt to call the SSSC hotline: (800) 325-5621.

OASIS ACTIVATION

OASIS was activated on May 13, 2024.

New! FSA VIN LISTS ACTIVATION

FSA VIN Lists for vehicles that have software released will be available through https://web.fsavinlists.dealerconnection.com by September 11, 2024. Owner names and addresses will be available by October 4, 2024. FSA VIN Lists for the remaining vehicles will be available as dealer bulletin supplements are released to include those vehicles.

NOTE: Your FSA VIN Lists may contain owner names and addresses obtained from motor vehicle registration records. The use of such motor vehicle registration data for any purpose other than in connection with this program is a violation of law in several states, provinces, and countries. Accordingly, you must limit the use of this listing to the follow-up necessary to complete this service action.

SOLD VEHICLES

- Owners of affected vehicles will be directed to dealers for repairs.
- Immediately contact any of your affected customers whose vehicles are not on your VIN list but are identified in OASIS. Give the customer a copy of the Owner Notification Letter (when available) and schedule a service date.
- Correct other affected vehicles identified in OASIS which are brought to your dealership.
- Dealers are to prioritize repairs of customer vehicles over repairs of new and used vehicle inventory.

Customer Satisfaction Program 24B27 – Supplement #3

STOCK VEHICLES

- Correct all affected units in your new vehicle inventory before delivery.
- Use OASIS to identify any affected vehicles in your used vehicle inventory.

BRANDED / SALVAGED TITLE VEHICLES

Affected branded / salvaged title vehicles are eligible for this service action.

OWNER REFUNDS

Refunds are not approved for this program.

MOBILE REPAIR CLAIMING QUESTIONS

Dealers participating in the Remote Experience Program:

- Ford Dealers refer to EFC14125, 2024 Remote Experience Program.
- Lincoln Retailers refer to EFC14164, 2024 Remote Experience Program.

Dealers NOT participating in the 2024 Remote Experience Program:

- For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. Work with the Dealership warranty administrator to create an SSSC contact ID#.
- Once an SSSC agent responds to the new contact ID#, you may opt to call the SSSC hotline: (800) 325-5621.

PICK-UP & DELIVERY- Participating Dealers

Dealers participating in the Remote Experience Program:

• Ford Dealers - Refer to EFC14125, 2024 Remote Experience Program, Pick-Up & Delivery Offset section for additional details.

PICK-UP & DELIVERY- Non-participating Dealers

Ford Dealers not participating in the 2024 Remote Experience Program for Pick-Up & Delivery are authorized to claim unique services for completing this program.

- Dealers are authorized to claim one-half labor hour per repair for vehicle Pick-Up & Delivery services. Refer to Labor Allowances for details.
- Dealers must retain a Vehicle Pick-Up & Delivery Record with the repair order documentation.

ADDITIONAL REPAIR (LABOR TIME AND/OR PARTS)

Additional repairs identified as necessary to complete the FSA should be managed as follows:

- For related damage and access time requirements, refer to the Warranty and Policy Manual / Section 6 – Ford & Lincoln Program Policies / General Information & Special Circumstances for FSAs / Related Damage.
- For vehicles within new vehicle bumper-to-bumper warranty coverage, no SSSC approval is required, although related damage must be on a separate repair line with the "Related Damage" radio button checked.
 - Ford vehicles 3 years or 36,000 miles
- For vehicles outside new vehicle bumper-to-bumper warranty coverage, submit an Approval Request to the SSSC Web Contact Site before completing the repair.

Customer Satisfaction Program 24B27 – Supplement #3

CLAIMS PREPARATION AND SUBMISSION

- **Technician Competency Requirement:** The STST Competency 10 certification requirement in the U.S. market only will be enforced starting with repair orders opened on or after August 31, 2024. FSA repairs will reject and the claim will not be paid if the repairing technician is not certified in STST Competency 10 FSA. See EFC15332 for more details.
- Claim Entry: Enter claims using Dealer Management System (DMS) or One Warranty Solution (OWS) online.
 - When entering claims:
 - Claim type 31: Field Service Action
 - Sub Code: 24B27
 - Customer Concern Code (CCC): E69
 - Condition Code (CC): 04
 - Causal Part Number: 12A650, Quantity 0
 - For additional claims preparation and submission information, refer to the Recall and Customer Satisfaction Program (CSP) Repairs in the OWS User Guide.
- Related Damage/Additional labor and/or parts: Must be claimed as Related Damage on a separate repair line from the FSA with the same claim type and subcode as described in Claim Entry above.

IMPORTANT: Click the Related Damage Indicator radio button.

- Pick-Up & Delivery:
 - Dealers participating in the Remote Experience Program
 - Refer to EFC14125, 2024 Remote Experience Program, Pick-Up & Delivery (PDL) Offset section for additional details.
 - Dealers NOT participating in the Remote Experience Program
 - Dealers may claim one-half labor hour per repair for vehicle Pick-Up & Delivery services.
 - Dealers must retain a Vehicle Pick-Up & Delivery Record with the repair order documentation.
- Mobile Repair:
 - Dealers participating in the Remote Experience Program
 - Ford Dealers refer to EFC14125, 2024 Remote Experience Program.
 - Lincoln Retailers refer to EFC14164, 2024 Remote Experience Program.
 - Dealers NOT participating in the Remote Experience Program
 - Mobile repair allowances can be claimed for dealer-performed mobile repairs.
 Dealers that are working with Ford-contracted mobile repair companies should refer to those companies for claiming instructions.
 - For dealer-performed mobile repairs, retain a copy of the Service Management signed record (see Repair Procedure Improvement & Revised Labor Time), with the repair order documentation.
 - Claim the mobile repair allowance Labor Operation Code 24B27 along with the applicable Labor Operation Code for the repair (refer to the Labor Allowances table in Labor Allowances and Parts Ordering Information).

Customer Satisfaction Program 24B27 - Supplement #3

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
All Vehicles - Update the Powertrain Control Module (PCM) software.	24B27B	0.3 Hours
Mobile Service:		
This allowance is only for <u>non-eligible</u> 2024 Remote Experience Program Dealers.	24B27MM	0.5 Hours
Can be used when the repair takes place away from the dealership.		
If Additional Time is Required Due to Travel, Please Submit an SSSC Approval Form		
Vehicle Pick-Up & Delivery Allowance:		
This allowance is only for <u>non-eligible</u> 2024 Remote Experience Program Dealers.	24B27PP	0.5 Hours
NOTE: This allowance is for dealer-performed vehicle Pick- Up & Delivery for dealership repairs only. Can only be claimed once, regardless of outstanding FSAs repaired.		

PARTS REQUIREMENTS / ORDERING INFORMATION

Parts are not required to complete this repair.


CERTAIN 2020-2024 MODEL YEAR SUPER DUTY AND 2021-2025 MODEL YEAR ECONOLINE VEHICLES AMBULANCE AND SHUTTLE BUS PACKAGE EQUIPPED WITH A 6.8L OR 7.3L GASOLINE ENGINE — POWERTRAIN CONTROL MODULE (PCM) SOFTWARE UPDATE

NEW! SERVICE PROCEDURE

- IMPORTANT! The Service Technician Specialty Training (STST) Competency 10 certification requirement in the U.S. market only will be enforced starting with repair orders opened on or after August 31, 2024. Field Service Action (FSA) repairs will reject and the claim will not be paid if the repairing technician is not certified in STST Competency 10 FSA. See Electronic Field Communication (EFC)15332 for more details.
- For 2021-2023 Econoline Vehicles Proceed to "Module Programming IDS" on Page 3.
- For all other vehicles Proceed to "Module Programming FDRS" below.

Module Programming - FDRS

- **NOTE:** Program appropriate vehicle modules before performing diagnostics and clear all Diagnostic Trouble Codes (DTCs) after programming. For DTCs generated after programming, follow normal diagnostic service procedures.
- 1. Connect a battery charger to the 12 Volt (V) battery.
 - Use of a heavy-duty charger is recommended to maintain proper battery voltage during this procedure.
- **NOTE:** Verify the negative cable of the charger is installed on a chassis or engine ground and not the 12V battery negative terminal to prevent the battery saver mode from activating on the vehicle.
- **NOTE**: If the diagnostic software does not load or if the vehicle cannot be identified properly, make sure there is a good internet connection and the Vehicle Communication Module (VCM) is properly connected to the Data Link Connector (DLC).
- 2. Log into Ford Diagnostic and Repair System (FDRS).
- **NOTE**: Vehicle information is automatically retrieved by the diagnostic software and a Network Test is run. Vehicle identification data appears on the screen when this is complete.
- 3. Click Read VIN from Vehicle or manually enter the Vehicle Identification Number (VIN).
- **NOTE**: Available modules are shown on the left hand (LH) side of the screen and available procedures are listed on the right hand (RH) side of the screen. Modules that are communicating are highlighted in green.
- 4. Select Toolbox tab.
- 5. From the list on the LH side of the screen, select the PCM.



- 6. From the list on the RH side of the screen, select **PCM Powertrain Control Module (PCM) Software Update**.
- 7. Click **RUN**. Follow all on-screen instructions carefully.
- 8. From the list on the RH side of the screen, select **Self-Test** and click **RUN**.
- 9. Click the Run Selected Tests button in the lower right.
- 10. Click the Clear & Retest button at the top of the screen to clear DTCs in all modules.
- 11. Disconnect the battery charger from the 12V battery once the programming has completed.

NOTE: Advise the customer this vehicle is equipped with an adaptive transmission shift strategy which allows the vehicle's computer to learn the transmission's unique parameters and improve shift quality. When the adaptive strategy is reset, the computer will begin a re-learning process. This re-learning process may result in firmer than normal upshifts and downshifts for several days.

Important Information for Module Programming

NOTE: When programming a module, use the following basic checks to ensure programming completes without errors.

• Make sure the 12V battery is fully charged before carrying out the programming steps and connect FDRS/scan tool to a power source.

NOTE: A good internet connection is necessary to identify the vehicle and to load the diagnostic software.

- Inspect the Vehicle Communication Module II (VCM II)/Vehicle Communication Module III (VCM III) or the Vehicle Communication and Measurement Module (VCMM) and the cables for any damage. Make sure scan tool connections are not interrupted during programming.
- A hardwired connection is strongly recommended.
- Turn off all unnecessary accessories (radio, heated/cooled seats, headlamps, interior lamps, HVAC system, etc.) and close doors.
- Turn the accessories back on after programming has completed.
- Disconnect/depower any aftermarket accessories (remote start, alarm, power inverter, CB radio,etc.).
- Follow all scan tool on-screen instructions carefully.
- Disable FDRS/scan tool sleep mode, screensaver, hibernation modes.
- Create all sessions key on engine off (KOEO). Starting the vehicle before creating a session will cause errors within the programming inhale process.

Recovering a module when programming has resulted in a blank module

- a. Disconnect the VCM II/VCM III or the VCMM from the data link connector (DLC) and your computer.
- b. After ten seconds, reconnect the VCMII/VCMIII or the VCMM to the DLC and the PC. Launch FDRS. The VCMII/VCMIII or the VCMM icon should turn green in the bottom right corner of the screen. If it does not, troubleshoot the FDRS to VCM connection.
- c. If you are using the same FDRS as the initial programming attempt, select the appropriate VIN from the Vehicle Identification menu. If you are using a different FDRS, select "Read VIN from Vehicle" and proceed through the Network Test.

- d. In the Toolbox menu, navigate to the failed module and Download/Run Programmable Module Installation (PMI). Follow the on-screen prompts. When asked if the original module is installed, select "No" and continue through the installation application.
- e. Once programming has completed, a screen may list additional steps required to complete the programming process. Make sure all applicable steps are followed in order.

NEW! Module Reprogramming - IDS

NOTE: Reprogram appropriate vehicle modules before performing diagnostics and clear all Diagnostic Trouble Codes (DTCs) after programming. For DTCs generated after reprogramming, follow normal diagnostic service procedures.

- 1. Connect a battery charger to the 12 Volt (V) battery.
 - Use of a heavy-duty charger is recommended to maintain proper battery voltage during this procedure.

NOTE: Verify the negative cable of the charger is installed on a chassis or engine ground and not the 12V battery negative terminal to prevent the battery saver mode from activating on the vehicle.

NOTE: Make sure the IDS computer does not enter sleep mode during programming.

2. Reprogram the Powertrain Control Module (PCM) using Integrated Diagnostic Software (IDS) release 130.07 or higher. Make sure you are connected to the Internet prior to reprogramming.

NOTE: Calibration files may also be obtained at www.motorcraftservice.com.

NOTE: Follow the IDS on-screen instructions to complete the reprogramming procedure.

- 3. Check and clear all DTCs.
- 4. Disconnect the battery charger from the 12V battery once the reprogramming has completed.

NOTE: Advise the customer that this vehicle is equipped with an adaptive transmission shift strategy which allows the vehicle's computer to learn the transmission's unique parameters and improve shift quality. When the adaptive strategy is reset, the computer will begin a re-learning process. This re-learning process may result in firmer than normal upshifts and downshifts for several days.

Important Information for Module Programming

NOTE: When programming or reprogramming a module, use the following basic checks to ensure programming completes without errors.

- Inspect the Vehicle Communication Module II (VCM II)/Vehicle Communication Module III (VCM III) or the Vehicle Communication and Measurement Module (VCMM) and the cables for any damage. Make sure scan tool connections are not interrupted during programming.
- A hardwired connection is strongly recommended.
- Turn off all unnecessary accessories (radio, heated/cooled seats, headlamps, interior lamps, HVAC system, etc.) and close doors.
- Turn the accessories back on after programming has completed.
- Disconnect/depower any aftermarket accessories (remote start, alarm, power inverter, CB radio,etc.).
- Follow all scan tool on-screen instructions carefully.
- Disable IDS/scan tool sleep mode, screensaver, hibernation modes.
- Create all sessions Key ON Engine OFF (KOEO). Starting the vehicle before creating a session will cause errors within the programming inhale process.

Recovering a module when programming has resulted in a blank module: NEVER DELETE THE ORIGINAL SESSION!

- a. Obtain the original IDS that was used when the programming error occurred during Module Reprogramming (MR) or Programmable Module Installation (PMI).
- b. Disconnect the VCM II/VCM III from the Data Link Connector (DLC) and the IDS.
- c. Reconnect the VCM II/VCM III to IDS and then connect to the DLC. Once reconnected, the VCM II/VCM III icon should appear in the corner of the IDS screen. If it does not, troubleshoot the IDS to VCM II/VCM III connection.
- d. Locate the original vehicle session when programming failed. This should be the last session used in most cases. If not, use the session created on the date that the programming failed.

NOTE: If the original session is not listed in the previous session list, click the Recycle Bin icon at the lower right of the previous session screen. This loads any deleted sessions and allows you to look through them. Double-click the session to restore it.

- e. Once the session is loaded, the failed process should resume automatically.
- f. If programming does not resume automatically, proceed to the Module Programming menu and select the previously attempted process, PMI or MR.
- g. Follow all on-screen prompts/instructions.
- h. The last screen on the IDS may list additional steps required to complete the programming process. Make sure all applicable steps listed on the screen are followed in order.

NEW VEHICLE RECOMMENDED DELIVERY HOLD

Customer Satisfaction Program 24B27 - Supplement #3

Certain 2020-2024 Super Duty and 2021-2025 Model Year Econoline Ambulance and Shuttle Bus Package Equipped with a 6.8L or 7.3L gasoline engine Powertrain Control Module Software Update

Mobile Service Repair Assessment

Assessment levels have been identified to help determine the ease of performing eligible mobile service repairs for a Field Service Action (FSA) outside of the dealership service facility.

Dealer Bulletin

Within the Administrative Information Attachment of the dealer bulletin a mobile service repair assessment level(s) will be provided. These assessment levels have been determined using the amount of time, equipment and labor identified to perform the intended service action.

Assessment Levels

- Mobile Reprogramming

- Light Mobile Service

- Enhanced Mobile Service

- Wheel and Tire Mobile Service

Not a Mobile Service Repair

Description of each level that is used to determine the overall assessment.

- Mobile Reprogramming
 - Module Programming or similar type services
 - Minimum tools maybe required other than an IDS/FDRS setup
 - FDRS programming that requires internet connection (wi-fi or mobile hotspot)
 - Make sure vehicle has a charge port to ensure battery voltage is maintained during flashing of the module(s)
 - Repairs not greater than 1 hour in length (including time to wait for programming)

 Note: The location will need a charging station or wall box to maintain the 12-volt battery.
- Light Mobile Service
 - Interior repair procedures that do not require seat, dash, or headliner removal
 - Under hood repairs that do not require large component removal
 - Exterior repairs that do not require large component/panel removal
 - Repairs may require standard hand tools (Access to a Technician starter kit or similar)

NEW VEHICLE RECOMMENDED DELIVERY HOLD

Customer Satisfaction Program 24B27 - Supplement #3

Certain 2020-2024 Super Duty and 2021-2025 Model Year Econoline Ambulance and Shuttle Bus Package Equipped with a 6.8L or 7.3L gasoline engine Powertrain Control Module Software Update

- - Enhanced Mobile Service

- A two-person process is required anytime a procedure requires work under the vehicle
- Brake Inspection and Brake Repair/Replacement
- Limited Suspension Component replacement (no alignment)
- Under Vehicle access for limited repairs (no large component removal)
- Vehicle Check Up VCU
- Pre-Delivery Inspection PDI
- Used Car Inspection/Presale Inspection
- May require floor jack, jack stands, and impact tools

Note: Wheel lock may be required.

🥕 🥕 🥕 - Advanced Mobile Service

- Fluid Exchange/Oil Change
- Light Repairs
- Brake Hydraulic Repairs



- Wheel and Tire Mobile Service
 - Tire Removal from Wheel
 - Tire Balancing
 - Tire Repair

Note: Specialized Mobile Service unit and equipment including Tire balancer and Tire Changer required.

— Not a Mobile Service Repair

- Large component removal
- BEV Battery Replacement
- Requires a vehicle hoist to complete the repair (more than inspection)
- Required vehicle alignment
- Requires significant vehicle disassembly
- Repairs greater than 2-3 hours
- Any repairs that require M-Time
- Includes a service procedure where the vehicle owner may be distressed about the state of their vehicle

Mobile Repair / Vehicle Pick-Up and Delivery Record

VIN	_ received (check one):
☐ Mobile Repair	
☐ Pick-up and/or delivery service	
As outlined below for the 24B27 Field S	Service Action program.
□ Mobile Repair – Date:	
	OR
□ Pick-up – Date:	
□ Delivery – Date:	
Repair Order #	Repair Order Date
Service Manager Signature	 Date