

Service Alert

Mazda North American Operations
Irvine, CA 92618-2922



Subject: CONNECTED VEHICLE SYMPTOM TROUBLESHOOTING	Service Alert No.: SA-017/24
	Last Issued : 09/10/2024

BULLETIN NOTES

This Service Alert supersedes the previously issued service alert listed below. The changes are noted in Red text.

Previous SAs:	Date(s) Issued:
SA-017/24	04/11/24 and 03/14/24
SA-009/23	10/23/23, 08/28/23, 08/15/23, 07/05/23, 06/12/23, 05/24/23, 04/25/23, 03/28/23, 03/01/23 and 02/06/23
SA-017/22	12/13/22, 10/10/22, 08/25/22, 05/06/22, 04/04/22
SA-013/21	12/22/21, 10/13/21, 09/14/21, 05/11/21, 04/27/21, 03/15/21, 02/22/21, 02/08/21 and 02/02/2021
SA-031/20	12/09/20, 11/30/20, 11/06/20, 10/28/20, 06/16/20, 06/05/20, 06/01/20, 05/18/20, 04/14/2020, 04/02/20, 03/11/20 and 02/27/20

APPLICABLE MODEL(S)/VINS:

2019-2025 Mazda3	2021-2023 CX-9	2024-2025 CX-90
2020-2025 CX-30	2022-2023 MX-30	2024 MX-5
2021-2025 CX-5	2023-2025 CX-50	2025 CX-70

DESCRIPTION

Some customers may complain about any of the following:

1. Infotainment Center Display does not provide the Authorization Code (OTP) during the MyMazda App Connected Vehicle enrollment.
2. Remote function(s) inoperative.
 - Engine Start / Stop
 - Door Lock / Unlock
 - Lights ON / OFF
 - Climate Control
3. MAZDA CONNECT connected vehicle reception strength icon shows "X" or "\".










CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Index







- MAZDA CONNECT Indication
- Remote Engine Start Will Not Function
- Remote Engine Start Function Will turn engine OFF
- Deactivation Mode

MAZDA CONNECT Indication





Indication	Explanation
Mazda3, CX-30, CX-50, MX-30 	Radio waves are not being received. Move to a location with good reception.
	Weak reception.
	Good Reception
	Strong reception.
	Currently conducting an operation check of the communication unit. If this condition continues, consult an Authorized Mazda Dealer.
	Currently conducting an operation check of the onboard communication unit. NOTE: Communication is not possible during this display.
CX-5, CX-50, CX-9, MX-30 Mazda3, CX-30 built July 1, 2021 and later 	The communication function is temporarily disabled due to infotainment system setting. 
	<ul style="list-style-type: none"> • No CV Contract • Deactivation Mode • Connected Service contract has ended

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



	<p>(Subscription expired)</p> <ul style="list-style-type: none"> TCU has not been initialized, go to SA-004/21
<p>Vehicles built before July 1, 2021</p> 	<p>Customer deactivated Connected Services (Opt-Out)</p>
<p>Vehicles built after July 1, 2021</p> 	<ul style="list-style-type: none"> eMDCS Warranty Vehicle Inquiry will show Campaign CSP04 Status Open
<p>CX-5, CX-50, CX-9, MX-30 Mazda3, CX-30 built July 1, 2021 and later</p> <p>Connected Services Disabled message appears at engine start up</p> 	<p>Connected Services disabled (box unchecked)</p>  <p>Enable Connected Services (box checked) to prevent message appearing at engine start up.</p>  <p>Note: If customer Opted-Out (CSP04), advise customer to keep Connected Services box checked. The vehicle will not transmit data.</p>
<p>Connected Vehicle Maintenance Mode</p> 	<p>Connected Vehicle Maintenance Mode enabled. Go to MGSS SERVICE CAUTIONS FOR VEHICLES WITH TELEMATICS COMMUNICATION SYSTEM to disable Maintenance Mode.</p> <p>NOTE: Connected Vehicle Maintenance Mode is unnecessary if the customers vehicle is in Deactivation Mode .</p>

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Remote Engine Start Will Not Function under the following conditions

Item	Condition
1	Remote Engine Start function is not available on EV and PHEV (inline 4) models. See SA-038/23
2	Vehicle battery voltage low
3	Automatic Transmission shift position except "P"
4	Vehicles equipped with manual transmission
5	Vehicle speed above 3 mi/h (5 km/h)
6	Brake pedal switch malfunction
7	Engine has been running by remote engine start function
8	Engine started by remote engine start more than 2 consecutive times while the vehicle is not driven. The vehicle must be driven 1-mile or 24-hours must pass from the last successful Remote Engine Start for the use count to reset.
9	2021 Mazda3, 2021 CX-30, CX-50, MX-30: Vehicle's electrical control area network (CAN) is in "Sleep Mode" 
10	A registered key is detected in the vehicle
11	Brake pedal switch detects brake application
12	Low fuel warning 
13	Engine starts, then turns OFF due to abnormal high engine rpm detected. (Engine rotation over 3000 rpm continued for more than 0.2[s])
14	No engine rpm detected after sending engine start request. (Engine rotation 0 rpm continued for more than 0.2[s])
15	When the CAN data signal for engine shut off is present (e.g.: door ajar signal)
16	After 10 second maximum cranking time
17	Burglar alarm status is "Alarm" and "Alarm stand by" (CAUTION - DO NOT enable, see Theft-Deterrent System section in SA-012/20)
18	Room fuse blown/missing
19	Connected Vehicle Maintenance Mode enabled (Restricted Transmitting Mode in MDARS)

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

	
20	Vehicle is parked (stored) for approximately 1 week or longer or in deep sleep mode. Drive the vehicle for a few miles to recover.
21	DTC Stored 
22	Aftermarket Remote Engine Start accessory installed.
23	Mazda Remote Engine Start (BCKA-V7-620) accessory installed (No MyMazda app remote engine start function). Mazda Remote Engine Start (RES) Removal a. Remove the Mazda Remote Engine Start (RES) accessory module. b. Deactivate and activate Advanced Key(s). Refer to MGSS IMMOBILIZER SYSTEM-RELATED PARTS PROGRAMMING [(US)]
24	First remote control attempt fails, second attempt works fine. Go to TSB 16-002/20 .
25	CSP04 Status Open

Remote Engine Start Function Will turn engine OFF under the following conditions

Item	Condition
1	Vehicle door(s) opened
2	Vehicle trunk opened
3	Vehicle hood opened
4	Ignition switch push button "ON" detected
5	Remote engine STOP request
6	Brake pedal switch detects brake application
7	DTC Stored
8	Engine will stop running automatically after 15 minutes for safety, security and emissions.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.




Deactivation Mode

- **Deactivation Mode Temporary Suspension 6/16/2023 (6/11/2023 retail date and later)**
- **Vehicles retailed before 6/11/2023 and in Deactivation Mode will remain in Deactivation mode.**

NOTE:

- Customer/Dealer can activate CV services anytime via MyMazda app
 - Customer - There might be a slight delay in making the backend connection since it was temporarily deactivated.
 - Dealer - Go to Repair Procedure -> TCU Activation
- When TCU is in Deactivation Mode, infotainment Over-the-Air (OTA) Connectivity Master Unit (CMU) software update is not possible (disabled).
- Prior to Retail Date, the TCU is active.

Deactivation Mode Status Check:

	<p>TCU Active</p>	<p style="text-align: center;">Reception Icon Shows normal strength</p> 
<p>Infotainment Center Display</p>	<ul style="list-style-type: none"> • TCU in Deactivation Mode • No CV Contract • One Time Passcode (OTP) is processing 	<p style="text-align: center;">Reception Icon Shows "X"</p> 
<p>Mazda Connected Vehicle Viewer (MCVV)</p>	<p>TCU CV Contract Status</p> <ol style="list-style-type: none"> 1. Go to Mazda Connected Vehicle Viewer (MCVV) 2. Enter VIN and then select "Search" 	<p style="text-align: center;">No CV Contract</p>  <p style="text-align: center;">CV Contract Active</p>

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

TCU Activation Status Check

Connected Vehicle Information Search Screen

Search Condition

VIN: 7MMVABXY9PN1

Search [Clear]

Select	VIN	Customer First Name	Customer Last Name	Year and Model	Body Color	Communication Line Status	Warning	Condition Monitor
Select	7MMVABXY9PN1	DANIEL	G	2023 2.5 TURBO MERIDIAN EDITION AWD	ZIRCON SAND METALLIC	Opened		✓

1. Go to [Mazda Connected Vehicle Viewer \(MCCV\)](#)

Connected Vehicle Information Search Screen

Search Condition

VIN: []

Search [Clear]

Select	VIN	Customer First Name	Customer Last Name	Year and Model	Body Color	Communication Line Status	Warning	Condition Monitor
[Back]								

2. Select "Vehicle Communication Line Status Reference"
3. Enter VIN and then select "Search"

Vehicle Communication Line Status Search Screen

Search Condition

VIN: []

Search [Clear]

VIN	Vehicle Communication Line Status			Year and Model	Body Color
	Status	Request Date	Status Detail		
JM10R06B4P0	Closed	02/06/2023 18:25	Close Completed 02/06/2023 18:25	2023 EV FWD W/ PREMIUM PLUS PKG	MACHINE GRAY METALLIC

TCU in Deactivation Mode (Status -> Closed)

Vehicle Communication Line Status Search Screen

Search Condition

VIN: JM10R06B4P0

Search [Clear]

VIN	Vehicle Communication Line Status			Year and Model	Body Color
	Status	Request Date	Status Detail		
JM10R06B4P0	Closed	02/06/2023 18:25	Close Completed 02/06/2023 18:25	2023 EV FWD W/ PREMIUM PLUS PKG	MACHINE GRAY METALLIC

One Time Passcode (OTP) is processing (Status -> Open Requested)

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

TCU Active (Status -> Opened)


VIN	Vehicle Communication Line Status			Year and Model	Body Color
	Status	Request Date	Status Detail		
7MMVABXY9	Open Requested	04/27/2023 11:14	Processing	2023 2.5 TURBO MERIDIAN EDITION AWD	ZIRCON SAND METALLIC

VIN	Vehicle Communication Line Status			Year and Model	Body Color
	Status	Request Date	Status Detail		
JM1RA0B6P0	Opened	02/08/2023 18:25	Open Completed 02/08/2023 18:25	2023 EY FWD W/ PREMIUM PLUS PKG	MACHINE GRAY METALLIC

REPAIR PROCEDURE

CAUTION: DO NOT swap TCU with another vehicle as the TCU is VIN locked after activation. A TCU swap with another vehicle will disable Connected Services on both vehicles.

Repair Flowchart



CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

↓	↓	↓
Check Campaign Status	Enrollment / Take-Over	Check Campaign Status
↓	↓	↓
Remote Function Troubleshooting	OTP Troubleshooting	Customer deactivate Connected Services (Opt-Out)
		↓
		No reception

PREPARATION:

1. Confirm that the Telematics Communication Unit (TCU) is at the latest software level. Go to [Telematics Communication Unit \(TCU\) Updates](#)
2. Go to [eMDCS Vehicle Inquiry](#) and confirm the following campaigns are not shown or closed:

- CSP06
- CSP07
- SSPC7
- DRW41

3. Go to [eMDCS Vehicle Inquiry](#) and confirm CSP04 is not shown.
4. If Hotline assistance is needed, please fill out the [Dealer Connected Vehicle Questionnaire](#) before contacting Hotline. The questionnaire collects data needed by Hotline agent.
5. In most cases, the customer will not leave their device with you for troubleshooting, therefore a connected vehicle Take-Over is necessary. Use your personal device or dealer supplied device for troubleshooting. Go to [Enrollment / Take-Over](#).

- At customer pick-up, inform customer to re-enroll into Connected Services as a new primary user.

6. Confirm the customer's phone and vehicle have good to strong reception during the concern as shown in the table below.



- If the reception icon shows "X", the TCU is deactivated. Enrollment is not possible. Go to [TCU Activation](#).

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



- Customer/Dealer can activate CV services anytime via MyMazda app
 - Customer - There might be a slight delay in making the backend connection since it was temporarily deactivated.
 - Dealer - Go to [TCU Activation](#)
- If the reception icon shows " \ ", move the vehicle to an area with a clear view of the sky.



- If the reception is weak, move the vehicle to a location where the reception is good to strong as shown in the table, then try to get the Authorization Code and/or operate the remote functions before proceeding to the Repair Procedure if there is still an issue.
- If the reception is good to strong, proceed to Connected Vehicle Troubleshooting below.

NOTE: Vehicles stored for long periods may lose GPS clock synchronization. If the vehicle is stored for a long period, test drive the vehicle to give the GPS clock time to synchronize before enrolling or testing connected vehicle functions.






Index

1. [Unable to create a MyMazda account](#)
2. [Remote function\(s\) inoperative](#)
3. [No One Time Pass Code \(OTP\)](#)
4. [Connected vehicle reception strength icon shows "X" or "\"](#)
5. [MyMazda App displays incorrect tire pressures \(Except CX-5 and CX-9\)](#)
6. [Unable to activate Connected Services \(2019 Mazda3\)](#)
7. [Software Update Error \(2020 Mazda3\)](#)
8. [Functions inoperative \(2021-> CX-30, CX-50, Mazda3 and MX-30\)](#)
9. [First remote control attempt fails, second attempt works fine](#)
10. [Engine turns off when opening door](#)
11. [Low Tire pressure will not clear after correcting tire pressure](#)
12. [MyMazda App does not display tire air pressures \(CX-5, CX-9\)](#)


- [MCVV One Time Passcode \(OTP\) Troubleshooting](#)
- [TCU Activation](#)
- [2nd Owner Take-Over](#)
- [Customer Opt-Out](#)

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.


- Educational Videos
- Resources

Connected Vehicle Troubleshooting		
Symptom	Cause	Action
<p>The customer is not able to create a MyMazda account. The customer receives the following error: MyMazda App - Internal Usher SDK error.</p>  <p>MyMazda will send an SMS to verify your mobile phone number (carrier charges may apply).</p> <p>MyMazda Website - ERROR! Unable to send one-time password.</p> 	<p>Customer inadvertently texted “Stop” to 1-949 518-0058 (Twilio SMS for Mazda)</p> 	<p>1. Text “Start” to 1-949 518-0058 (Twilio SMS for Mazda) 2. Retry to create a MyMazda account.</p> <p>NOTE: USA and Canada only</p> 
<p>1</p> <p>2 Remote function(s) inoperative.</p> <ul style="list-style-type: none"> • Engine Start / Stop • Door Lock / Unlock • Lights ON / OFF 	<p>Go to the MyMazda App to view the reason for remote function failure.</p>	<p>Push Notification</p> 


CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

<ul style="list-style-type: none"> Climate Control 				<p>OS Lock Screen Tap the push notification</p>	<p>Home Tap the alert card</p>	<p>Inbox Detail Tap "check vehicle status"</p>
			<p>Activity History</p> <p>Go to the MyMazda App INBOX -> ACTIVITY HISTORY -> to view reason for remote function failure.</p> 			
	<p>Check Campaign Status</p>	<p>Go to eMDCS Vehicle Inquiry and confirm the following campains are not shown or closed:</p> <ul style="list-style-type: none"> CSP06 CSP07 SSPC7 DRW41 				
<p>Remote Function Troubleshooting</p>	<p>1. Confirm Connected Services is enabled (box checked). Go to Settings -> System Settings -> Connected Services.</p>					

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

		 <p>2. Use MDARS to ID the vehicle and check for DTC's stored. Are DTC(s) stored?</p> <ul style="list-style-type: none"> • Yes - Go to MGSS and perform normal DTC diagnostics. • No - Go to next step. <p>3. Confirm TCU software version. Go to Telematics Communication Unit (TCU) Updates</p> <p>4. Disconnect battery for 30 seconds and then reconnect (KAM reset). NOTE: Test drive vehicle after battery disconnect to allow the GPS clock to synchronize before retrying Authorization Code.</p> <p>5. Perform one of the following:</p> <ul style="list-style-type: none"> • Customer: Un-enroll Connected Services, then re-enroll into Connected Services as a new primary user. • Dealer: Perform customer take-over enrollment for test confirmation, then at customer pick-up, inform customer to re-enroll into Connected Services as a new primary user. <p>6. Fill out Dealer Connected Vehicle Questionnaire</p> <p>7. Contact Hotline for additional technical support if needed.</p>
	Remote Climate Control only available on EV and PHEV	No action needed. See SA-038/23
	Only a single remote request can be made per 60-second period	Customer needs to wait 60 seconds for the initial request cycle to be completed to make the second request.
	Remote Transmitter Key(s) in the vehicle	Do not leave keys in vehicle.
	1. Aftermarket Remote Engine Start accessory installed.	1. Remove the aftermarket accessory. 2. The customer can use either the

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

		<p>2. Mazda Remote Engine Start (BCKA-V7-620) accessory installed.</p> 	<p>Mazda Remote Engine Start accessory or the MyMazda app function. Cannot use both.</p> <p>Mazda Remote Engine Start (RES) Removal</p> <p>a. Remove the Mazda Remote Engine Start (RES) accessory module.</p> <p>b. Deactivate and activate Advanced Key(s). Refer to MGSS IMMOBILIZER SYSTEM-RELATED PARTS PROGRAMMING [(US)].</p>
		<p>TCU in "deep sleep" mode due to vehicle being parked for a long period.</p>	<p>Advise customer to drive the vehicle as normal (at least several miles) and the Connected Services should start working again.</p>
		<p>Low fuel</p>	<p>Advise customer that Remote Engine Start may start vehicle temporarily, but vehicle will turn off automatically when the fuel level is low to conserve the remaining fuel.</p>
		<p>Vehicle is equipped with Manual Transmission</p>	<p>Advise customer that vehicles with a manual transmission do not have the Remote Engine Start/Stop function capability.</p>
		<p>Engine started with key transmitter instead of MyMazda App.</p>	<p>Advise customer they will see an error message when attempting to make a Remote Engine Off request if they initially turned on vehicle with a physical key (instead of through their MyMazda app).</p>
<p>3</p>	<p>No One Time Passcode (OTP) (Vehicle infotainment center display does not provide the Authorization Code during the MyMazda App enrollment)</p>	<p>MyMazda App Enrollment Preparation</p> <ol style="list-style-type: none"> 1. Create a MyMazda account. 2. Complete any "OPEN" Recalls / Special Service Programs. Go to MGSS -> warranty Veh. Inq. 3. Update the Telematics Communication Unit (TCU) to the latest software version. Go to Telematics Communication Unit (TCU) Updates. 4. 2019 Mazda3 only - Update the Connectivity Master Unit (CMU) to the latest software version. Go to MGSS -> MAZDA CONNECT Updates. 5. Check TCU activation status. <ol style="list-style-type: none"> a. Go to MAZDA CONNECT home screen. b. Select Entertainment c. Select Source List and then select any of the following: <ul style="list-style-type: none"> • FM • AM • SiriusXM 	

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

d. Check the Connected Vehicle reception strength icon:

- Reception strength icon shows normal strength. The TCU is active and ready for enrollment. Go to [Enrollment / Take-Over](#).



- Reception strength icon shows "X". The TCU is deactivated. Enrollment is not possible. Go to [TCU Activation](#).

Note: Use MCVV to check OTP status. Go to [Mazda Connected Vehicle Viewer \(MCVV\) One Time Passcode \(OTP\) Troubleshooting](#)



- Reception strength icon shows "\". Move the vehicle to an area with a clear view of the sky.




CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.


Enrollment / Take-Over

1. Install the MyMazda APP

Note: If 2nd owner, follow this same Enrollment procedure to perform a Take-Over. Previous owner will receive email notification of Take-Over.




2. Register your user information




CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

3. Register vehicle information




4. Register Connected Service




CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

5. Switch the ignition ON in your Mazda vehicle.
6. Wait 30 seconds.
7. Tap Next.




8. Tap Request to receive authorization code on your vehicle's Mazda Connect center display.

Wait a few minutes for the infotainment center display to show the Authorization Code.




CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

9. After a few minutes, the infotainment center display will show the Authorization Code. Enter the authorization code in the MyMazda app, then tap Submit.



10. After enrollment is successfully processed and the vehicle is connected, you will receive a push notification.



OTP Troubleshooting

1. Check reception strength icon:

-  - Go to Step 2.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



- - Go to [MCVV OTP Troubleshooting](#)

2. Use MDARS to ID the vehicle and check for DTC's stored. Are DTC(s) stored?

- Yes - Go to MGSS and perform normal DTC diagnostics.
- No - Perform [Diagnostic Information \(ODR\) Data Collection Procedure](#), then go to step 3.

3. Confirm TCU software version. Go to [Telematics Communication Unit \(TCU\) Updates](#)

4. 2019 Mazda3 Only - Confirm [CMU software version](#) is at 11012 or later.

5. Retrieve MAZDA CONNECT CMU log data. Go to MGSS -> Infotainment -> [MAZDA CONNECT CMU Data Retrieval](#)

6. Perform "[Activating Remote Control by Smart Phone](#)" (links TCU to BCM)

7. Clear DTC(s).

NOTE: If DTC 2050:55 is stored, go to [SA-003/20](#) to clear DTC.

8. Check [TCU Remote Service Flag Information](#)

- Remote Service Flag Information 1101... - go to step 9.
- Remote Service Flag Information 0000... - go to step 10.


9. Disconnect 12V battery for 5-10 minutes, then retry connected vehicle enrollment.

NOTE: Test drive vehicle after battery disconnect to allow the GPS clock to synchronize before retrying Authorization Code.




10. Fill out [Dealer Connected Vehicle Questionnaire](#)

11. Contact Hotline for additional





CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

			technical support if needed.
		<p>Deactivation Mode</p> <p>—</p>	<p>Customer/Dealer can activate CV services anytime via MyMazda app</p> <ul style="list-style-type: none"> • Customer - There might be a slight delay in making the backend connection since it was temporarily deactivated. • Dealer - Go to TCU Activation
		<p>Customer deactivate Connected Services (Opt-Out)</p>	<p>Go to eMDCS Vehicle Inquiry. Does eMDCS show CSP04 status closed?</p> <ul style="list-style-type: none"> • Yes - Customer opt-out. No action needed. • No - CSP04 is not shown. Go to next Action below.
<p>4</p>	<p>MAZDA CONNECT connected vehicle reception strength icon shows "X"</p>  <p>This is a normal condition if the customer has not enrolled into connected vehicle services.</p>	<p>No reception</p>	<ol style="list-style-type: none"> 1. Check for DTCs. Are there any DTC's stored? <ul style="list-style-type: none"> • Yes: Go to MGSS for normal DTC diagnosis. • No: Go to next step. 2. Confirm TCU software version. Go to Telematics Communication Unit (TCU) Updates 3. 2019 Mazda3 Only - Confirm CMU software version is at 11012 or later. 4. Disconnect battery terminal for 5-10 minutes, then test drive the vehicle. Is the reception strength signal normal? <ul style="list-style-type: none"> • Yes: Repair complete. • No: Go to next step. 5. Perform TCU activation. Go to SA-004/21. Is the reception strength signal normal? <ul style="list-style-type: none"> • Yes: Repair complete. • No: Go to next step. 6. Compare Tel antenna No. 1 signal strength with good known vehicle near by. Go to DIAGNOSTIC ASSIST FUNCTION [CONNECTIVITY MASTER UNIT (US)] Functional Inspection / Adjustment ->


CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



			<p>Navigation System Inspection</p> <p>Good - Contact Hotline for technical support</p>  <p>No Good - Swap Tel antenna No. 1 with known good vehicle</p> 
5	<p>Except CX-5 and CX-9</p> <p>MAZDA CONNECT and/or MyMazda App displays incorrect tire pressures after battery disconnect and/or infotainment CMU software update.</p> 	<p>Incorrect calendar entry (month/day/year) after a battery disconnect or infotainment system software update.</p>	<p>Go to SA-002/21</p>
6	<p>2019 Mazda3 only</p> <ul style="list-style-type: none"> The customer is not able to activate Connected Services via the MyMazda app after CSP06 completion. MAZDA CONNECT connected vehicle reception strength icon is missing or shows unsubscribed after CSP06 completion. 	<p>Improper telematics communication unit (TCU) software.</p>	<p>Go to CSP07 Repair instructions.</p>

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.


			
7	<p>2020 Mazda3 only</p> <ul style="list-style-type: none"> • Infotainment center display does not provide the Authorization Code • Infotainment center display “Software Update Error” message 	Enrollment error	Go to SSPC1
8	<p>2021 Mazda3, CX-30, CX-50, and MX-30 functions inoperative</p> <ul style="list-style-type: none"> • Vehicle Status Alert • Remote Engine Start / Stop • Remote Door Lock / Unlock • Remote Hazard Lights ON / OFF • Vehicle Finder (vehicle location mapping function is available) 	Vehicle's electrical control area network (CAN) is in "Sleep Mode"	 <p>or</p>  <p>No dealer visit is required. Sleep Mode can be reset by starting the engine and idling or driving for 5 minutes or longer.</p> <p>Go to 09-010/22.</p>
9	<p>First remote control attempt fails, second attempt works fine.</p> <ul style="list-style-type: none"> • Engine Start / Stop • Door Lock / Unlock • Lights ON / OFF 	Improper telematics communication unit (TCU) software.	Go to TSB 16-002/20 .
10	Engine turns off when customer	Normal Operation	Advise that, for customer's safety and

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

	opens vehicle door.		security, vehicle is designed to shut-off automatically when the vehicle door is opened.
11	<ul style="list-style-type: none"> Low Tire pressure will not clear after correcting tire pressure. Vehicle status is inaccurate. 	MyMazda App is not real time.	<ul style="list-style-type: none"> Customer must go to MyMazda app's Inbox and read/open all the messages related to the low tire pressure alert, then the "Low tire pressure" alert will clear from MyMazda app's Health Report Message will clear after next drive cycle.
12	<p>CX-5, CX-9 The MyMazda App does not display tire air pressures</p> 	CX-5 and CX-9 Normal Operation	No action Needed

Mazda Connected Vehicle Viewer (MCVV) One Time Passcode (OTP) Troubleshooting (Vehicles built after July 1, 2021 (20 TCU, AT&T))												
OTP Request		MCVV Vehicle Communication Line Status Reference Status	Next Step									
		<p>New Vehicle Inventory (TCU no enrollment ever) Status: Opened Status Detail: Open Completed (with no date)</p> <table border="1"> <thead> <tr> <th colspan="3">Vehicle Communication Line Status</th> </tr> <tr> <th>Status</th> <th>Request Date</th> <th>Status Detail</th> </tr> </thead> <tbody> <tr> <td>Opened</td> <td></td> <td>Open Completed</td> </tr> </tbody> </table> 	Vehicle Communication Line Status			Status	Request Date	Status Detail	Opened		Open Completed	<p>OTP request successful.</p> <p>If not, go to No One Time Passcode (OTP) -> OTP Troubleshooting -> Step 2.</p>
Vehicle Communication Line Status												
Status	Request Date	Status Detail										
Opened		Open Completed										
	2	Status: Open Requested	400S19									

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



Status Detail: Processing

Vehicle Communication Line Atatus		
Status	Request Date	Status Detail
Open Requested	10/12/2022 23:41	Processing



Status: Open Requested
Status Detail: Request Failed

Vehicle Communication Line Atatus		
Status	Request Date	Status Detail
Open Requested	10/12/2022 23:41	Request Failed 10/12/2022 23:11




Status: Open Requested
Status Detail: Open Failed

Vehicle Communication Line Atatus		
Status	Request Date	Status Detail
Open Requested	10/12/2022 23:41	Open Failed 10/12/2022 23:11




Status: Open Flag Setting Requested
Status Detail: Processing


Vehicle Communication Line Atatus		
Status	Request Date	Status Detail
Open Flag Setting Requested	10/12/2022 23:01	Processing 10/12/2022 23:11



400S25
With new App



400S25
With old App



Phone carrier connection is processing.

The customer needs to wait for the completion of the activation.





If no change after waiting 12 hours, go to [No One Time Passcode \(OTP\)](#) -> OTP Troubleshooting -> Step 2.

Phone carrier connection is complete.

System waiting for:
a. Ignition ON.
b. Flag Setting

The customer needs to wait for the completion of the [flag download](#) and


CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

		<p>Status: Open Flag Setting Requested Status Detail: Request Failed</p> <table border="1"> <thead> <tr> <th colspan="3">Vehicle Communication Line Atatus</th> </tr> <tr> <th>Status</th> <th>Request Date</th> <th>Status Detail</th> </tr> </thead> <tbody> <tr> <td>Open Flag Setting Requested</td> <td>10/12/2022 23:01</td> <td>Request Failed 10/12/2022 23:51</td> </tr> </tbody> </table> 	Vehicle Communication Line Atatus			Status	Request Date	Status Detail	Open Flag Setting Requested	10/12/2022 23:01	Request Failed 10/12/2022 23:51	<p>IG-ON. If not:</p> <ol style="list-style-type: none"> Disconnect 12V battery 5-10 minutes, then retry OTP request. go to No One Time Passcode (OTP) -> OTP Troubleshooting -> Step 2.
Vehicle Communication Line Atatus												
Status	Request Date	Status Detail										
Open Flag Setting Requested	10/12/2022 23:01	Request Failed 10/12/2022 23:51										
		<p>Status: Open Flag Setting Requested Status Detail: Flag Setting Failed</p> <table border="1"> <thead> <tr> <th colspan="3">Vehicle Communication Line Atatus</th> </tr> <tr> <th>Status</th> <th>Request Date</th> <th>Status Detail</th> </tr> </thead> <tbody> <tr> <td>Open Flag Setting Requested</td> <td>10/12/2022 23:01</td> <td>Flag Setting Failed 10/12/2022 23:51</td> </tr> </tbody> </table> 	Vehicle Communication Line Atatus			Status	Request Date	Status Detail	Open Flag Setting Requested	10/12/2022 23:01	Flag Setting Failed 10/12/2022 23:51	
Vehicle Communication Line Atatus												
Status	Request Date	Status Detail										
Open Flag Setting Requested	10/12/2022 23:01	Flag Setting Failed 10/12/2022 23:51										
		<p>Status: Close Requested Status Detail: Close Failed</p> <table border="1"> <thead> <tr> <th colspan="3">Vehicle Communication Line Atatus</th> </tr> <tr> <th>Status</th> <th>Request Date</th> <th>Status Detail</th> </tr> </thead> <tbody> <tr> <td>Close Requested</td> <td>10/12/2022 23:01</td> <td>Close Failed 10/12/2022 23:51</td> </tr> </tbody> </table> 	Vehicle Communication Line Atatus			Status	Request Date	Status Detail	Close Requested	10/12/2022 23:01	Close Failed 10/12/2022 23:51	<p>Possible customer has WiFi Contract. The customer must cancel WiFi contract.</p>
Vehicle Communication Line Atatus												
Status	Request Date	Status Detail										
Close Requested	10/12/2022 23:01	Close Failed 10/12/2022 23:51										
		<p>TCU has history of enrollment Status: Opened Status Detail: Open Completed (with date)</p> <table border="1"> <thead> <tr> <th colspan="3">Vehicle Communication Line Atatus</th> </tr> <tr> <th>Status</th> <th>Request Date</th> <th>Status Detail</th> </tr> </thead> <tbody> <tr> <td>Opened</td> <td>10/12/2022 23:01</td> <td>Open Completed 10/12/2022 23:51</td> </tr> </tbody> </table> 	Vehicle Communication Line Atatus			Status	Request Date	Status Detail	Opened	10/12/2022 23:01	Open Completed 10/12/2022 23:51	<p>OTP request successful. If not, go to No One Time Passcode (OTP) -> OTP Troubleshooting -> Step 2.</p>
Vehicle Communication Line Atatus												
Status	Request Date	Status Detail										
Opened	10/12/2022 23:01	Open Completed 10/12/2022 23:51										

TCU Activation

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

1. Select "hamburger menu" on top right of screen




2. From the MYMAZDA dropdown, select My Vehicles




CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

3. Select "menu" on top right of screen




4. Select "Add Vehicle"




CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

5. Select "SCAN VIN"




6. Select "SCAN"

Note: You can also manually enter the VIN if preferred. Select "ENTER VIN"




CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

7. Select "NEXT"




8. Select "VALIDATE"




CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

9. Select "NEXT"




10. Enter Vehicle Name and select local dealer. Then select "SUBMIT"




CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

11. Select "ENROLL"




12. Select "START"




CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.





13. Agree to the Terms & Conditions, then select "AGREE"



14. You will see a message stating "Activation Process in Progress", Select "CLOSE"



CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

<p>15. You will receive a message saying "Connectivity is Complete"; however, it is actually not complete. OK to close this window. Go to next step.</p>	
<p>16. Turn the ignition OFF for 10 minutes or longer.</p>	
<p>17. Turn the ignition ON.</p>	
<p>18. Check the Connected Vehicle reception strength icon:</p>	
<ul style="list-style-type: none"> Reception strength icon shows normal strength. TCU is now active. Proceed to Enrollment / Take-Over. 	

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

- Reception strength icon shows "X". TCU activation is still processing. Repeat steps 16-18.


Note:

- This step may need to be repeated a few times until normal strength is shown.
- If steps 16-18 was repeated several times with no change, disconnect 12V battery for 5-10 minutes, then recheck reception strength icon.




Diagnostic Information (ODR) Data Collection Procedure

1. ID the vehicle using MDARS




2. Select "Toolbox"

3. Select Vehicle Icon




CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.


4. Expand "Collect Diagnostic Information"



5. Select Collecting diagnostic information "Run".




6. Turn the ignition ON, then select "Next"




CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

7. Wait for collection to complete.



8. Confirm that the Diagnostic Information (ODR) collection has been successful. Select "Next" to exit.



CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Activating Remote Control by Smart Phone (links TCU to BCM)

NOTE: This procedure cannot be performed if the key transmitter power saving function is enabled. See SA-040/20.

1. Connect MDARS.




2. Use MDARS to verify if the Telematics Control Unit (TCU) is at the latest software level (Toolbox > Software Update > Run > TCU).

Is the TCU at the latest software level?

- **Yes:** Go to step 3.
- **No:** Update TCU software, then go to step 3.

3. Select the following:

- Toolbox
- Repair icon
- MAZDA CONNECT
- Activating Remote Control by Smart Phone
- RUN.




4. Follow the on-screen instructions and wait for process to complete.

NOTE: If the Activating Remote Control by Smart Phone shows "Incomplete", the possible causes are:

- The advanced key is not in the vehicle.
- The connected Vehicle Maintenance Mode is


CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

enabled.
 c. The Key transmitter power saving function is enabled.
 d. The pacemaker radio wave interference prevention function is enabled.



5. Select Quick Check (A), then start the engine and select the DTC Clear icon (B).

CAUTION: If the engine is not started, DTC P2610 is stored and cannot be erased.








TCU Software Version Check

1. Press and hold the Volume knob, then press and hold the Entertainment and Favorite buttons at the same time for 3-5 seconds and the Factory/Service Inspection screen will appear.

CX-5 and CX-9

Except CX-5 and CX-9






CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

		
<p>2. Select Service Information.</p>		
<p>3. Select TCU Linked information.</p>		
<p>4. Scroll down to TCU Software Version and confirm the software version is up to date. Go to Telematics Communication Unit (TCU) Updates Is the TCU software version correct?</p> <ul style="list-style-type: none"> • Yes: TCU Software Version Check is complete. • No: Go to Telematics Communication Unit (TCU) Updates to update the TCU software version. 		

TCU Remote Service Flag Information Check

<p>1. Press and hold the Volume knob, then press and hold the Entertainment and Favorite buttons at the same time for 3-5 seconds and the Factory/Service Inspection screen will appear.</p>	<p>CX-5 and CX-9</p>	<p>Except CX-5 and CX-9</p>
--	-----------------------------	------------------------------------

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

		
<p>2. Select Service Information.</p>		
<p>3. Select TCU Linked information.</p>		
<p>4. Scroll down to Remote Service Flag Information.</p> <p>Is the Remote Service Flag Information 1101... or 0000...?</p> <ul style="list-style-type: none"> • 1101... - Disconnect 12V battery for 1 hour, then retry connected vehicle enrollment. • 0000... - Contact Hotline for technical support. 		

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Customer Opt-Out

Some customers may request to stop data communication from their vehicle. Use this procedure to manually deactivate the TCU.

1. Check Connected vehicle reception strength icon




Infotainment Center displays "X"
No action needed.

Inform the customer that TCU is already deactivated. Data communication is not being transmitted from the vehicle




Infotainment Center displays normal reception.
Go to next step


2. Is the customer currently enrolled into Connected Vehicle services?




Yes - MCVV shows customer enrollment
Go to step 4.




CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

	<p>No - MCVV shows no customer enrollment Go to next step 3.</p>
<p>3. Enroll into Connected Vehicle services. Note: This step can be performed by dealer or customer.</p>	<p>Connected Vehicle Online Enrollment Information</p> <ol style="list-style-type: none"> 1. Installing the MyMazda APP 2. Registering Your User Information 3. Registering Vehicle Information 4. Registering Connected Service
<p>4. After enrollment, using the MyMazda App, delete VIN.</p>	<div style="display: flex; align-items: center;">  </div> <p>a. From the main screen, select menu.</p>

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.




b. From the MYMAZDA drop down, select My Vehicles



c. Select Edit Vehicle

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



d. Select Delete Vehicle

5. Turn the ignition OFF and wait 5-10 minutes



6. Turn the ignition on and confirm that the connected vehicle reception strength icon shows "X"

Inform the customer that TCU is deactivated. Data communication is not being transmitted from the vehicle

Note: The following functions have been disabled

- Connected Vehicle Services (Remote Functions, Find My Car....etc)
- In-car WiFi
- Recall Notifications
- Over the Air (OTA) software updates*
- Alexa*
- Hybrid Navigation*

*Some Models

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Educational Videos[Overview](#)[Using MyMazda App](#)[In-car Wi-Fi hotspot](#)[MyMazda remote](#)[Notifications](#)[Saftey features](#)**Resources**[Connected Vehicle Online Enrollment Information](#)

- [1. Installing the MyMazda APP](#)
- [2. Registering Your User Information](#)
- [3. Registering Vehicle Information](#)
- [4. Registering Connected Service](#)

[SA-015/23 - MAZDA CONNECTED SERVICES - FREQUENTLY ASKED QUESTIONS \(FAQ\)](#)[Dealer Connected Vehicle Questionnaire](#)[Connected Services Owner's Manual](#)[MAZDA CONNECT and MAZDA CONNECTED SERVICES USER GUIDE](#)[MAZDA CONNECTED VEHICLE VIEWER \(MCVV\) USER GUIDE](#)[MAZDA CONNECT ESSENTIALS \(30076WBT\)](#)[MAZDA CONNECT & CONNECTED SERVICES FOCAL POINT \(30093FOC\)](#)[MAZDA CONNECTED SERVICES SMART CARDS](#)[MAZDA CONNECTED SERVICES: CUSTOMER OUTREACH](#)

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.