

Technical product information

Topic	Engine light in the DIP - Various oxygen sensor / Fuel ratio DTC's logged within the Engine Control Module(s)
Market area	Bentley: worldwide (2WBE),China 796 VW Import Comp. Ltd (Vico), Beijing (6796)
Brand	Bentley
Transaction No.	2075331/1
Level	EH
Status	Approval
Release date	

Event memory entries

Diagnostic address	Event memory entry	Fault type	Fault status
0001 - Engine electronics	P003100: O2 Sensor Heater Contr. Circ.(Bank1(1)Sensor 1) Low		static
0001 - Engine electronics	P003000: O2 Sensor Heater Contr. Circ.(Bank1(1)Sensor 1)		static
0001 - Engine electronics	P005100: O2 Sensor Heater Contr. Circ.(Bank2 Sensor 1) Low		static
0001 - Engine electronics	P005000: O2 Sensor Heater Contr. Circ.(Bank2 Sensor 1)		static
0001 - Engine electronics	P016A00: Excessive Time To Enter Closed Loop Air/Fuel Ratio Control		static
0011 - Engine Electronics 2	P003100: O2 Sensor Heater Contr. Circ.(Bank1(1)Sensor 1) Low		static
0011 - Engine Electronics 2	P003000: O2 Sensor Heater Contr. Circ.(Bank1(1)Sensor 1)		static
0011 - Engine Electronics 2	P005100: O2 Sensor Heater Contr. Circ.(Bank2 Sensor 1) Low		static
0011 - Engine Electronics 2	P005000: O2 Sensor Heater Contr. Circ.(Bank2 Sensor 1)		static
0011 - Engine Electronics 2	P016A00: Excessive Time To Enter Closed Loop Air/Fuel Ratio Control		static

New customer code

Object of complaint	Complaint type	Position
electrical power, electric system, data transfer -> data bus systems	component / consumables	
vehicle service -> vehicle diagnosis -> guided fault finding	control units, services -> with event log entry	
power transmission -> power distribution, power flow -> power flow	functionality -> without function / defect	
electrical power, electric system, data transfer -> power supply	functionality	

Vehicle data

Continental GT/C - Flying Spur - Bentayga Series

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
3S3*	2018	E		*	*	*
3S3*	2019	E		*	*	*
3S3*	2020	E		*	*	*
3S3*	2021	E		*	*	*
3S3*	2022	E		*	*	*
3S3*	2023	E		*	*	*
3S3*	2024	E		*	*	*
3S4*	2019	E		*	*	*
3S4*	2020	E		*	*	*
3S4*	2021	E		*	*	*
3S4*	2022	E		*	*	*
3S4*	2023	E		*	*	*
3S4*	2024	E		*	*	*
4V1*	2017	E		*	*	*
4V1*	2018	E		*	*	*
4V1*	2019	E		*	*	*
4V1*	2020	E		*	*	*
4V1*	2021	E		*	*	*
4V1*	2022	E		*	*	*
4V1*	2023	E		*	*	*
4V1*	2024	E		*	*	*
ZG2*	2020	E		*	*	*

ZG2*	2021	E		*	*	*
ZG2*	2022	E		*	*	*
ZG2*	2023	E		*	*	*
ZG2*	2024	E		*	*	*
ZV1*	2023	E		*	*	*
ZV1*	2024	E		*	*	*

Documents

Document name
master.xml

Customer statement / workshop findings

Engine light in the DIP - Various oxygen sensor / Fuel ratio DTC's logged within the Engine Control Module(s)

Technical background

In the event that one or a combination of DTC's shown below are evident within the engine control module(s) the operative should carry out the instructions within the Measure section of this TPI

Production change

-

Measure

- 1) Referring to the VIN applicable wiring diagram within Elsa pro - Conduct a wiring integrity check of the oxygen sensor circuits
- 2) Locate the fuse(s) which are assigned to the oxygen sensor circuits
- 3) Conduct a visual inspection of the following:

- Fuse holder terminals - Check for damage / misalignment of terminals

Hint: In this scenario the terminals must be repaired / replaced (depending on damage) once repaired / replaced the fuse must be renewed, ensure both fuse blades are aligned to both terminals before fitting the fuse

- Fuse - Check for damage / bent fuse blade(s)

Hint: The fuse blades shown in Figure 1 are damaged / bent, in this scenario the fuse must be renewed, ensure both blades are aligned to both terminals before fitting the fuse




Figure 1

NOTICE

In the event the issue is still evident after conducting the previous steps, the operative must raise a to raise technical DISS query and await feedback before conducting any further work

Warranty accounting instructions

Warranty type: 110 or 910
 Service ID number: 24 70
 Damage type: 00 55

Diagnosis time

Labour operation code: 01 51 00 00
 Time: As per ODIS log must not exceed 50 TU

Time to conduct wiring integrity checks

Labour operation code: 97 09 01 00
 Time: 50 TU