

<b>REFERENCE:</b>	<b>TSB:</b> 18-076-24 <b>GROUP:</b> 18 - Vehicle Performance	<b>Date:</b>	October 4, 2024	<b>REVISION:</b>	18-027-24
<b>VEHICLES AFFECTED:</b>	<b>2023 (M6) Jeep Compass (India)</b> This bulletin applies to vehicles built on and after <b>**February 01, 2023 (MDH 0201XX)**</b> equipped with a 2.0L I4 Turbo Diesel Engine W/ESS (Sales Code EBS).	<b>MARKET APPLICABILITY:</b>			
		<input type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input checked="" type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH			
<b>CUSTOMER SYMPTOM:</b>	<p><b>Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must exhibit/set one or more of the following Diagnostic Trouble Codes (DTCs):</b></p> <ul style="list-style-type: none"> <li><b>**P2002 - Diesel Particulate Filter Flow Resistance Monitoring Too High Level 2 Component Or System Operation Obstructed Or Blocked.**</b></li> <li>Oil change service light comes on at 15,000km (9,321 Miles). The actual maintenance interval for the Australian market is 20,000km (12,427 Miles).</li> <li>"DEF Low Refill Soon" message will appear in the Instrument Panel Cluster (IPC).</li> <li>Engine power output is lower than expected when applying the throttle.</li> </ul> <p><b>**Customers may also comment on the following:</b></p> <ul style="list-style-type: none"> <li>Vehicle will go to limp-in mode.**</li> </ul>				
<b>CAUSE:</b>	PCM Software				

This bulletin supersedes Technical Service Bulletin (TSB) 18-027-24, date of issue March 28, 2024, which should be removed from your files. All revisions are highlighted with **\*\*asterisks\*\*** and include new vehicle build date, a new DTC, a new Customer Symptom and new LOPs.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 24-064, date of issue March 28, 2024. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

**REPAIR SUMMARY:**

This bulletin involves inspecting and possibly reprogramming the PCM with the latest available software.

**CLAIMS DATA:**

Labor Operation No:	Labor Description	Skill Category	Labor Time
**18-19-06-AH	Inspect Powertrain Control Module (PCM) (0 - Introduction)	1 - Engine Repair And Performance	0.1 Hrs.
18-19-06-AI	Inspect and Reprogram Powertrain Control Module (PCM) (0 - Introduction)	1 - Engine Repair And Performance	0.2 Hrs.**
Failure Code	RF	Required Flash	
	CC	Customer Concern	

**The dealer must choose which failure code to use depending on if this is a Rapid Service Update (RSU) or Technical Service Bulletin.**

- The “RF” failure code is required for essential module flash/reprogramming and can only be used after confirmation that the VIN is included on the RSU.
- The failure code “RF” (Required Flash) can no longer be used on Technical Service Bulletin flashes. The “RF” failure code must be used on an RSU.
- If the customer’s concern matches the SYMPTOM/CONDITION identified in the Technical Service Bulletin, failure code CC is to be used. When utilizing this failure code, the 3C’s must be supplied.

**DIAGNOSIS:**

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

**SPECIAL TOOLS/EQUIPMENT:**

Description	Ref. No.	Notes
wiTECH or Equivalent	–	–

**REPAIR PROCEDURE:**

**NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.**

**NOTE: If this flash process is interrupted/aborted, the flash should be restarted.**

1. Is the vehicle on the RSU VIN list?

- YES>>> Proceed to [Step 2](#).
- NO>>> Proceed to [Step 3](#).

2. Does the PCM have the latest software already installed?
  - YES>>> This bulletin has been completed, use Inspect LOP (18-19-06-AH) to close the active RSU.
  - NO>>> Proceed to [Step 3](#).
3. Reprogram the PCM with the latest available software. If issues arise when flashing a module using the wiTECH Diagnostic Application, please submit a ticket to the Helpdesk. The helpdesk can be found within the Help menu.
4. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

**POLICY:**

Reimbursable within the provisions of the warranty.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*