



Service Bulletin

Bulletin No.: 21-NA-120


Date: September, 2024

TECHNICAL

Subject: Diagnostic Tip for Noise, Vibration and/or Harshness Issues/Clunk Noise Heard During Coast Down Event

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 2500HD/ 3500HD	2020	2025			L5P, L8T	MGM, MGU, MKM
GMC	Sierra 2500HD/ 3500HD						

Involved Region or Country	North America, Middle East, Israel
Additional Options (RPOs)	NQF (TRANSFER CASE-ELECTRIC SHIFT CONT, TWO SPEED, ALUM) NQH (TRANSFER CASE-ACTIVE, TWO SPEED, SWITCH ACTIVATED, ALUM)
Condition	Some technicians or customers may comment on one or more of the following conditions after the transfer case was removed from the transmission and reinstalled during a recent repair: <ul style="list-style-type: none"> • Harsh downshift during a coast down event • Noise during a coast down event • Vibration during a coast down event • Harshness issues such as a clunk noise heard during coast down event
Cause	This condition may be caused by a misalignment between the transmission output shaft and the transfer case input. ⇒ Transfer case to transmission misalignment could cause the transfer case shift collar to slip out of engagement.

<p>Correction</p>	<div style="text-align: center;">  </div> <p style="text-align: right; font-size: small;">5411622</p> <ol style="list-style-type: none"> 1. Connect the GDS Scan Tool and monitor transmission shift data. 2. Drive the vehicle and duplicate the condition while monitoring transmission shift data to determine if the noise/clunk/roughness occurs during the downshift or if the noise/clunk/roughness occurs randomly during the de-acceleration event. <p>⇒ If it is determined that the noise/clunk/roughness does not occur at a transmission downshift, shift point follow published Service Information for Transfer Case Assembly Replacement (with MGM, MGU, MKM Automatic Transmission).</p> <p>Note: The transfer case does not need to be completely removed from the vehicle. The attaching bolts must be loosened (not removed) to allow the transfer case to be separated from the transmission a minimum of a ½ (13mm) but no more than 1 inch (25mm). The use of transmission jack or adjustable jack stand may provide support in holding the transfer case to the transmission. Proper transfer case to transmission bolt installation, tightening sequence and proper torque must be followed.</p> <p>If the noise/clunk/roughness is occurring during a transmission downshift, shift point, refer to SI for further diagnostics.</p>
--------------------------	--

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Version	5
Modified	Released May 24, 2021 Revised November 17, 2022 - Added 2022 and 2023 Model Years. Revised September 19, 2023 - Added 2024 Model Year. Revised January 17, 2024 - Added L8T to Engine RPO section. Revised September 16, 2024 - Added 2025 to Model Year.

