



Bulletin No.: PIT6147A
Published date: 09/20/2024

Preliminary Information

PIT6147A Unable To Complete SPS Programming Of The Instrument Panel Cluster (IPC)

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet	Silverado 1500 New (RPO J22, VIN Digit 5 = A / D)	2022	All	All All	All
Chevrolet	Silverado 1500	2023 - 2024	All	All All	All
Chevrolet	Silverado 2500HD/3500HD	2024	All	All All	All
Chevrolet	Suburban	2021 - 2024	All	All All	All
Chevrolet	Tahoe	2021 - 2024	All	All All	All
GMC	Sierra 1500 New (RPO J22, VIN Digit 5 = H / U)	2022	All	All All	All
GMC	Sierra 1500	2023 - 2024	All	All All	All
GMC	Sierra 2500HD/3500HD	2024	All	All All	All
GMC	Yukon	2021 - 2024	All	All All	All

Involved Region or Country	North America
Additional Options (RPO)	UDV - Instrument Panel Cluster
Condition	A dealer may find that the Instrument Panel Cluster (IPC) will not complete SPS programming and they receive a popup box to select a part number.
Cause	The bootloader software part number may not have populated when attempting to SPS program the IPC.

Correction:

If prompted by SPS to select a part number, use GDS2 to find *Boot Software Part Number 1* under P16 Instrument Panel Cluster Control Module / Identification Information for the correct part number.



Note: If the Boot Software Part Number 1 is not listed in the dropdown list in SPS, contact Techline Customer Support Center for assistance.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810195	Instrument Cluster Reprogramming with SPS	Use Published Time

Version History

Version	2
Modified	04/09/2024 - Created on. 09/20/2024 - Updated Condition and Correction information