



Bulletin No.: PIC6549A
Published date: 09/26/2024

Preliminary Information

PIC6549A Black Radio Screen

Models

Brand: Chevrolet Trax **Model:** Trax **Model Years:** 2024 **VIN:** All **Engine:** All **Transmissions:** All

Involved Region or Country	North America
Additional Options (RPO)	IVA
Condition	A customer may comment that their radio display may have gone blank.
Cause	Please verify the software in the radio is up to date. This can be found in settings>about. If it is lower than 169.3, please update the radio before proceeding with this PI. This may be due to software anomaly or a loose/defective LVDS cable

Correction:

Correction:

First verify that the LVDS connection at the radio control, Instrument panel display, and radio are seated properly.

If there is a bad/loose connection, correct the condition and retest

If the connections were seated properly, or after correcting a loose connection and the condition still exists, replace the LVDS cable.

If the condition still exists after LVDS cable replacement contact TAC


Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
3486268	Verify LVDS connections at Radio, Radio control, and IPC display	0.8
Add time	Replace LVDS cable	1.0
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	2
Modified	05/07/2024 - Created on. 09/26/2024 - Updated to change correction and add labor op

 GM Global Brands
© 2024 General Motors. All Rights Reserved.