



Bulletin No.: PIC6502B
Published date: 09/27/2024

Preliminary Information

PIC6502B Accessing the Rear Compartment In the Event of a Power Loss

Models

Brand: Chevrolet **Model:** Corvette **Model Years:** 2020 - 2025 **VIN:** All **Engine:** All **Transmissions:** All

Involved Region or Country	North America
Condition	Some customers may comment that they are unable to access the rear compartment in the vehicle if there is a loss of battery power.
Concern	If there is a loss of battery power to the vehicle, and the customer requires access to the rear compartment, follow the instructions below.

Correction:

For model years 2020 - 2022, remove the rear license plate to access the lock cylinder. Remove the mechanical key shank from the transmitter, insert it into the lock cylinder, and rotate it to open the rear compartment.

If the vehicle is a 2023+ model year, then the mechanical lock cylinder located behind the rear license plate has been eliminated on all variants. Another possible scenario, is if the vehicle had previously been in an accident where the rear tub assembly had been repaired / replaced. The new tub may not have provisions for the lock cylinder. In either case, one of several alternate methods must be used to access the rear compartment on these vehicles. The following methods are organized from the easiest, to the most difficult. Please try the simple attempts first, before attempting the more involved methods to access the rear compartment. If any one method works, there is no need to continue with the rest of this document. It is highly suggested that the technician view the January 2023 Emerging Issues Video before attempting any of these procedures. This is currently listed as course #10223.01V. The following three methods will address an electrical failure of the rear compartment latch assembly.

If the vehicle is a convertible (RPO CM9), then an easy method to gain access to the rear compartment is to follow the document in SI titled "Opening the Liftgate Latch Without Electrical Power", currently Document ID: 6291324. This will direct the technician to first apply paint protection to the vehicle, and then fully open the rear stowage compartment lid, commonly referred to as the tonneau panel. Insert a wedge or airbag tool in order to open up a slight gap between the leading edge of the weather stripping and the rear compartment lid. Then, insert a slender tool with a bore scope attached. Locate and pull on the emergency release handle that is located on the RH (passenger) side of the latch assembly.

NOTE: The following method is only possible when the rear compartment is not full of items that may block access to the emergency release handle in the trunk. Ask the customer if they have any items in the rear compartment such as groceries, golf bags, rigid items, etc. SOME items may be in the rear compartment that will not affect this attempt at all, so it still may be worth trying this method.

A potential method that can be used to gain access to the rear compartment for a coupe or a convertible, is to follow the document in SI also titled "Opening the Liftgate Latch

Without Electrical Power", currently Document ID: 6287070. The first step to accessing the rear compartment is to raise the vehicle on a lift. Remove the right rear wheel/tire assembly. Partially remove the rear of the wheel liner to access the grommet in the body. A large wiring harness runs from the wheel well area into the rear compartment. Remove the rubber grommet and gently push the wiring harness aside. Obtain a slender tool with a hook on the end. Attach a bore scope to this tool and insert it into the rear compartment access. Locate and pull on the emergency release handle that is located on the RH (passenger) side of the latch assembly.

If the customer has items in the rear compartment that prevent access to the emergency release handle, an alternate method will have to be used. Regardless if the vehicle is a coupe or a convertible, the tech will need to follow the procedure shown in the January 2023 Emerging Issues Video (beginning at the 22:34 mark) for drilling the appropriate access hole in the rear tub. Refer to the SI document also titled Opening the Liftgate Latch Without Electrical Power, currently Document 6287071. The servicing tech MAY need to obtain a specific tool for this procedure as well. This tool is not called out in specific detail in SI.

Follow the directions found in the video to open the rear compartment using this method.

Finally, one last possibility exists, and that is when the rear compartment latch assembly has a mechanical concern, and none of the methods listed above will work. If that is the case, please create a brand new case by contacting the Technical Assistance Center (TAC) and then calling them to discuss potential next steps. Refer to this PIC when creating the case.

Warranty Information

Because the repair may be one of several listed, please use the labor op that most closely matches the repair that was required.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

Version History

Version	3
Modified	05/10/2023 - Created on. 08/07/2024 - Update model year. 09/27/2024 - Update model year.

Attachments

- [Z06 - E-RAY - STINGRAY.pdf](#)

 GM Global Brands

© 2024 General Motors. All Rights Reserved.