



Technical Service Bulletin

45 DTC C1399F0 is stored in the ABS control module

43 24 99 2063679/5 September 10, 2024. Supersedes Technical Service Bulletin Group 45 number 24-38 dated January 12, 2024 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
e-tron GT, and RS e-tron GT	2022 – 2025	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
5	-	Revised header (Added Model Year) Revised Technical Background (Updated Information) Revised Warranty (Removed Warranty Table)
4	01/12/2024	Revised header (Added Model Year)
3	05/20/2022	Revised header (Added Model Year)

Customer states:

- Recuperation too low when braking on new vehicle.

Or

- After brake discs/brake pads have been replaced.

Workshop findings:

The following DTC may be stored in the ABS control module, -J104- (address word 0003):

- **DTC C1399F0** (Brake application mode active).

Technical Background 1

The brake application mode for breaking in the pad on the disc is being used for the first time at Audi.

This can be initiated in ODIS via “003 Brake-In Service Brakes”, whenever any of the brake discs and/or brake pads are replaced and is also active on new vehicles.

At the same time, recuperation is deactivated, and braking is performed manually. During this time, the specified DTC (C1399F0) is logged in the ABS control module, J104 (address word 0003).

The breaking-in process then takes place when the brakes are applied while driving. This is not shown actively to the customer in the instrument cluster or the MMI.

This mode and the DTC are deactivated automatically when the required amount of energy is reached, (for example: when the breaking-in process is complete).



Technical Service Bulletin

The percentage reached by the brake application mode can be read out via the measured value “Progress of the break-in of service brakes” in the ABS control unit.

Production Solution

Not applicable.

Service

No measure is necessary (refer to Technical Background).

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2063679**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.