

Quality Bulletin

TITLE:

**Delivery Action DP1033: PS3 MK C1 Rattling Noise
Model Year 2025 Polestar 3**

GROUP: 52	NO: DP1033	ISSUING DEPARTMENT: Product, Safety and Compliance	CAR MARKET: United States and Canada	
REVISIONS:			ISSUE DATE: 2024-10-18	STATUS DATE: 2024-10-18
Page 1 of 2				

BULLETIN REFERENCE

- A. DELIVERY ACTION DP1033 DESCRIPTION
- B. VEHICLES INVOLVED
- C. PORT VEHICLES
- D. PARTS INFORMATION/PARTS RETURN
- E. OWNER NOTIFICATION
- F. VEHICLES IN INVENTORY
- G. SERVICE POINT RESPONSIBILITY
- H. TECHNICIAN COMPETENCY REQUIREMENT
- I. REIMBURSEMENT PROCEDURES & ALLOWANCE

A. DELIVERY ACTION DP1033 DESCRIPTION

Polestar Automotive USA on behalf of Polestar Performance AB, has decided to launch Delivery Action DP1033: PS3 MK C1 rattling noise on certain MY 2025 Polestar 3 vehicles.

Polestar has identified that the hydraulic unit (MK C1) may cause a rattling noise when depressing the brake.

The corrective action is to replace the hydraulic unit (MK C1) according to VIDA instructions.

A total of 7 U.S. vehicles are eligible for this Delivery Action.

B. VEHICLES INVOLVED

NOTE: SERVICE POINT MUST CONFIRM VEHICLE ELIGIBILITY PRIOR TO BEGINNING THE REPAIR FOR THIS DELIVERY ACTION. VEHICLES IN RETAILER INVENTORY MUST BE REPAIRED PRIOR TO DELIVERY.

Vehicle eligibility must be confirmed:

- Vehicle Inquiry – Warranty Vehicle Inquiry where the message “Delivery Action DP1033 PS3 MK C1 Rattling Noise” will appear for eligible vehicles, F4=History from the main Inquiry menu must be selected to confirm Delivery Action DP1033 has not been completed. Eligibility can also be confirmed in VIDA.

Quality Bulletin DP1033

All vehicles must be checked for any incomplete Recalls, Service Campaigns, or Service Upgrades. All open Recall, Service Campaigns or Service Action repairs must be completed.

C. PORT VEHICLES

NOT all eligible vehicles arriving from the ports will have been completed. It is the Service Point's responsibility to check vehicle eligibility prior to delivery.

D. PARTS / PARTS RETURN

Please refer to Parts Bulletin DP1033.

E. OWNER NOTIFICATION

No owner notification. This action does not apply to retailed vehicles.

F. VEHICLES IN INVENTORY

All vehicles marked for Delivery Action DP1033 must be remedied prior to delivery.

G. SERVICE POINT RESPONSIBILITY

All vehicles qualifying for this Delivery Action must be repaired prior to a customer taking possession of the vehicle at new car delivery.

H. TECHNICIAN COMPETENCY REQUIREMENT

The technician competency requirement for this campaign repair is G1.

I. REIMBURSEMENT PROCEDURES & ALLOWANCE

Delivery Action DP1033 claims should be submitted using the LONG FORM application only.

Claim Type: DP1033
Cause Code: 02
CSC Code: XW
Main OP: 97567-2

Failed Part No: 36010807 (Hydraulic unit, exch)

<u>Operation Number</u>	<u>Repair Description</u>	<u>Qty</u>	<u>Models</u>	<u>Labor Time</u>
97567-2	Brake Control Module, replace acc. to QB	1	Polestar 3	1.8
99942-2	Software download acc. to QB	1	Polestar 3	0.5
99943-3	Software download acc. to QB	1	Polestar 3	0.2

*Labor times provided are current at the time of release and are subject to change: Claims will be paid at the time in effect on the repair date.