

Technical Service Bulletin (TSB) Oil Change Monitor Displaying Prematurely

REFERENCE:	TSB: 01-001-24 REV. A GROUP: 01 - Lubrication and Maintenance	Date:	October 29, 2024	REVISION:	01-001-24
VEHICLES AFFECTED:	2023 - **2025** (GC) Alfa Romeo Tonale 2023 - **2025** (GG) Dodge Hornet			MARKET APPLICABILITY: <input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH	
CUSTOMER SYMPTOM:	Customers may experience the following: <ul style="list-style-type: none"> The oil change light is illuminated on the Instrument Panel Cluster (IPC) shortly after taking delivery of the vehicle within 6,437 Km (4,000 mi). 				
CAUSE:	Manufacturing issue				

This bulletin supersedes Technical Service Bulletin (TSB) 01-001-24, date of issue October 11, 2024, which should be removed from your files. All revisions are highlighted with ****asterisks**** and include adding 2025 model year vehicles to Vehicles Affected and new LOPs.

REPAIR SUMMARY:

This bulletin involves resetting the oil life monitor and if necessary, changing the engine oil and filter.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
**09-55-01-97	Reset Enhanced Automatic Oil Change Indicator (0 - Introduction)	1 - Engine Repair and Performance	0.2 Hrs.
09-55-01-98	Change Engine Oil and Filter, Includes Reset Enhanced Automatic Oil Change Indicator (0 - Introduction)	1 - Engine Repair and Performance	0.7 Hrs. **
Failure Code	ZZ	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1 (AR)	68439517AA	Filter, Engine Oil	1.3L Engine
5 qts / 4.7L (AR)	68523988AA	Oil, 0W-30 Quart	1.3L Engine
1 (AR)	04892339BE	Filter, Engine Oil	2.0L Engine
5 qts / 4.7L (AR)	68523981AA	Oil, 5W-30 Quart	2.0L Engine

DIAGNOSIS:

Upon initial delivery of a stored vehicle to the customer, validate the mileage on the vehicle and determine the number of days since the vehicle was built. Perform the repair below according to both the mileage and the number of days since vehicle build.

Prior To Delivery Of Vehicle To Customer

1. If the number of days since vehicle build is equal to or less than 365 days, **AND** if mileage is equal to or less than 241 Km (150 mi), the oil life monitor should be reset/cleared. Proceed to [Step 2](#) of the Repair Procedure.
2. If the number of days since vehicle build is greater than 365 days **OR** the mileage is greater than 241 Km (150 mi), the engine oil and filter should be changed, and the oil life monitor reset/cleared, proceed to [Step 1](#) of the Repair Procedure.

Customer Owned Vehicle

1. If a customer brings the vehicle back to the dealer due to the oil service light being on with less than 6,437 Km (4,000 mi) on the vehicle, the dealer should change the oil and filter, and reset/clear the oil life monitor under warranty. Proceed to [Step 1](#) of the Repair Procedure.
2. If a customer brings the vehicle back to the dealer due to the oil service light being on with more than 6,438 Km (4,001 mi) on the vehicle, this bulletin does not apply. Normal oil change procedure should be performed.

REPAIR PROCEDURE:

1. Perform an engine oil and filter change. Refer to the detailed service procedures available in DealerCONNECT> Service Library under: Service Info> 09 - Engine, 1.3L or 2.0L / Lubrication / Oil / Standard Procedure (Engine Oil And Filter - Replacement).
2. Perform an Oil Change Reset procedure below.
 - Without pressing the brake pedal, push the Engine Stop/Start (ESS) button and cycle the ignition to On/Run position (**do not start the engine**).
 - Fully depress the accelerator pedal, slowly, three times within 10 seconds.
 - Cycle the ignition to the Off position.

NOTE: If the oil change indicator message illuminates when the vehicle is started, the oil change indicator system did not reset. If necessary, repeat this procedure. If the above procedure fails to complete, use the scan tool to complete the reset process.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.