



**Countries:** AUSTRALIA, BAHAMAS, BOLIVIA, BRAZIL, BELIZE, CANADA, CHILE, TAIWAN, COLOMBIA, COSTA RICA, DOMINICAN REPUBLIC, ECUADOR, EL SALVADOR, GUAM, GUATEMALA, GUYANA, HAITI, HONDURAS, JAMAICA, KOREA, SOUTH KOREA, MEXICO, ARUBA, NEW ZEALAND, NICARAGUA, PANAMA, PERU, PUERTO RICO, RUSSIA, SOUTH AFRICA, TRINIDAD AND TOBAGO, UNITED STATES, URUGUAY, VENEZUELA, Curaçao

**Document ID:** IK1400023

**Availability:** ISIS, Bus ISIS, FleetISIS, Body Builder, IsSIR

**Major System:** REAR AXLE

**Current Language:** English

**Other Languages:** [Français](#), [Español](#)

**Viewed:** 31586

**Revision:** 23

**Created:** 9/4/2012

**Last Modified:** 10/8/2024

**Author:** Mark Ehlers

[Less Info](#)

Hide Details

Coding Information

<b>Copy Link</b> 	<b>Copy Relative Link</b> 	<b>Bookmark</b>  <a href="#">View My Bookmarks</a>	<b>Add to Favorites</b> 	<b>Print</b> 	<b>Provide Feedback</b> 	<b>Helpful</b>  115	<b>Not Helpful</b>  13
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	---------------------------	------------------------------

**Title: Suspension Lean Diagnostics**

**Applies To: All Vehicles**

## Change Log

**Dealers: Please refer to the change log text box below for recent changes to this article:**

09/09/2034 - Updated article with MV & HV parts

07/15/2018 - Added new information to include CV Model units, also added a note that changing seats and plates can effect driveline angles, so measurements need to be taken.

11/06/2018 - Reassigning to different owner

06/09/2016 - Information added about induced leans under the "CAUTION:" tab.

12/14/2015 - Part number change to show correct shim thickness.

## Description

This article addresses chassis lean conditions on all chassis. **This does not include any diagnostics for body leans such as a cab lean.** Keep in mind that a chassis lean may cause or accentuate a cab lean. Filling out the printable form and using the notes in blue will help you to determine the source of the lean and identify the action and parts required to correct the lean. If you are not able to come to a repair direction after completely following the article and filling out the form, please attach the form and requested photos to a case file for further assistance.

- For any lean issues with a front suspension rating of 8,000 LBS or less please refer to [IK0300061 - 8,000 LBS Front Suspension Lean Correction](#).
- Some trucks are intentionally manufactured with different front axle spring rates on the driver and passenger sides. The Parts Catalog will illustrate this. Many MV's have this design feature.
  - If a chassis has a front lean complaint of less than 1/2 inch, AND there is no body installed, AND the parts catalog shows that it has different part number springs on front drivers side versus front passenger side, then DO NOT troubleshoot the lean until the body is installed or significant weight is installed on the chassis
- IROS 4x2 chassis require the most measurements. A front shim, rear seat or frame issue are the possible repair paths depending on the measurements in all steps of the diagnostic form. It is critical to take accurate measurements for all steps to determine if the issue is being caused by the rear suspension.
  - IROS 6x4 diagnostics does not include the pin bar height measurement. This is due to 4 points of contact to the frame for the rear suspension. Changing rear seats in an IROS equipped 6x4 will have minimal impact on a chassis lean.

- Other air suspensions designs do not allow the rear suspension to impact a front lean the way an IROS suspension can. As a result it has been found that a front shim or frame issue are the most common repair practices based on the results of the measurements.
- Vari-Rate rear spring suspension can be shimmed in the front or rear to correct a lean. A shim or a frame repair are the most common repair practices based on the results of the measurements.
- If you are unable to resolve the lean after completely following the iKNOW article, please open a case file with the form completely filled out. Attach the form and the 4 requested photos to the case file.

**CAUTION :**

- Shimming is not an acceptable practice for chassis lean created by the addition of auxiliary equipment or loading practices resulting in vehicle lean. These procedures are intended to assist the service technician in making industry acceptable corrections for nominal lean issues and are not intended to compensate for over/uneven loading or un-repaired vehicle damage - regardless of cause.
- There is an orderable option that will in fact create a lean for a purpose to compensate a heavy body install (Cement Mixers, Snow Plows). If the unit is leaning, refer to the component section of the unit in Service Portal. This feature is added for most DuraStars with 8k front ends with batteries, DEF tank, Air Tanks, and Fuel Tank all on the Left side.
  - 0003WAM - Typically a 1" spacer is installed on the Front Left.
  - 0503013 - May be built with different rate springs on left versus right or a 1/2" spacer is installed on the Front Left.

**NOTE:**


- On an air ride suspension, replacing the air spring or the MSM (main support member, aka – rear spring) will not have any effect on lean.
- Warranty will NOT COVER replacing a spring for the following complaints:

Weak spring	Leaning
Bottoming out	Lost arch

**Service Parts Information**

- Springs are very rarely found to be the cause of a lean. As a result, the most common springs that are replaced with no issue found upon review have been listed at the bottom of this article. To review the spring information [CLICK HERE](#)

Figure	Kit Description	Part Number	Quantity Required	Notes
1	3 Inch Wide x 1/2 Inch Thick Front Spacer (has center dowel in it)	2512808C1	1	As Needed
2	4 Inch Wide x 5.8 x 1/8 Inch Thick Front Spacer	442078C2	1	As Needed
2	4 Inch Wide x 5.8 x 3/8 Inch Thick Front Spacer	322019C4	1	As Needed
2	4 Inch Wide x 8.8 x 1/8 Inch Thick Front Spacer	442388C1	1	As Needed
2	4 Inch Wide x 8.8 x 3/8 Inch Thick Front Spacer	1618382C1	1	As Needed
3	4 Inch Wide x 1/4 Inch Thick Rear Spacer	493720C3	1	As Needed
3	4 Inch Wide x 3/8 Inch Thick Rear Spacer	540069C3	1	As Needed
3	4 Inch Wide x 1/2 Inch Thick Rear Spacer	493721C3	1	As Needed
	500871c2 = 1 inch spacer, 3956545c2= 2 inch spacer, 3894346c2= 1.5 inch spacer			



## Diagnostic Steps

- The diagnostic steps vary based on suspension type.
- The locations the chassis should be measured are the same on all types of suspensions.
  - This will allow for the most accurate results.
- Proper locations to measure for chassis lean (All suspension types).

**Figure 4**  
**Right Front Spring Shackle Bolt**



**Figure 5**

Left Front Spring Shackle Bolt



Figure 6  
Aft Frame Straight Truck





Figure 7  
Aft Frame Tractor




- Clicking the links below will open a printable form in a new window and jump to the appropriate section of this iKnow article.

Printable Form	
IROS Suspension	<a href="#">Click Here</a>
Other Air Suspension	<a href="#">Click Here</a>
Vari-Rate Suspension	<a href="#">Click Here</a>

## IROS Suspension

1. Check front axle suspension weight rating.
  - For any lean issues with a front suspension rating of 8,000 LBS or less please refer to [IK0300061 - 8,000 LBS Front Suspension Lean Correction](#).
2. Check the unit for any offset loading.
  - Note any items that may cause offset loading.
  - *If offset loading is present advise non-warrantable cause. Advise installing 14WAS – Dual leveling valves to correct issue.*
3. Inspect the suspension for any third party (bodybuilder) installed components such as stabilizer bars.
  - International does not install stabilizer bars on most suspensions.
  - Exceptions: BE Buses, Front suspension on CityStars, and the Multi-Link front air suspension (These will have stabilizer bars).
  - *Advise non-warrantable to remove components. Recommend removal of components to confirm they are causing the lean.*
  - *Also, a 3rd party component could be an item causing an offset load. Keep that in mind.*

4. Check the tire pressure for all tires.
  - o Adjust pressures if needed.
  - o Record current tire pressures.
  - o *It is recommended each axle be with 5% of each other. Especially if the lean is marginal.*
  
5. Verify ride height is properly set per instructions below.
  - o Park the vehicle unloaded on a level surface with a light application of the brakes.
  - o Do not apply the parking brake. Chock wheels to prevent vehicle movement.
  - o Make sure 120 psi is in the vehicle air system, and then shut off engine.
  - o Dump air from system, then re-pressurize and allow it to return to the ride height.
  - o Measurements are taken at the air spring assembly closest to the height control valve (usually forward left).
  - o Measure the vertical distance from the bottom of the straight edge that is resting against the u-bolts, to the bottommost position of the axle stop.
  - o **There should be no angle created between the two measurement points.**



- o If you're outside the listed values on the table below, the height control valve will need to be adjusted. If adjustment is needed [CLICK HERE](#)

<b>IROS Suspension Height Adjustment Specification Chart</b>			
<b>IROS Suspension Feature Code</b>	<b>Config</b>	<b>Model</b>	<b>Axle Travel in Inches (measured from axle stop, see Figure 2)</b>
14UNN, 14UNM, 14UNL, 14UNS, 14UNT, 14UNU	6x4	All	$2.75 \pm 0.125$ or $2 \frac{3}{4} \pm \frac{1}{8}$
14TBJ	4x2	7000, 8000, 9000	$2.75 \pm 0.125$ or $2 \frac{3}{4} \pm \frac{1}{8}$

14TBJ, 14TBG, 14TBH, 14TBK, 14TBR, 14TBS, 14TBT  <b>NOTE: For 14TBS, 14TBT Verify Model</b>  <b>NOTE: Above Codes are not with 14WAW</b>	4x2	3200, 4000. CE 200, CE 300, FE 300	$3.0 \pm 0.125$ or $3 \pm \frac{1}{8}$
14WAW (Flat Floor)	4x2	3000	$2.7 \pm 0.125$ or $2 \frac{11}{16} \pm \frac{1}{8}$
14TBS, 14TBT  <b>NOTE: For 14TBS, 14TBT Verify Model</b>	4x2	RE 200, RE 300	$2.375 \pm 0.125$ or $2 \frac{3}{8} \pm \frac{1}{8}$
14TBL, 14TBM, 14TBN  <b>NOTE: Verify Build Date</b>	4x2	4000	$4.6 \pm 0.125$ or $4 \frac{5}{8} \pm \frac{1}{8}$ <b>Models built before 02/23/2004</b> $3.2 \pm 0.125$ or $3 \frac{3}{16} \pm \frac{1}{8}$ <b>Models built starting 02/23/2004</b>
14UNH	6x4	9000	$1.55 \pm 0.125$ or $1 \frac{9}{16} \pm \frac{1}{8}$
14TBY	4x4	CXT, 7000	$3.1 \pm 0.125$ or $3 \frac{3}{32} \pm \frac{1}{8}$
14TCH	4x2	TerraStar	$3.0 \pm 0.125$ or $3 \pm \frac{1}{8}$
14TCP, 14TCR	4x2	AE Bus	$3.0 \pm 0.125$ or $3 \pm \frac{1}{8}$
<b>All dimensions are in inches</b>			

6. Once the proper ride height is set, and air bags are inflated with 120 psi, measure each corner of the vehicle as shown in Figures 4-7 and record measurements.

- The front tires MUST be pointed straight forward to prevent any influence to the lean from King Pin Inclination.
- Measure the front suspension at the spring shackle bolt as shown in Figures 4 and 5. Mark the bolt with a paint pen so you have a reference point for future measurements that may be required.
- Measure the rear of the vehicle at the aft frame flange (bottom of the flange) as shown in Figures 6 and 7. Location may vary slightly by application.
- *If the lean is less than or equal to 3/8" Front and/or Rear, the vehicle is in spec. The repair is not warrantable.*
- *You can still advise on what repair would correct the lean, but at customer pay.*

7. Dump the air from the suspension and verify the frame stop is touching the axle U-bolt on both sides of the truck. The frame stop may not touch the U-bolt on all vehicles. The space between the frame stop and U-bolt should be even from the right to left side for those applications.


- Remeasure from the same locations used in Step 6 and record (Measurements are taken with suspension dumped).
- This will help show if the rear suspension is contributing to the lean (Especially 4x2 chassis), or help confirm a frame issue as the cause.


- *Looking to see if opposite corners are still low (e.g. LF low RR low) which may help show a frame twist. Lean must be greater than 3/8".*
- *Looking to see if the rear goes into specification with suspension dumped. This may help show the Bar Pin Height is contributing, or show the frame is not twisted (Where a front shim may correct).*
- *If the front and rear both level out and the Bar Pin Height is not equal (Step 9) suspect an issue with a rear seat (4x2).*

### Re-inflate the air suspension before continuing

- Use a jack and place a 1 1/2" inch block under the **Front** tire with the lowest reading. (Do not drive the vehicle on to the block).
  - Remeasure from the bottom of the frame to ground and record.
    - This will show us how the rear suspension reacts and if shimming will help to correct the issue. (If the lean is prevalent in the front).
  - *Looking at the reaction in the rear here. (e.g. If the LF has a block, the weight transfer should cause the RR to be lower than the measurement at #6).*
  - *Use this information together with #7. Suspension reaction with a block together with suspension difference when the suspension is dumped.*
- Measure from the center of the bar pin to the ground and record. (This step only applies to Single Rear Axle vehicles).
  - Remove wooden block if previously installed.
  - You must remove the Spring Eye Bushing mounting bolts.
  - Using a frame jack at the rear of the vehicle, raise the frame evenly until the Bar Pin clears the Mounting Bracket on both sides.
    - The rear tires should still be on the ground during this procedure. Only lift the rear of the frame until the Bar Pin clears the mounting bracket.
    - This will help determine if there is an issue with a rear seat or rear seat mounting.
  - See Figure 8 below.
  - Do not perform this step on 6x4 configurations.
  - *If the Pin Bar Height is greater than 7/16" difference the repair will require changing a seat out on one side.*
  - *If the Pin Bar Height is 7/16" or less shimming the front suspension (steer axle) will be required to correct the lean.*
  - *You will need to watch what the result is in #8 closely when this measurement is off.*

Figure 9





10. Record the axle seats degrees or part number on the physical part if possible. See Figure 10 and Figure 11 below.
- *If a seat change is required to correct the lean, only change 1 seat size. (Only 1 seat will be replaced).*
  - *The seat that needs to be changed is the Pin Bar measurement that is smaller. (Only 1 seat will be replaced).*
  - *The change should increase the Pin Bar height on the Low Side.*
  - *If the seat is changed, measure drive line angles BEFORE and AFTER as these measurements may change.*
  - *If the seat is changed, make sure the correct Seat Plate is installed or changed if needed.*
  - *If the thicker side of the seat is facing forward (towards the steer axle) choose a seat one size smaller.*
  - *If the thicker side of the seat is facing rearward (away from the steer axle) choose a seat one size larger.*

Figure 10




Figure 11



11. Take 4 photos of the unit. Please ensure the photos clearly show the lean. (Only perform this step if a case file is needed).

- o Front, Rear, Left Side, Right Side.
- o *For documentation purposes. This will help show any potential offset loading (A/C system in a commercial bus, hydraulic tank, etc..) and the severity of the observed lean.*
- o *This is especially true if you have a case file with a front suspension less than or equal to 8000 lbs and shimming did not resolve the issue.*

Seat Parts Information				Plate Parts Information		
Pinion Angle Loaded	Machined Part Number	Cast Part Number	Cast Pinion Angle (As listed in parts catalog)	4x2 HD Plate	4x2 MD Plate (with Shock Mount)	
					Left Side	Right Side
0.60	3601570C2	3548295C1	2	3541719C3	3541725C3	3541726C3
2.26	3601571C2			3541720C3	3541727C3	3541728C3
2.50	3601572C2	3548296C1	4	3541720C3	3541727C3	3541728C3
2.75	3601573C2			3541720C3	3541727C3	3541728C3
3.23	3601574C2			3541720C3	3541727C3	3541728C3
3.47	3601575C2			3541721C3	3541729C3	3541730C3
4.45	3601576C2	3548297C1	6	3541721C3	3541729C3	3541730C3
5.42	3601577C2			3541721C3	3541729C3	3541730C3
8.33	3601579C2	3548298C1	10	3541722C3		
9.55	3601581C2			3541723C3		
10.28	3601583C2	3548299C1	12	3541723C3		
10.52	3601584C2			3541723C3		
11.49	3601585C2			3541724C3		
12.20	3601586C2	3548300C1	14	3541724C3		
12.46	3601587C2			3541724C3		

<b>يروس FEATURES for MV</b>			
0014TDE			
0014TBS			
0014TDV			
0014TBL			
0014TBM			
0014TBN			
0014TBJ			

<b>Shock Style</b>	<b>TOP SEAT</b>	<b>BOTTOM SEAT</b>	<b>Degree</b>
Outboard	3789563C2	3541719C3	-6
Outboard	3789567C1	3541720C3	-4
<b>Inboard</b>	3548295C2	3541725C3	Left
		3541726C3	Right
Outboard	4328054C1	3541719C3	-6
Outboard	3789571C2	3541721C4	-2
<b>Inboard</b>	3601568C3	3541727C4	Left
		3541728C4	Right
<b>Inboard</b>	3548296C3	3541727C4	Left
		3541728C4	Right
<b>Inboard</b>	3548297C3	3541729C4	Left
		3541730C4	Right

<b>يروس FEATURES for HV</b>			
14TBS			
14TBJ			

<b>Shock Style</b>	<b>TOP SEAT</b>	<b>BOTTOM SEAT</b>	<b>Degree</b>
Outboard	3548297C3	3541721C4	2
Outboard	3548296C3	3541720C3	4
Outboard	3548295C2	3541719C3	6

<b>Seat Parts Information for 107.9mm (4.25IN) width Axle (CV Model)</b>				<b>Plate Parts Information</b>		
<b>Pinion Angle Loaded</b>	<b>Machined Part Number</b>	<b>Cast Part Number</b>	<b>Cast Pinion Angle (As listed in parts catalog)</b>	<b>4x2 HD Plate</b>	<b>4x2 MD Plate (with Shock Mount)</b>	
					<b>Left Side</b>	<b>Right Side</b>
0.60	3601567C2		2	3541719C3	3541725C3	3541726C3
2.50	3601568C2		4	3541720C3	3541727C3	3541728C3
4.45	3601569C2		6	3541721C3	3541729C3	3541730C3
7.50	4028015C1			3541721C3	3541729C3	3541730C3

( [Back to Top](#) )

## Other Air Suspension

- Check front axle suspension weight rating.
  - For any lean issues with a front suspension rating of 8,000 LBS or less please refer to [IK0300061 - 8,000 LBS Front Suspension Lean Correction](#).
- Check the unit for any offset loading.
  - Note any items that may cause offset loading.
- Inspect the suspension for any third party (bodybuilder) installed components such as stabilizer bars.
  - International does not install stabilizer bars on most suspensions.

- Exceptions: BE Buses, Front suspension on CityStars, and the Multi-Link front air suspension (These will have stabilizer bars).
4. Check the tire pressure for all tires.
    - Adjust pressures if needed.
    - Record current tire pressures.
  5. Verify the ride height is set properly.
    - Follow the manufacturer's recommended ride height setting for the suspension installed.
    - [Hendrickson](#) suspension website.
  6. Measure each corner of the vehicle as shown in Figures 4-7 and record measurements.
    - a. The front tires MUST be pointed straight forward to prevent any influence to the lean from King Pin Inclination.
    - b. Measure the front suspension at the spring shackle bolt as shown in Figures 4 and 5. Mark the bolt with a paint pen so you have a reference point for future measurements that may be required.
    - c. Measure the rear of the vehicle at the aft frame flange (bottom of the flange) as shown in Figures 6 and 7. Location may vary slightly by application.
  7. Dump the air from the suspension and verify the frame stop is touching the axle U-bolt on both sides of the truck. The frame stop may not touch the U-bolt on all vehicles. The space between the frame stop and U-bolt should be even from the right to left side for those applications.
    - Remeasure from the same locations used in Step 6 and record (Measurements are taken with suspension dumped).
  8. Take 4 photos of the unit. Please ensure the photos clearly show the lean. (Only perform this step if a case file is needed).
    - Front, Rear, Left Side, Right Side.

( [Back to Top](#) )

---

## Vari-Rate Spring Suspension

1. Check front axle suspension weight rating.
  - For any lean issues with a front suspension rating of 8,000 LBS or less please refer to [JK0300061 - 8,000 LBS Front Suspension Lean Correction](#).
2. Check the unit for any offset loading.
  - Note any items that may cause offset loading.
3. Inspect the suspension for any third party (bodybuilder) installed components such as stabilizer bars.
  - International does not install stabilizer bars on most suspensions.
  - Exceptions: BE Buses, Front suspension on CityStars, and the Multi-Link front air suspension (These will have stabilizer bars).
4. Check the tire pressure for all tires.
  - Adjust pressures if needed.
  - Record current tire pressures.
5. Measure each corner of the vehicle as shown in Figures 4-7 and record measurements.
  - a. The front tires MUST be pointed straight forward to prevent any influence to the lean from King Pin Inclination.
  - b. Measure the front suspension at the spring shackle bolt as shown in Figures 4 and 5. Mark the bolt with a paint pen so you have a reference point for future measurements that may be required.
  - c. Measure the rear of the vehicle at the aft frame flange (bottom of the flange) as shown in Figures 6 and 7. Location may vary slightly by application.

6. Take 4 photos of the unit. Please ensure the photos clearly show the lean. (Only perform this step if a case file is needed).

- o Front, Rear, Left Side, Right Side.

( [Back to Top](#) )

## Measuring Spring Height

Below is the procedure to measure the most commonly replaced leaf springs on International trucks. If a leaf spring is in question for sagging, a lean, or a collapsed condition, then before the spring is replaced it should be measured. If the measurements taken on the spring are within the specifications shown below, then the spring is not causing the lean complaint or is not defective.


### NOTE:

- It is common for springs to be flat or have a negative arch when loaded.
  - o The springs are designed this way, and it is all based on the spring rate.

### Measurement Technique

The measurements below are with the spring in a free, unloaded state. This is known as free camber. To make these measurements, the spring must be removed from the vehicle. Use a piece of straight metal or a line, and place it between the centers of the 2 eyelets. Use a square to measure 90 degrees of the center of the top of the spring to the center line.

### Dual Eye Leaf Spring Measurements



Part Number	Unloaded Height(Inches)	Tolerance Range(Inches)
3806666C91	4.04"	+/- 0.25"
6090598C93	3.14"	+/- 0.25"
6090598C92	3.14"	+/- 0.25"
3610111C3	5.29"	+/- 0.25"
3869789C92	2.72"	+/- 0.25"
3533197C91	3.89"	+/- 0.25"
6112882C91	2.8"	+/- 0.25"
2040041C92	3.55"	+/- 0.25"


3533196C91	3.55"	+/- 0.25"
3806667C91	3.49"	+/- 0.25"
3533198C91	3.97"	+/- 0.25"
3540221C91	3.08"	+/- 0.25"

4045769C93

2.69"

+/- 0.25"

**Spring End to Spring End Measurements**



Part Number	Unloaded Height(Inches)	Tolerance Range(Inches)
3534532C92	6.25"	+/- 0.25"
3534537C91	6.25"	+/- 0.25"

( [Back to Top](#) )

**Other Resources**

- [Master Service Information Page](#)

Hide Details

Feedback Information

Viewed: 31585  
 Helpful: 115  
 Not Helpful: 13

Staff ID	Client ID	Comments	Created Date
	U01G497	You received the following feedback From: U01G497 - Dustin Dustin Email Address: Dustin.Dustin@navistar.com Job Classification: Dealer: Perkins Engines Company Limited Feedback: Can the Medium duty IROS seats/plate list be in a format to match the other lists. The screen snip makes it so tech service cannot copy and paste part numbers. Also LT/HD seats for the newer IROS I believe to be different part numbers then MV.	10/22/2024 9:56:36 AM