



Service Bulletin

Bulletin No.: 24-NA-222

Date: October, 2024

INFORMATION

Subject: Information on Whoosh Noise from Engine Area While Driving

This Service Bulletin replaces PIP5914. Please discard PIP5914.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2020	2025	-	-	All	All

Involved Region or Country	North America, Europe, Middle East, Israel, Palestine, Japan, Thailand, Australia/New Zealand
Condition	Some customers may comment on a whoosh, gasp, or air rush noise from the engine area while driving. It may also be found that the noise is associated with active fuel management transition.
Cause	The cause of the condition may be a normal operating characteristic.

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Information

This condition can be attributed to the change in air flow through intake and exhaust due to active fuel management transition.

Commanding the cylinder deactivation exhaust valves may assist with duplicating the concern.

This condition may be more noticeable on convertibles.

Condition may be duplicated on a like vehicle.

If it has been confirmed the sound is related to active fuel management transition and is observed on a like vehicle, the condition can be considered characteristic and no repair attempts should be made.

Parts Information

No parts are required for this repair.

Version	1
Modified	Released October 07, 2024

