



SIB 16 02 24

2024-11-15

**DELIVERY STOP: REPLACE THE LOW AND HIGH PRESSURE FUEL PUMP**

This Service Information Bulletin (Revision 1) replaces SI B16 02 24 **dated July 2024**.

**What's New:**

- Part number Correction

<input type="checkbox"/>	THIS REPAIR IS MOBILE FRIENDLY
--------------------------	--------------------------------

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop if the campaigns have a status of remedy available. Otherwise, please release the vehicle.

**MODEL**

E-Series	Model Description	Production Date
G60	5 Series Sedan	June 12, 2024
G70	7 Series Sedan	June 12, 2024 – June 19, 2024

**AFFECTED VEHICLES**

Vehicles which require this campaign to be completed will show it as “Open” when checked either in AIR, AWP, Campaign Summary or Warranty Vehicle Inquiry.

Please make sure you check your dealer inventory as soon as possible. As of July 13, 2024, you can see a list of affected vehicles in Inventory Campaign Details (ICD) under ROSS.

**SITUATION**

There may be a restriction in the low-pressure fuel line at the tank flange for the in-tank delivery pump (low pressure pump). As a result, the required fuel flow volume is not available. If there is an insufficient supply of fuel (even if only for a very brief period), the high-pressure pump might suffer preliminary damage. In addition, in the event of a fault, there might be a power reduction or “jerking” motions while driving.

**CAUSE**

The flange lid on the supply unit might have a reduced cross-section for connecting the fuel feed line.

**PROCEDURE**

Replace the in-tank delivery unit and the high-pressure pump.

Follow Repair Instruction:

- **16 14 090 Removing and installing/replacing the supply unit**, and
- **13 51 017 Removing and installing the high-pressure pump**

**PARTS INFORMATION**

Use and invoice the applicable part numbers listed below.

**G60 (5 Series)**

Part Number	Description	Quantity
16 11 5 A2A C81	Supply unit	1
16 11 7 476 100	O-ring	1

13 51 7 934 496	High-pressure pump	1
13 53 8 489 570	High-pressure line	1
13 51 7 632 572	Torx socket with washer	2
11 12 9 847 198	Profile seal	1

Or:

### G70 (7 Series)

Part Number	Description	Quantity
16 11 5 A06 486	Supply unit	1
16 11 7 476 100	O-ring	1
13 51 7 934 496	High-pressure pump	1
51 71 1 696 566	Torx screw with washer	2
13 51 7 632 572	Torx socket with washer	2
11 12 9 847 198	Profile seal	1
07 11 9 907 857	Hexagon screw with washer	2
07 14 7 483 888	Hexagon bolt	6

### CLAIM INFORMATION

Reimbursement for this Action will be via normal claim entry utilizing the applicable work package information below and the part numbers listed above that apply.

<b>Repair Code:</b>	<b>0016870200</b>	---
---------------------	-------------------	-----

Below are the special flat rate labor operation code choices for this action.

**Completion before the first vehicle delivery to a customer or the vehicle is already in the workshop.**

Work Package	Labor Operation	Description (Plusposition work)	Labor Allowance
# 1	00 76 918	Replace supply unit and high-pressure pump (Includes draining enough fuel for access and reinserting it)	20 FRU (530i All); 22 FRU (540i All); 26 FRU (740i xDrive); 27 FRU (740i)
And			
When applicable:	00 76 919	Additional work electrical rear seat (G70)	16 FRU

Or:

**The vehicle arrives at your center and this Action shows open (No other Main work will be performed or claimed during this workshop visit).**

Work Package	Labor Operation	Description (Main work)	Labor Allowance
# 2	00 76 282	Replace supply unit and high-pressure pump (Includes draining enough fuel for access and reinserting it)	22 FRU (530i All); 24 FRU (540i All); 28 FRU (740i xDrive); 29 FRU (740i)
And			
When applicable:	00 76 919	Additional work electrical rear seat (G70)	16 FRU

Only one Main work flat rate labor operation code can be claimed per workshop visit.

### Claim Repair Comments

Only reference the SIB number and the work package (Pkg) number performed in the technician’s RO notes and in the claim comments (For example: B16 02 24 WP 1), unless otherwise required by State law.

**Alternative Mobility Solution (AMS) for Vehicle Owners (RO and Claim Comments Required)**

This Service Action repair qualifies for Alternative Mobility Solution (AMS) expense reimbursement, claim this item under the Defect Code noted above as follows:

- Sublet Code 2 - Itemize the AMS sublet amount on the repair order and in the claim comment section.

Please refer to SI B01 29 16 for additional information.

**FEEDBACK REGARDING THIS BULLETIN**

Technical Feedback	To submit feedback for the technical topic of this bulletin: Submit your feedback in the rating box at the top of this bulletin
Warranty Feedback	To submit feedback for the CLAIMS section of this bulletin: Submit an IDS ticket to the Warranty Department, or use the chat available in the Warranty Documentation Portal
Parts Feedback	To submit feedback for the PARTS section of this bulletin: Submit an IDS ticket to the Parts Department

