



Bulletin No.: PIT6257

Published date: 10/9/2024

Preliminary Information

PIT6257 P0534 Service High Voltage System Message

Models

Brand: Chevrolet **Model:** Blazer EV **Model Years:** 2024 - 2025 **VIN:** All **Engine:** All **Transmissions:** All

Involved Region or Country	North America
Condition	Service High voltage and possibly additional messages coming on. P0534
Cause	It is possible that the circuits are crossed in the harness for temperature sensors 5 and 6

Correction:

Inspect the wires at temperature sensors B222E sensor 5 and B222F sensor 6.

If they cannot be clearly seen it may be helpful to take a photo with a phone or use a borescope.

There should be a blue/black wire at B222E, temp sensor 5 and a gray/yellow wire at B222F temp sensor 6.

If this is found, due to the difficulty in accessing the sensors, swap the circuits at the K16 Battery Energy Control Module (BECM)

Swap X2 47 with X2 72 at the BECM and put labels on the circuits indicating the proper wire colors to avoid confusion in the future.

If it is found that the circuits are in the correct locations follow SI diagnostics for the code.

Version History

Version	1
Modified	10/09/2024 - Created on.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.