

JLRTB02130NAS2

TECHNICAL BULLETIN

01 JAN 2001



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

This bulletin supersedes TSB JLRTB02130NAS/2024 dated 04 NOV 2024, which should either be destroyed or clearly marked to show it is no longer valid (e.g. with a line across the page). Only refer to the electronic version of this Technical Bulletin in TOPIx.

Changes are highlighted in blue

SECTION:

501-05

SUBJECT /CONCERN:

LOADSPACE COVER HANDLE ASSEMBLY LOOSE

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	ASSEMBLY PLANT:
Range Rover (LK)	2022 Onwards	Solihull

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:

SITUATION:

The loadspace cover handle assembly becomes loose.

This condition relates to vehicles with **5 seats or executive second row seats** only.

CAUSE:

On some occasions during customer use, the rigid loadspace cover handle assembly becomes loose/adrift and the upper and lower sections detach.

ACTION:

Apply felt patches to the original loadspace cover handle upper.

PARTS:

NOTE:

*An allowance equivalent to £20 Sterling has been allocated for the amount of 1.6 mm felt tape required from the JLR Squeaks and Rattles Kit.

PART NUMBER	DESCRIPTION	QUANTITY
*ZZZ001	Felt tape - 1.6 mm thick	£20

WARRANTY:

NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Use TOPIx to obtain the latest repair time.
- The JLR claims submission system requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Loadspace Cover Handle Assembly Loose	99.01.01.09	0.1	N/A	526124119PVJ

NOTE:


Normal Warranty procedures apply.

SERVICE INSTRUCTION:

1. Open the tailgate.

2.  **NOTE:**

Care must be taken not to damage the components, a suitable plastic trim tool must be used to release the clips.



Carefully separate the upper and lower loadspace cover handle assembly.


3. Select the 1.6 mm thick felt from the JLR Squeaks and Rattles Kit.
4. Measure, mark and cut 1 section of felt to the following dimensions:
 - 190 mm x 15 mm (7.5 inch x 0.6 inch)
5. Measure, mark and cut 2 sections of felt to the following dimensions:
 - 6.5 mm x 5 mm (0.25 inch x 0.2 inch)

⚠ WARNINGS:

- The felt must not be allowed to overlap.
- The felt must not be placed too close or on top of the clips, the edges of the loadspace cover handle assembly upper, or the rib.

△ NOTE:

The 3 cut sections of felt are to be installed to the loadspace cover handle assembly upper.




Install the 3 cut sections of felt.

- Install the 190 mm x 15 mm (7.5 inch x 0.6 inch) cut section of felt **(A)** to the loadspace cover handle upper as shown in the illustration.
- Install the 2, 6.5 mm x 5 mm (0.25 inch x 0.2 inch) cut sections of felt **(B)** to either end of the loadspace cover handle upper, as shown in the illustration.

7.

⚠ CAUTION:

The loadspace cover handle assembly upper and lower sections must be correctly located during installation.



Correctly locate the loadspace cover handle assembly upper and lower onto the loadspace cover.

- Press the loadspace cover handle assembly upper and lower sections together until an audible click is heard.

8.

Close the tailgate.