



Bulletin No.: PIC6556G

Published date: 12/5/2024

Preliminary Information

PIC6556G Diagnostic Tip - One or More of the Following DTCs Setting in the Image Processing Module B1DD0 SYM57, B0126 SYM82, B1599 SYM13

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Buick	Enclave	2025	All	All All	All
Cadillac	CT5	2025	All	All All	All
Cadillac	Escalade Models	2025	All	All All	All
Cadillac	Escalade IQ	2025	All	All All	All
Cadillac	Lyriq	2023 - 2025	All	All All	All
Chevrolet	Equinox EV	2024	All	All All	All
Chevrolet	Silverado EV RST	2024	All	All All	All
Chevrolet	Suburban	2025	All	All All	All
Chevrolet	Tahoe	2025	All	All All	All
Chevrolet	Traverse (New Model)	2024 - 2025	All	All LK0	All
GMC	Acadia	2024 - 2025	All	All All	All
GMC	Sierra Denali EV	2024	All	All All	All
GMC	Yukon Models	2025	All	All All	All

Involved Region or Country	North America
Additional Options (RPO)	UKL - (LANE ACTIVE SAFETY-KEEP ASSIST, HANDS FREE LANE FOLLOWING)
Condition	It may be found that one or more of the following DTCs are set B1DD0 SYM57, B0126 SYM82, B1599 SYM13 is set in the Image Processing Control module current with no other camera or coax DTCs setting and the DTC will not clear.
Cause	Possible Drivers Monitoring Camera fault.

Correction:

1. **Disconnect the Image Processing Module for 30 minutes, reconnect and perform Serial Data Authentication (SDAC), clear DTCs with SPS2.**
2. **Perform 5 key cycles and recheck DTCs.**
3. **If B1DD0 SYM57 and B0126 SYM82 are no longer setting, check Super Cruise availability.**
 - a. **If Super Cruise is now functioning, return the vehicle to the customer.**
 - b. **If Super Cruise is not available, perform SI diagnostics for DTCs set.**

4. If B1DD0 SYM57 is setting current, check for B1599 SYM13 setting as current.
 - a. If B1599 SYM13 is not set current and only B1DD0 SYM57 is set current, proceed to step 5.
 - b. If both B1DD0 SYM57 and B1599 SYM13 are current, proceed to step 8.
5. If B1599 SYM13 is not set current and B1DD0 SYM57 or B0126 SYM82 is set Current or History, Check the LVDS cable for damage.
 - a. If damaged - replace the LVDS cable, clear DTCs perform a key cycle and check for DTCs.
 - b. If B1DD0 SYM57 is still setting, Replace the Drivers Monitoring Camera, clear DTCs and perform a key cycle.
6. If B1DD0 SYM57 is no longer setting Check Super Cruise availability.
 - a. If Super Cruise is functioning, return the vehicle to the customer.
7. If Super Cruise is still unavailable, Disconnect the 12-volt battery for 30 minutes, then reconnect.
 - a. If Super Cruise is available, return the vehicle to the customer.
 - b. If Super Cruise is Unavailable, perform SI diagnostics.
8. Check Drivers Monitoring Camera mounting and connections then disconnect the 12 Volt battery, reconnect, clear DTCs and then recheck DTCs.
9. If B1DD0 SYM57 and B1599 SYM13 are no longer setting Check for Super Cruise availability
 - a. If Super Cruise is available, return the vehicle to the customer.
10. If B1DD0 SYM57 is set current and B1599 SYM13 is no longer setting, Replace the Drivers Monitoring Camera, clear DTCs and check for Super Cruise operation.
11. If B1599 SYM13 is set current refer to SI Diagnostics for B1599 SYM13.

Additional SI Keywords

assist, cruise, driver, drivers, service, super, unavailable

Version History

Version8	8
Modified	<p>06/07/2024 - Created on.</p> <p>06/13/2024 - Updated Models.</p> <p>06/20/2024 - Removed reference to PIT6065 and edit correction.</p> <p>07/26/2024 - Updated Correction.</p> <p>09/09/2024 - Updated Correction.</p> <p>09/19/2024 - Added Sierra Denali EV.</p> <p>10/29/2024 - Updated Models.</p> <p>12/05/2024- Updated Traverse/Acadia to 2025, Added 2025 Enclave</p>