



**Bulletin No.:** PIT6308

**Published date:** 12/17/2024

## Preliminary Information

### PIT6308 Rear Tail Lamp or Lamps Inoperative

#### Models

**Brand:** Chevrolet **Model:** Traverse **Model Years:** 2024 - 2025 **VIN:** All **Engine:** All LKO **Transmissions:** All

<b>Involved Region or Country</b>	North America
<b>Condition</b>	The body mounted tail lamps (one or both) are completely inoperative.
<b>Cause</b>	Software Anomaly internal to the lamp

#### Correction:

If you get a Traverse where the rear lighting is inoperative, follow the procedure below:

If the left-hand tail lamp is inoperative, remove the F13RA in the X53A Body Wiring Harness Junction Block - Rear fuse to reset the lamp(s).

If the right-hand tail lamp is inoperative, remove the F9RA fuse in the X53A Body Wiring Harness Junction Block - Rear fuse to reset the lamp(s).

If the rear lighting is working after cycling the fuse(s), return the vehicle to the customer. If it does not work after cycling the fuse(s), the failure is not related to this software anomaly. Please follow service information to root cause the condition.


#### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
* 2086958	Cycle Fuses for Rear Lighting Inoperative	0.5 Hr.
*This is a unique Labor Operation for Bulletin use only.		

#### Version History

<b>Version</b>	<b>1</b>
<b>Modified</b>	<b>12/17/2024 - Created on.</b>

 GM Global Brands

© 2024 General Motors. All Rights Reserved.