



# Technical Service Bulletin

---

**93 Service info: Q8 e-tron - B200000 in 00C6**

93 24 43 2076352/1 December 13, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q8 e-tron, Q8 Sportback e-tron, SQ8 e-tron, and SQ8 Sportback e-tron	2024 – 2025	All	Not Applicable

## Condition

### Customer states:

No customer concerns, it is found during PDI or any other diagnostic work.

### Workshop findings:

During pre-delivery inspection/maintenance/repairs.

During a workshop visit due to a complaint about charging.

The following DTC and symptom code is/are logged in *the* charging unit for high-voltage battery (diagnostic address: 00C6):

- **B200000** Control module faulty – symptom: 1049088 - active/static

**IMPORTANT:** The log date for the DTC specified under “Standard ambient conditions” differs from the date of the workshop visit or the date when the complaint occurred:

**Example:** Issue where charging was not possible occurred at the charging station on 10/22/2024, workshop visit on 10/25/2024, log date for event memory entry is 04/14/2024.



# Technical Service Bulletin

**Address: 00C6 System Name: 00C6 - High-voltage battery charger Log Version: UDS/ISOTP (Results:**

## + Identification

### - DTC memory entries (Data source: Vehicle)

#### DTC memory entry

Number:	B200000: Faulty control module
Error type 2:	active/static
Symptom:	1049088
Status:	01101101

### - Standard ambient conditions

Date:	4/14/24
Time:	12:12:05 PM
Mileage (DTC):	320
Priority:	2
Frequency counter:	1
Elimination counter / driving cycle:	0

## Technical Background 1

The DTC entries logged in the control module can be ignored in this case:

1. The DTC has no effect on the vehicle's functions or electrical systems.
2. Although the customer has an issue with charging, the event memory entry is not the cause of the issue if the log date for the event memory entry does not match the time when the issue occurred. In this case, further investigation is required to determine the cause of the complaint.

## Production Solution

Not applicable

## Service

Parts replacement does not solve this issue. Claims for replaced parts will be subject to review.

## Warranty

This TSB is informational only and not applicable to any Audi Warranty



# Technical Service Bulletin

---

## Additional Information

All part and service references provided in this TSB (**2076352**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying,