

**26-19-01 - AdBlue® Warning and or MIL ON - Ad Blue® Leakage at Reductant Injector**

Release date: 01/30/2025

Condition

Applicable Vehicles						
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To	PR Code
Jetta	2015	2.0L TDI (CVCA)	All	AJ_FM200001	AJ_FM296633	-
Jetta	2015	2.0L TDI (CVCA)	All	AJ_FM350050	AJ_FM358215	-
Beetle	2015	2.0L TDI (CVCA)	All	AT_FM600001	AT_FM639473	-
Beetle Convertible	2015	2.0L TDI (CVCA)	All	AT_FM800001	AT_FM811301	-
Passat	2015	2.0L TDI (CVCA)	All	A3_FC000001	A3_FC064622	-
Golf	2015	2.0L TDI (CRUA)	All	AU_FM000001	AU_FM069384	-
Golf SportWagen	2015	2.0L TDI (CRUA)	All	AU_FM500001	AU_FM501189	-

Revision Table			
Instance Number	Published Date	Version Number	Reason For Update
2039436/14	1/30/25	26-19-01	Update to Labor Operation Numbers.
2039436/13	3/29/22	26-19-01	Update to AdBlue® part number.
2039436/12	3/18/21	26-19-01	Update warranty table due to SAGA updates.



26-19-01 - AdBlue® Warning and or MIL ON - Ad Blue® Leakage at Reductant Injector

Release date: 01/30/2025

2039436/11	1/11/21	26-19-01	Update part number suffix.
2039436/1	1/21/15	V261501	Original publication.

The following fault code may also be stored in the ECM Fault Memory:

DTC	Description
P20E8	Reductant Pressure Too Low

Technical Background

Welding process issues of the reductant line connector to the supply line may cause AdBlue® leakage at the reductant injector.

Production Solution

Improved parts implemented into production.

Service

Inspect the connection of the reductant supply line connector at the reductant injector in the engine compartment. If white crystalized (dried) AdBlue® is found at the reductant injector (see Figure 1 & 2), it will be necessary to replace the reductant supply line.



Figure 1



Figure 2



26-19-01 - AdBlue® Warning and or MIL ON - Ad Blue® Leakage at Reductant Injector

Release date: 01/30/2025

Thoroughly clean the area of the reductant supply line connection with water to remove the crystallized AdBlue®.

Replace the reductant supply line.

Refill reductant agent as required per part table quantity.

NOTICE

It is not necessary to replace the reductant injector.

Warranty

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual ¹⁾

Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
Jetta	2015	2.0L TDI (CVCA)	All	AJ_FM200001	AJ_FM296633
Jetta	2015	2.0L TDI (CVCA)	All	AJ_FM350050	AJ_FM358215
Beetle	2015	2.0L TDI (CVCA)	All	AT_FM600001	AT_FM639473
Beetle Convertible	2015	2.0L TDI (CVCA)	All	AT_FM800001	AT_FM811301
Passat	2015	2.0L TDI (CVCA)	All	A3_FC000001	A3_FC064622
Golf	2015	2.0L TDI (CRUA)	All	AU_FM000001	AU_FM069384
Golf SportWagen	2015	2.0L TDI (CRUA)	All	AU_FM500001	AU_FM501189

SAGA Coding

Claim Type: Use applicable Claim Type ¹⁾



26-19-01 - AdBlue® Warning and or MIL ON - Ad Blue® Leakage at Reductant Injector

Release date: 01/30/2025

Service Number:	Damage Code	HST	Damage Location (Depends on Service No.)
2684	0050	--	--
Parts Manufacturer		Passat	WVO ²⁾
		Golf, Golf SportWagon, Jetta, Beetle, Beetle Convertible	3ME ²⁾
Passat			
Labor Operation ³⁾ : Battery Prep & Charge		01500010 = see Elsa for latest time units.	
Labor Operation ³⁾ : Reductant Agent Supply Line Remove + Install		26841905 = see Elsa for latest time units.	
Labor Operation ³⁾ : Clean Up of crystallized Ad Blue		26842999 = 30 TU	
Labor Operation ³⁾ : Reductant Agent Inspect + Add		26883500 = see Elsa for latest time units.	
Jetta, Golf, Golf SportWagen, Beetle, Beetle Convertible			
Labor Operation ³⁾ : Battery Prep & Charge		01500010 = see Elsa for latest time units.	
Labor Operation ³⁾ : Reductant Agent Inspect + Add		26883500 = see Elsa for latest time units.	
Labor Operation ³⁾ : Clean Up of crystallized Ad Blue		26842999 = 30 TU	
Labor Operation ³⁾ : Upper Engine Cover		10831900 = see Elsa for latest time units.	
Labor Operation ³⁾ : Front Reductant Agent Supply Line Remove + Install		26841952 = see Elsa for latest time units.	
Causal Part : Supply Line for Reduction Agent		See Parts Table Below	
Diagnostic Time ⁴⁾			
GFF Time expenditure	01500060 = Actual GFF print out		YES



26-19-01 - AdBlue® Warning and or MIL ON - Ad Blue® Leakage at Reductant Injector

Release date: 01/30/2025

Road Test	01210002 = 00 TU 01210004 = 10 TU	YES
Technical Diagnosis:	01320000 = 00 TU max.	NO
Claim Comment: Input "As per Technical Bulletin 2039436" in comment section of Warranty Claim.		
<p>1) Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only</p> <p>2) Code per warranty vendor code policy.</p> <p>3) Labor Time Units (TUs) are subject to change with ELSA updates.</p> <p>4) Documentation required per Warranty Policies and Procedures Manual.</p>		

Required Parts and Tools

Model	Part Number	Description
Passat	561 131 984 *	Supply Line for Reduction Agent
Golf, Golf SportWagen	5Q0 131 984 *	Supply Line for Reduction Agent
Jetta, Beetle, Beetle Convertible	5C0 131 984 E	Supply Line for Reduction Agent
ALL	G 052 910 S0	AdBlue® Max. Qty. = 2.00

Part numbers are accurate at time of publication. Always refer to ETKA for the latest part information.

Tool Description	Tool No:
Midtronics Battery Tester/Charger	InCharge 940 (INC-940) or GRX3000VAS
VAS Diagnostic Tool	VAS 6150/X & VAS 6160/X with ODIS Service with: current online updates

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.