| Technical Service Bulletin (TSB)  PARTS & SERVICES  Technical Service Bulletin (TSB)  Extended Crank Condition Due To Loss of Fuel Pressure |   |       |                   |              |                           |  |
|---|---|-------|-------------------|--------------|---------------------------|--|
| REFERENCE:  | <b>TSB</b> : 14-004-25 <b>GROUP</b> : 14 - Fuel System  | Date: | February 12, 2025 | REVISION:    | _                         |  |
| VEHICLES<br>AFFECTED:   | 2021 - 2024 (WD) Dodge Durango This bulletin applies to vehicles built on or after February 01, 2021 (MDH 0201XX) and on or before November 24, 2024 (MDH 1124XX) equipped with a 3.6L V6 VVT Engine Upgrade 1 (Sales Code ERC) or a 5.7L V8 Hemi MDS VVT Engine (Sales Code EZH) and Durango Pursuit Vehicle (Sales Code AZ1). |       |                   | ⊠ NA<br>□ SA | PPLICABILITY:  MEA IAP CH |  |
| CUSTOMER<br>SYMPTOM:  | Customers may experience the following:  • Extended engine crank condition.   |       |                   |              |                           |  |
| CAUSE:  | Fuel pressure regulator   |       |                   |              |                           |  |

# **REPAIR SUMMARY:**

This bulletin involves performing a fuel pressure test and possibly replacing the fuel pump module.

# **CLAIMS DATA:**

| Labor Operation No: | Labor Description  | Skill Category   | Labor Time |
|---------------------|--|------------------|------------|
| 14-50-01-90         | Fuel Pump Module Test and<br>Replace (Left Side)<br>(0 - Introduction) | 14 - Fuel System | 2.0 Hrs.   |
| Failure Code        | ZZ   | Service Action   |            |

# **RELATED LOP:**

| Labor Operation No: | Labor Description                      | Skill Category   | Labor Time |
|---------------------|--|------------------|------------|
| 14-50-01-60         | Skid Plate Equipped (0 - Introduction) | 14 - Fuel System | 0.1 Hrs.   |

#### **SPARE PARTS:**

| Qty    | Part No.   | Description             | Notes |
|--------|------------|-------------------------|-------|
| 1 (AR) | 68535771AB | Module, Fuel Pump/Level |       |
|        |            | Unit                    |       |

### **DIAGNOSIS:**

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

### **REPAIR PROCEDURE:**

- Perform a fuel pressure and Fuel system leak down test. Refer to the detailed service procedures available in DealerCONNECT/ Service Library under: Service Info>29 - Non-DTC Diagnostics / Drivability - Gas / Diagnosis and Testing.
- 2. Is the fuel pressure and system leak down within specification?
  - YES >>> This bulletin has been completed. Perform further diagnostics.
  - NO >>> Proceed to Step 3.
- 3. Replace fuel pump module. Refer to the detailed service procedures available in DealerCONNECT/ Service Library under: Service Info>14 - Fuel System / Fuel Delivery, Gas / Module, Fuel Pump / Removal/ Installation.

### **POLICY:**

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.