

SIB 51 08 24

2025-02-14

FOGGING IN THE INSIDE OF THE WINDSHIELD IN THE AREA OF THE ADCAM

This Service Information Bulletin (Revision 1) replaces SI B51 08 24 dated April 2024.

What's New:

- Models added
- Claim Information section updated

☐ THIS REPAIR IS MOBILE FRIENDLY

MODEL


G05 (X5 Sports	G06 (X6 Sports	G07 (X7 Sports	G09 (BMW XM Sports
Activity Vehicle)	Activity Coupe)	Activity Vehicle)	Activity Coupe)
G45 (X3 Sports	G60 (5 Series Sedan)	G70 (7 Series Sedan)	i20 (iX Sport Activity
Activity Vehicle)	,	,	Vehicle)
U10 (X2 Sports	U11 (X1 Sports Activity		
Activity Coupe)	Vehicle)		

SITUATION



The Augmented Reality Camera (ARCAM) shows up blurry when activated.

CAUSE



Contamination on the inside of the windshield in front of the Autonomous Driving Camera (ADCAM; arrow).

CORRECTION

Using a clean and dry microfiber cloth, clean the affected area of the inner windshield and ADCAM lenses using BMW glass cleaner.

PROCEDURE

1. Remove the ADCAM camera per the repair instructions listed in ISTA/AIR 66 51 541 or 66 51 590.

Copyright ©2025 BMW of North America, Inc.

about:blank 1/4

2. Spray the glass cleaner onto a clean/dry microfiber cloth.

Note: DO NOT spray the windshield.

- 3. Clean the inner section of windshield where the ADCAM sits and clean the ADCAM lenses.
- 4. Reinstalled the ADCAM and reassess the vehicle.

PARTS INFORMATION

Obtain and confirm the part numbers for your specific vehicle by entering the chassis number in either ETK or AIR which considers specific equipment and/or options.

Part Number	Description	Quantity
83 19 2 455 137	BMW Glass Cleaner w/ anti-fog - (16 oz)	Shop supply

CLAIM INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Repair	5131900300	Ux Gx Fx I20	Fitting in field of view of ADCAM camera
Code:	5131900300	on inside of w	indscreen

Below are the special flat rate labor operation code choices for this action.

Completion before the first vehicle delivery to a customer or the vehicle is already in the workshop.

Work Pkg	Labor Operation	Description (Plusposition work)	Labor Allowance
# 1	00 74 708	Removing and installing ADCAM camera and cleaning relevant area of windshield	3 FRU*

Or:

The vehicle arrives at your center for this repair procedure (No other Main work will be performed or claimed during this workshop visit).

Work Pkg	Labor Operation	Description (Main work)	Labor Allowance
# 2	00 74 097	Removing and installing ADCAM camera and cleaning relevant area of windshield	4 FRU*

Only one of the flat rate labor operation codes listed above can be used for claim submission and reimbursement. Also, only one Main work flat rate labor operation code can be claimed per workshop visit.

Claim Repair Comments

Only reference the SIB number and the work package (Pkg) number performed in the RO technician notes and the claim comments (For example: B51 08 24 WP 1), unless otherwise required by State law.

BMW Group's AIR Application Resource for Flat Rate Labor Operation Codes

(*) Only if the FRU allowance is not listed in AIR.

To obtain the corresponding flat rate unit (FRU) allowance information from the BMW Group AIR application resource, start by entering the the Chassis Number (last seven (7) characters of the VIN), and click on the "Search" icon. If two or more model vehicle choices show, select the applicable Model, or enter the full VIN (17 characters) instead. Click on the "Flat Rate Units" button and enter a flat rate labor operation code number in the field to the right, click on the "Search" icon to display the corresponding listing of "Flat rate unit

Copyright ©2025 BMW of North America, Inc.

about:blank 2/4

FEEDBACK REGARDING THIS BULLETIN

Technical Feedback	To submit feedback for the technical topic of this bulletin: Submit your	
	feedback in the rating box at the top of this bulletin	
Warranty Feedback	To submit feedback for the CLAIMS section of this bulletin: Submit an IDS	
	ticket to the Warranty Department, or use the chat available in the	
	Warranty Documentation Portal	
Parts Feedback	To submit feedback for the PARTS section of this bulletin: Submit an IDS	
	ticket to the Parts Department	

about:blank 3/4