

Replacement of Cap for Coolant System (98/13)



Information

- Document with limited validity.

This Quick Information will remain valid until further notice.

Change Overview:

Release	Date	Change
0	01/23/2014	▪ First publication
1	01/23/2025	▪ Model line 718 Boxster / 718 Cayman (982) added

Model Year: **As of 2012**

Vehicle Type: **Boxster (981)/ Boxster (982)
Cayman (981)/ Cayman (982)
911 (991)**

Concerns: **Cap for coolant system.**

Information: **Caps that are perfectly OK are being unnecessarily replaced.**

Action Required: If traces of coolant residue can be seen around the cap, a leak test must be carried out on the coolant system before replacing the cap or any other components.

The procedure for leak-testing the coolant system cap is described in the Workshop Manual "190101 Checking the cooling system" in the PIWIS information system.

Slight coolant residues on the cap for the cooling system are not a defect and are not sufficient grounds for replacing the cap.

References: ⇒ *Workshop Manual '190101 Checking the cooling system'*

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2025 Porsche Cars North America, Inc.