

WRK2 – Replacing Coolant Regulator (Workshop Campaign)

Change
Overview:

Release	Date	Change
0	12/13/2024	▪ First publication
1	02/03/2025	▪ Addition of part number 95813307300

Model Year: **2023**

Vehicle Type: **Macan (95B)**
Macan T (95B)

Concerns: **Coolant regulator**

Cause: **It is possible that coolant regulators in which the radial shaft sealing ring does not meet the required specifications have been installed in the affected vehicles.**
If this is the case, a gradual loss of coolant over a prolonged vehicle run time can lead to a drop in the coolant level in the coolant expansion tank and eventually result in a yellow warning message on the instrument cluster.

Action: Replace the coolant regulator.




Information

The coolant regulator is integrated in the coolant regulator housing and cannot be replaced separately. In order to replace the coolant regulator, the coolant regulator housing must be replaced.

Affected Vehicles: Only vehicles assigned to the campaign (see also PCSS Vehicle Information).

Installation
Position:



Installation position of coolant regulator housing

Required parts and materials

The **part numbers** of the **required parts and materials** for the respective vehicle can be seen in the **assigned scope**. For an overview of the campaign scopes, see: ⇒ *Technical Information 'Warranty processing'*.

Required Tools

- Tools:
- Battery charger with a current rating of **at least 90 A**, e.g., **VAS 5908 - battery charger 90 A**
 - **P90999 - PIWIS Tester 4**
 - Torque wrench, 2-10 Nm (1.5-7.5 ftlb.), e.g. **V.A.G 1783 - torque wrench, 2-10 Nm (1.5-7.5 ftlb.)**
 - Torque wrench, 6-50 Nm (4.5-37 ftlb.), e.g., **V.A.G 1331A - torque wrench, 6-50 Nm (4.5-37 ftlb.)**
 - **VAS 6935 - Pole terminal puller**
 - **VAS 6199A - Clamping pliers**
 - **9696 - Filling device**
 - **V.A.G 1274/10 - Pipe for coolant tester**
 - **V.A.G 1274/8 - Adapter for cooling system tester**

Replacing coolant regulator

- Work Procedure:
- 1 Remove **previous** coolant regulator housing. ⇒ *Workshop Manual '195519 Removing and installing coolant regulator housing'*
 - 2 Transfer the coolant pump with a **new** seal to a **new** coolant regulator housing.
For procedure, see:
⇒ *Workshop Manual '195019 Removing and installing coolant pump'*
 - 3 Install a **new** coolant regulator housing. ⇒ *Workshop Manual '195519 Removing and installing coolant regulator housing'*
 - 4 Enter the campaign into the Warranty and Maintenance logbook.

Warranty processing



Information

The specified labor time was determined specifically for carrying out this campaign and includes all necessary preliminary and subsequent rework. The labor time may differ from the labor time published in the Labor Operation List in the PCSS.

Scope 1: Replacing coolant regulator

Labor time:		
Replacing coolant regulator		Labor time: 334 TU
Includes:	Removing and installing coolant pump drive belt Removing and installing throttle body Draining and filling coolant	
Required parts:		
Part No.	Designation – Location	Quantity
V04015005P	Coolant regulator	1 piece
PAC121043A	Moulded seal – Coolant pump	1 piece
95813307300	Seal – Throttle body part	1 piece
95812113100	Connection socket with sealing ring – Coolant regulator housing	1 piece
WHT001163B	Hexagon-head bolt with inner multiple-tooth head (Duo) M16 x 16.5 – Coolant pump drive wheel	1 piece

PAF911296	M12 x 100 x 90 12-point screw – Coolant pump holder	1 piece
Required materials (usually already available in the Porsche Center):		
V04015003P	Coolant additive, 20-liter/ 5.28 gal container	0.03 pieces
⇒ Damage number WRK2 066 000 2		

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2025 Porsche Cars North America, Inc.