

**Surround View Camera Intermittent Operation**

**Vehicles Affected**

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
911	As of 2020 up to 2024	992	N/A	KA6

**Revision History**

Revision	Release Date	Changes
0	March 4, 2024	Original document
1	April 1, 2024	Update of Service Information & Warranty
2	August 28, 2024	Update of PartID
3	February 26, 2025	Update of MY

**Condition**

Customer complains of intermittent operation for one or multiple surround view cameras. Failed surround camera(s) appear blank with a crossed-out camera icon.




Figure 1

Advanced Technical Information

**Technical Background**

Any component failure of the surround view system can lead to a single or a combination of surround camera images being blank within the PCM display.

Fault codes that may be present include:

- C12\*\*02 - X peripheral camera, video wiring, Signal error
- B127\*04 - X camera faulty
- B127\*54 - X camera, calibration
- B200FFA - Surround View camera - internal fault

**Service Information**

The countermeasure currently consists of a two-part repair that should be performed to the vehicle during separate visits to the workshop. Repairs made must be accompanied by supporting diagnostic work with objective evidence of the issue, e.g., pictures or videos. Refer to the steps below for instructions.

Vehicle's first visit for this concern:

1. Create a Pre-VAL.
2. Verify the concern is isolated to the surround view system.
3. Replace the components listed:
  - a. All four surround view cameras
  - b. Both side view mirror wiring harnesses
  - c. Both door wiring harnesses (containing coax cables)
  - d. Front bumper wiring harness
  - e. Rear bumper camera cable (image below for reference)
4. Verify operation of the surround view system after the repair has been completed.
5. Create a Post-VAL.




Figure 2

Advanced Technical Information

Vehicle's second visit for this concern:

1. Create a Pre-VAL.
2. Verify the concern is isolated to the surround view system & ensure the previous repair has been performed correctly and completely.
3. Perform the next repair:
  - a. Replace zFAS control unit.
  - b. Overlay new coax cables from ZFAS control unit to: (Part Numbers are from VW/Audi)
    - i. Front bumper wiring harness
      - zFAS connector housing: **6Q0\_035\_576**
      - Bumper connector housing: **WNK70000004** (Porsche Part Number from Campaign WNK7)
    - ii. Rear bumper cable connection
      - zFAS connector housing: **6Q0\_035\_576\_B**
      - Bumper connector housing: **4L0\_035\_576\_A**
    - iii. Both door wiring harnesses
      - zFAS connector housing (driver side): **6Q0\_035\_576\_D**
      - zFAS connector housing (passenger side): **4L0\_035\_576\_C**
      - A-pillar connector housing: **6Q0\_035\_575\_A**

Recommended using **VAS 6720 & Wire Insertion Tool Set** (e.g. Snap-On - WINS1000R).



**Figure 3**  
**Snap-On - WINS1000R**

**IMPORTANT:** Ensure no material is removed from any grommet when piercing and do **NOT** drill any holes. Avoid damaging wires by pointing insertion tool **AWAY** from wires while penetrating.

4. Verify operation of the surround view system after the repair has been completed.
5. Create a Post-VAL.



**Figure 4**  
**Cabin Side - Clutch Master Cylinder Grommet**



**Figure 5**  
**Exterior Side - Clutch Master Cylinder Grommet**

Additional Service Information:


- Pictures above are of driver side camera overlay to zFAS control unit from A-pillar connector. Grommet of use is for the missing clutch master cylinder.
- If the vehicle is a manual, refer to the pictures below to be used for driver side camera overlay. Passenger footwell grommet is to also be used for rear and passenger camera overlays. When overlaying wires, ensure wires are secured to existing harnesses and area of piercing is properly sealed.
- Recommended points of piercing are designated by green X's.



**Figure 6**  
**Cabin Side - Passenger Footwell Grommet**



**Figure 7**  
**Tub Side - Passenger Side Grommet**




**Figure 8**  
Rear Camera Connection Point (Right Rear Taillight)



**Figure 9**  
Front Camera Connection Point  
(Front Right Wheel Well)



**Figure 10**  
Door Harness Connection Point (1)



**Figure 11**  
Door Harness Connection Point (2)

**Warranty**

For documentation and warranty invoicing, enter the working position and PCSS encryption specified below in the warranty claim:

1st Workshop Visit:

APOS	Labor operation	Option Specific
03350050	On board diagnostics	
03350053	On board diagnostics (Pre-VAL)	
91691900	Front camera remove and reinstall	
91671901	Side camera remove and reinstall (left)	
91671902	Side camera remove and reinstall (right)	
91435500	Reversing camera control unit replace	
97151952	Wire harness front remove and reinstall	
66791905	Rear-view mirror housing remove and reinstall (left)	
66791906	Rear-view mirror housing remove and reinstall (right)	
97321903	Door wire harness remove and reinstall (left)	
97321904	Door wire harness remove and reinstall (right)	
97591999*	Rear camera coaxial cable replacement	
03350063	On board diagnostics (Post-VAL)	

**\* 50 TU may be claimed for 97591999.**

2nd Workshop Visit:

APOS	Labor operation	Option Specific
03350050	On board diagnostics	
03350053	On board diagnostics (Pre-VAL)	
85141900	Air inlet housing remove and reinstall	
97090912	Main wire harness loosen and fasten (engine compartment – right)	

## Advanced Technical Information

APOS	Labor operation	Option Specific
97090901	Main wire harness loosen and fasten (luggage compartment – left)	
97090902	Main wire harness loosen and fasten (luggage compartment – right)	
92191900***	Wiper link remove and reinstall	
68171900***	Console remove and reinstall (PDK)	PDK
68171905***	Console remove and reinstall (Manual)	Manual
70411952	Front floor covering remove and reinstall (right)	
70291900	Trim panel for seat well remove and reinstall	
70851900	Roof trim panel rear remove and reinstall	
97091999**	Create and overlay new coaxial cables from zFAS control unit to surround cameras	
97090910***	Main harness loosen and fasten (convertible top – right)	Cabriolet
03350063	On board diagnostics (Post-VAL)	

**\*\* Only actual time elapsed up to a maximum of 600 TU, verified by a separate identifiable time punch, may be claimed for 97091999.**

**\*\*\* Option specific to be claimable.**

PCSS encryption:

Location (FES5)	91720	Surround view camera control unit
Damage type (SA4)	1613	No function occasionally

### Search Items

992, 911, RTV, surround, camera, reverse

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.