GENERAL MOTORS DCS7158 URGENT - DISTRIBUTE IMMEDIATELY

Date: March 6, 2025

Subject: A252495390 - Service Update

Oil Plug Seated Improperly

Models: 2025 Cadillac CT5-V Blackwing

General Motors is releasing Service Update A252495390 today.

What Should Dealers Do: Dealers should review IVH or the Dealer Maxis reports for open VINs in their inventory. Dealers can view the attached bulletin and it will also be displayed in Service Information tomorrow.

The Stock VIN list of vehicles in dealer inventory is attached to this message. Note: this list is only accurate at the time of report creation and all VINs should be validated in IVH prior to repair.

END OF MESSAGE

Service Update

A252495390 Oil Plug Seated Improperly



Release Date: March 2025 Revision: 00

Attention: This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

		Model Year		
Make	Model	From	То	
Cadillac	CT5-V Blackwing	2025	2025	

Investigate Vehicle History (IVH) in the GM Global Warranty Management system should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	Certain vehicles listed above may have a condition in which the oil plug in the oil pan may not be seated properly.
Correction	Dealers will inspect, and if necessary, press in the oil plug.

Parts

No parts are required for this repair.

Warranty Information

Labor		Labor	Trans.	Net
Operation	Description	Time	Type	Item
9107866	Inspect Only – No Further Action Required	1.0	ZFAT	N/A
9107867	Inspect and Press Oil Plug	1.1	ZFAT	N/A

Service Procedure

1. Remove the Front Cradle Shear Plate. Refer to Front Cradle Shear Plate Replacement (1SV) in SI.



6860566

2. Locate the oil pan pickup tube plug on the front of the oil pan (driver's side) as shown.

Service Update

A252495390 Oil Plug Seated Improperly





6860567

IMPORTANT: The depth to which the plug is pressed beyond the counterbore may vary. As long as the counterbore line is visible as indicated above, no further action is required.

- 3. Inspect the oil pan pickup tube plug.
 - If the plug is pressed to a point where the counterbore line is visible (indicated by white arrow above) no further action is required. Proceed to step 6.
 - If the plug is NOT pressed deep enough to expose the counterbore line, proceed to the next step.



6860568

Important: Do NOT press the plug in too far. You want to put some pressure on it, stop and check the depth, and then repeat, doing this as many times as necessary until you have achieved the appropriate depth. It may not feel like the plug is moving at all, but it will be.

- 4. Using a ½ to 3/8 adapter, an appropriate length extension, and a socket on the other end of the extension as shown, use a prybar to *carefully* press the plug further into the oil pan, frequently checking the depth to ensure you are not pressing it in too far.
 - Use a sharpie or some painters tape to make a mark 12mm (1/2 inch) from the end of the ½ to 3/8 adapter. This will alert you to when the plug is pressed in about to the depth of the counterbore line.

Service Update

A252495390 Oil Plug Seated Improperly



- Wedging a block of wood or body wedge between the sway bar and the core support will be helpful to prevent flex.
- Wrapping a piece of rubber hose around the pry bar will be helpful to stop it from slipping.
- Once you have achieved the desired depth by pressing the plug past the counterbore line (as shown in step 3), no further action is required.
- Reinstall the Front Cradle Shear Plate. Refer to Front Cradle Shear Plate Replacement (1SV) in SI.

Dealer Responsibility

Whenever a vehicle subject to this service update enters your vehicle inventory or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Pre-Owned (CPO), courtesy transportation vehicles, dealer shuttle vehicles, CarBravo, etc. in dealers' possession and subject to this field action must be held and inspected/repaired per the service procedure of this bulletin before customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Pre-Owned (CPO) vehicles currently in the dealers' inventory within the SHIFT Digital system will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the SHIFT Digital system, or once again be used in the Courtesy Transportation Program.

Dealer Reports - For USA & Export

The Inventory tab of the Open Vehicle Report will contain Service Update Bulletin VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will not contain Service Update Bulletin VIN data because the intent of a Service Update Bulletin is to not inconvenience a customer with a special trip for service. Service Update Bulletins are to be completed when the customer is in for a regularly scheduled visit.