

REFERENCE:	TSB: 08-063-25 GROUP: 08 - Electrical	Date:	March 11, 2025	REVISION:	-						
VEHICLES AFFECTED:	<p>2021 - 2023 (WL) Grand Cherokee / Grand Cherokee L 2022 - 2023 (WS) Wagoneer / Grand Wagoneer</p> <p>This bulletin applies to vehicles built equipped with one of the following radios:</p> <ul style="list-style-type: none"> ● Uconnect 5 W 8.4" Display (ROW+DAB) (Sales Code UUF). ● Uconnect 5 Nav W 8.4" Disp (ROW+DAB) (Sales Code UUL). ● Uconnect 5 Nav w 10.1" Disp (ROW+DAB) (Sales Code UUN). ● Uconnect 5 Nav w 12.0" Disp (ROW+DAB) (Sales Code UUQ). 			<p>MARKET APPLICABILITY:</p> <table style="width: 100%; border: none;"> <tr> <td><input type="checkbox"/> NA</td> <td><input checked="" type="checkbox"/> MEA</td> </tr> <tr> <td><input type="checkbox"/> SA</td> <td><input checked="" type="checkbox"/> IAP</td> </tr> <tr> <td><input type="checkbox"/> EE</td> <td><input type="checkbox"/> CH</td> </tr> </table>		<input type="checkbox"/> NA	<input checked="" type="checkbox"/> MEA	<input type="checkbox"/> SA	<input checked="" type="checkbox"/> IAP	<input type="checkbox"/> EE	<input type="checkbox"/> CH
<input type="checkbox"/> NA	<input checked="" type="checkbox"/> MEA										
<input type="checkbox"/> SA	<input checked="" type="checkbox"/> IAP										
<input type="checkbox"/> EE	<input type="checkbox"/> CH										
CUSTOMER SYMPTOM:	<p>Customers may experience one or more of the following:</p> <ul style="list-style-type: none"> ● Unable to select the Turn by Turn Navigation. ● Blank Performance Pages (Rearview Camera (RVC) Functions Normally). ● Android Auto® Voice Recognition (VR) inoperative. ● Media tuner delayed. ● Charge Schedule not accepting updates via phone (RVC Functions Normally). ● Ambient light inoperative. ● Map in Instrument Panel Cluster (IPC) inoperative. ● Media Widget blank. ● Navigation map black. ● Off-Road Pages inoperative (RVC Functions Normally). ● VR inoperative. ● Incorrect song title displayed (Carplay® only). ● Radio display switches from Media Page to Home Page (RVC Functions Normally). ● Ghost touch on Navigation screen (RVC Functions Normally). ● Widgets missing. ● New User Profile does not load. ● Returns to wrong page after View Camera Event selected by customer in the Camera View Pages (RVC Functions Normally). 										
CAUSE:	Software improvements										

REPAIR SUMMARY:

This bulletin involves inspecting and if required, updating the radio software level to U33.43. Depending on the radio's current software level the radio may need a one or two USB update.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-60-F2-94	Radio, Software - Create USB Jump Drive from Uconnect Website UUF Radio w/ U33.43 (One Time Only) (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.
18-60-F2-9H	Radio, Software - Create USB Jump Drive from Uconnect Website UUF Radio w/ U29.42 (One Time Only) (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.
18-60-F2-9J	Radio, Software - Create USB Jump Drive from Uconnect Website UUL Radio w/ U33.43 (One Time Only) (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.
18-60-F2-9K	Radio, Software - Create USB Jump Drive from Uconnect Website UUL Radio w/ U29.42 (One Time Only) (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.
18-60-F2-9L	Radio, Software - Create USB Jump Drive from Uconnect Website UUN Radio w/ U33.43 (One Time Only) (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.
18-60-F2-9M	Radio, Software - Create USB Jump Drive from Uconnect Website UUN Radio w/ U29.42 (One Time Only) (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.
18-60-F2-9N	Radio, Software - Create USB Jump Drive from Uconnect Website UUQ Radio w/ U33.43 (One Time Only) (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-60-F2-9V	Radio, Software - Create USB Jump Drive from Uconnect Website UUQ Radio w/ U29.42 (One Time Only) (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.
18-60-F2-90	Radio, Check Software Level and Perform Software Update UUF or UUL radio w/ U33.43 (ONE Update) (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.
18-60-F2-91	Radio, Check Software Level and Perform Software Update UUN or UUQ radio w/ U33.43 (ONE Update) (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.
18-60-F2-92	Radio, Check Software Level and Perform Software Update UUF or UUL radio w/ U29.42 and U33.43 (TWO Updates) (0 - Introduction)	6 - Electrical and Body Systems	0.4 Hrs.
18-60-F2-93	Radio, Check Software Level and Perform Software Update UUN or UUQ radio w/ U29.42 and U33.43 (TWO Updates) (0 - Introduction)	6 - Electrical and Body Systems	0.4 Hrs.
Failure Code	CC	Customer Concern	

The dealer must use failure code CC with this Technical Service Bulletin.

- If the customer's concern matches the SYMPTOM identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If Diagnostic Trouble Codes (DTCs) or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	–	–

REPAIR PROCEDURE:

- NOTE:**
- A 20GB USB flash drive formatted as NTFS is required for U29.42.
 - A 4GB USB flash drive formatted as FAT32 is required for U33.43.

It is also recommended to use a quality, name brand (Kingston®) flash drive over a generic USB flash drive.

1. Check radio software version. Go to “Vehicle Settings” then select “System Information” and look for “Radio Version”.
2. What is the radio software level (Application Version) at?
 - U33.43 or higher >>> The radio software is already up to date. Normal diagnostics should be performed.
 - At or above **U29.42** and under **U33.43** >>> The radio will only need one USB flash drive to update the radio. Create a USB flash drive with U33.43 software. Proceed to [Step 3](#).
 - At or Below **29.42** >>> The radio will need two USB flash drives to update the radio. Create two USB flash drives with U29.42 and U33.43 software. Proceed to [Step 3](#).
3. Have one or two USB flash drives been created?
 - YES>>> Proceed to [Step 12](#).
 - NO>>> Proceed to [Step 4](#).

NOTE: If the software cannot be downloaded, make sure you have proper security access. If not, have the Service Manager or Shop Foreman download the software update.

4. Go to DealerCONNECT>Service>Uconnect Command Center>Uconnect>More Information >Dealer software downloads to download the files.

NOTE: If a 2-step update is required, please always download and flash the U29.42 software first. After U29.42 is installed successfully, flash U33.43 software

5. Use a blank USB flash drive with at least **4GB** of space and formatted to **FAT32** for the **U33.43** update. Use a blank USB flash drive with at least **20GB** of space and formatted to **NTFS** for the **U29.42** update. Follow the on-screen instructions to download the software files.

NOTE: When downloading the software file from the Uconnect site, always select the MAC version, regardless of the computer being used.

6. Download the software update file to your local PC's desktop. Make sure to select the "MAC" radial button for all downloads Fig. 1.




Fig. 1

MAC Download Steps

7. Perform the following steps to format the USB flash drive.
- a. Select "FAT32 or "NTFS"" format.
 - b. Select "Default allocation size" under Allocation Unit Size.
 - c. Select "Quick Format" under Format Options.
 - d. Click "Start".
8. Be sure to download the file to your designated folder before transferring the zip file to the blank USB flash drive.

NOTE: A blank USB flash drive will be needed for each radio update, additional updates cannot be on the same USB flash drive.

9. Download the radio SW from the desktop to a blank USB flash drive. Use a blank USB flash drive with at least **4GB** or **20GB** of space and formatted to **FAT32** or **NTFS**. Follow the on-screen instructions to download the software files.
10. Do not unzip the folder/file and move all contents to the root directory of the USB.
11. There should only be one file on the USB root directory labeled as a zip folder.

NOTE: Once the USB flash drive have been created, it is recommended to label the USB flash drive with the bulletin number and proper radio Sales Codes.

12. Start the vehicle and insert the correct USB flash drive with new software into the USB port.

NOTE: Engine should be running the entire time the radio is flashed.

NOTE: The software update screen may take up to a minute before it is displayed. If the update screen isn't displayed, cycle the ignition to "Off" then "Run" .

13. Press Update Now [Fig. 2](#).




Fig. 2
Software Update Screen

14. Press Continue [Fig. 3](#).




Fig. 3
Timer Screen

15. Wait for software update to complete 100% [Fig. 4](#).




Fig. 4
Progress Screen

Installing System Update

NOTE: System update process takes approximately five minutes. Wait until radio restarts and Home screen is displayed [Fig. 5](#), [Fig. 6](#).




Fig. 5
Software Update Installing




Fig. 6
Software Update Complete

NOTE: Flash time will take ~30 minutes to one hour.

NOTE: Vehicle should be running the entire time.

NOTE: Sometimes the radio throws an error pop up "Switch-Invalid_Binary" after successful radio update. Please ignore this error and click ok [Fig. 7](#).




Fig. 7
Switch-Invalid_Binary Error

1. What was the radio software level after this update?

- **U33.43**>>> The radio download has been completed. Proceed to [Step 2](#) of the Installing System Update section.
- **U29.42**>>> The next phase of the radio update needs to be performed. Proceed to [Step 12](#) of the Repair Procedure.

2. Go to Vehicle Setting -> Reset -> Perform Factory Reset. Once Factory Reset is completed, allow sleep cycle for approximately five minutes.
3. Using wiTECH, clear all DTCs that may have been set in any module due to reprogramming.
4. After Factory Reset is completed, allow a sleep cycle for five minutes.

NOTE: Suggest to customer to repeat the wireless device pairing again after deleting the existing pairing from the phone.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.