

GROUP	MODEL
Voluntary Emissions Service	2021-2024MY
Campaign	K5 (DL3a)
	w/1.6L T-GDI
NUMBER	DATE
SC288 (Rev 5, 3/19/2025)	April 2024

# VOLUNTARY EMISSIONS SERVICE CAMPAIGN


FUEL TANK AND/OR PCSV CHECK VALVE INSPECTION/REPLACEMENT + ECU SW UPGRADE (SC288)

### **NOTICE**

This bulletin has been revised to include additional information. New/revised sections of this bulletin are indicated by a black bar in the margin area.

This bulletin provides information to inspect the fuel evaporative system and, if necessary, replace the fuel tank and/or the Purge Control Solenoid Valve (PCSV) check valve on certain 2021-2024MY K5 (DL3a) vehicles equipped with a Gamma II 1.6L T-GDI engine, produced from March 27, 2020 through October 17, 2023. This bulletin also provides information to upgrade the ECU software logic. The subject vehicles may experience fuel tank swelling due to an issue with the PCSV check valve, which results in pressurized air to flow into the fuel tank. This may cause the Check Engine Light to illuminate, and in some cases, the engine to run rough, and/or an inability to refuel. These conditions may cause the vehicle to release air pollutant which exceed Federal and California standards.

Follow the procedure outlined in this publication to inspect the fuel evaporative system and, if necessary, replace the fuel tank and/or the PCSV check valve. Before conducting the procedure, verify that the vehicle is included in the list of affected VINs.




### **NOTICE**

Repair status for a VIN is provided on KDealer+ (Service  $\rightarrow$  Warranty Coverage  $\rightarrow$  Warranty Coverage Inquiry  $\rightarrow$  Campaign Information). Not completed Recall / Service Action reports are available on KDealer+ (Consumer Affairs  $\rightarrow$  Not Completed Recall  $\rightarrow$  Recall VIN  $\rightarrow$  Select Report), which includes a list of affected vehicles.

# FUEL TANK AND/OR PCSV CHECK VALVE INSPECTION/REPLACEMENT + ECU SW UPGRADE (SC288)

#### Flowchart:



Path 1: Vehicle IN → PCSV Check Valve Inspection (OK) → Upgrade ECU SW → Vehicle OUT

**Path 2:** Vehicle IN  $\rightarrow$  PCSV Check Valve Inspection (NG)  $\rightarrow$  Fuel Tank Band Inspection (OK)  $\rightarrow$  PCSV Check Valve Replacement  $\rightarrow$  Upgrade ECU SW  $\rightarrow$  Vehicle OUT

Path 3: Vehicle IN → PCSV Check Valve Inspection (NG) → Fuel Tank Band Inspection (NG) (attach photo) → Fuel Pump Cover Inspection (OK) → Fuel Tank <u>and</u> PCSV Check Valve Replacement → Upgrade ECU SW → Vehicle OUT


Path 4: Vehicle IN → PCSV Check Valve Inspection (NG) → Fuel Tank Band Inspection (NG) (attach photo) → Fuel Pump Cover Inspection (NG) (attach photo) → Open RA TL Case



# FUEL TANK AND/OR PCSV CHECK VALVE INSPECTION/REPLACEMENT + ECU SW UPGRADE (SC288)


### **Inspection Procedure: (PCSV Check Valve)**

1. Open the hood and locate the Purge Control Solenoid Valve (PCSV) (A).




2. Disconnect the PCSV check valve (B) from the outer hose clamps ends shown.

<u>Note</u>: The <u>new</u> PCSV check valve (B) assembly <u>comes</u> pre-assembled with new hose clamps and vapor hoses.



3a. Connect the SST air bleeding device (C) blue air line to the pressurization adapter (D).

SST 09580 3D100 SST KQ234 C6104FFF






# FUEL TANK AND/OR PCSV CHECK VALVE INSPECTION/REPLACEMENT + ECU SW UPGRADE (SC288)

- 3b. Connect the PCSV check valve (B) to the pressurization adapter (D).
- 3c. Connect the shop air supply hose to the air supply valve (E).
- 3d. Open shop air supply valve (E).




The pressurization adapter (D) MUST be connected to the PCSV check valve (B) in the direction shown. If the pressurization adapter is connected incorrectly, the inspection cannot be properly conducted due to incorrect airflow to the check valve.







- 5. Submerge the open end of the PCSV check valve (B) hose in water and confirm NO air bubbles are present.
  - Bubbles ARE present (NG), proceed to the 'Inspection Procedure: (Fuel Tank Bands and Service Cover)' (page 5).
  - NO bubbles present (OK), perform the 'ECU Upgrade Procedure' (page 8).

Note: DO NOT submerge the PCSV check valve (B) in the water. ONLY the hose is to be submerged in the water.














# FUEL TANK AND/OR PCSV CHECK VALVE INSPECTION/REPLACEMENT + ECU SW UPGRADE (SC288)

### **Inspection Procedure: (Fuel Tank Bands and Service Cover)**


1. Remove rear floor under covers (A).



Using a ruler, measure the gap between the fuel tank (B) and the  $\overline{\text{TOP}}$  of  $\underline{\text{BOTH}}$  fuel tank bands (C), as shown.

#### 2a. FWD/2WD

- If the gap between the fuel tank and the TOP of the fuel tank bands measures 24mm or LESS (OK), skip to complete the following:
  - 1. Replace the PCSV Check Valve
  - 2. ECU Upgrade Procedure (Page 8)
- If the gap between the fuel tank and the TOP of the fuel tank bands measures 25mm or MORE (NG), attach one clear photo using KDS Tablet Warranty Claim Attachment Tab of the NG measurement, then proceed to step 3.







# FUEL TANK AND/OR PCSV CHECK VALVE INSPECTION/REPLACEMENT + ECU SW UPGRADE (SC288)

### AWD/4WD

#### 2b. Left Hand Fuel Tank Band


- If the gap between the fuel tank and the TOP of the fuel tank bands measures 21mm or LESS (OK), proceed to measure the right hand fuel tank band.
- If the gap between the fuel tank and the TOP of the fuel tank bands measures 22mm or MORE (NG), attach one clear photo using KDS Tablet Warranty Claim Attachment Tab of the NG measurement, then proceed to step 3.






#### 2c. Right Hand Fuel Tank Band

- If the gap between the fuel tank and the TOP of the fuel tank bands measures 13mm or LESS (OK), skip to complete the following:
  - 1. Replace the PCSV Check Valve
  - 2. ECU Upgrade Procedure (Page 8)
- If the gap between the fuel tank and the TOP of the fuel tank bands measures 14mm or MORE (NG), attach one clear photo using KDS Tablet Warranty Claim Attachment Tab of the NG measurement, then proceed to step 3.








# FUEL TANK AND/OR PCSV CHECK VALVE INSPECTION/REPLACEMENT + ECU SW UPGRADE (SC288)

3. Remove the 2<sup>nd</sup> row bench seat (D) to access the fuel pump service cover (E).




Note: AWD model shown on the right for reference, the FWD models shown below feature a single fuel tank service cover access.



- 4. Inspect the seat floor to fuel pump service cover (E) (4 sides) for any gaps:
  - If a gap is NOT present (OK), the cover is seated flush with the seat floor panel, then proceed to replace both the PCSV check valve and Fuel Tank (page 12).

    After completing the two replacements, perform the 'ECU Upgrade Procedure' (page 8).
  - If a gap IS present (NG), the cover is lifted/detached from the seat floor panel, create a Techline Repair Assistance (RA) case, and attach one clear photo using KDS Tablet Warranty Claim Attachment Tab of the NG condition to the Techline case and Warranty Claim.







# FUEL TANK AND/OR PCSV CHECK VALVE INSPECTION/REPLACEMENT + ECU SW UPGRADE (SC288)

### **ECU Upgrade Procedure:**

To correct this condition, the ECU should be reprogrammed using the KDS download, as described in TSB SST081.

#### Upgrade Event Name

792.DL3a Gamma 1.6TGDI ECU Logic Improvement for Preventing Fuel Tank Pressure Increase 2nd

### **NOTICE**

- Confirm a <u>fully charged battery</u> (12.3 volts or higher is necessary) is used <u>or</u> utilize a fully charged jump starter box connected to the battery.
- Ensure the KDS is sufficiently charged at 60% or higher prior to reflash.
- All ECU upgrades must be performed with the ignition set to the 'ON' position unless otherwise stated.
- Damaged VCI II units should not be used and promptly replaced.
- Be careful not to disconnect the VCI-II connected to the vehicle during the ECU upgrade procedure.
- DO NOT start the engine during ECU upgrade.
- DO NOT turn the ignition key 'OFF' or interrupt the power supply during ECU upgrade.
- When the ECU upgrade is completed, turn the ignition 'OFF' and wait 10 seconds before starting the engine.
- ONLY use approved ECU upgrade software designated for the correct application.

### **(i)** IMPORTANT

It is recommended to ALWAYS check the Electronic Parts Catalog (EPC) to locate the ECU Part Number respective to Auto/Manual Mode ROM IDs. DO NOT reference the parts label affixed to the ECU.

# **NOTICE**

If a 'Communication Fail' error notice appears or the upgrade cannot be performed, DO NOT disconnect the KDS/VCI-II. Contact GIT America Help Desk at (888) 542-4371 or Techline.

### **NOTICE**

Before attempting an ECU upgrade on any Kia model, make sure to first determine whether the applicable model is equipped with an immobilizer [IMMO] security system. Failure to follow proper procedures may cause the PCM to become inoperative after the upgrade and any claims associated with this repair may be subject to chargeback.



# FUEL TANK AND/OR PCSV CHECK VALVE INSPECTION/REPLACEMENT + ECU SW UPGRADE (SC288)

#### **ROM ID INFORMATION TABLE:**

**Upgrade Event #792** 

1.07	11.41.40	100	_		ИID	
MY	IMMO	ISG	Туре	ECU P/No.	Previous	New
	Yes	ISG		39121 2MKKO	TDLA1NU06F022E0K TDLA1NU06F122E0K TDLA1NU06F223E0K TDLA1NU06F424E0K TDLA1NU06F524E0K TDLA1NU06F52FE0K TDLA1NU06F6FBE0K	TDLA1NUO6F7FBEOK
	No		2WD	39123 2MKKO	TDLA1NU06E022E0K TDLA1NU06E122E0K TDLA1NU06E223E0K TDLA1NU06E424E0K TDLA1NU06E524E0K TDLA1NU06E52FE0K TDLA1NU06E6FBE0K	TDLA1NU06E7FBE0K
21MY	Yes			39121 2MKTO	TDLA1NU06F022E03 TDLA1NU06F122E03 TDLA1NU06F223E03 TDLA1NU06F424E03 TDLA1NU06F524E03 TDLA1NU06F52FE03 TDLA1NU06F6FBE03	TDLA1NU06F7FBE03
	No	NON-ISG	2WD	39123 2MKTO	TDLA1NU06E022E03 TDLA1NU06E122E03 TDLA1NU06E223E03 TDLA1NU06E424E03 TDLA1NU06E524E03 TDLA1NU06E52FE03 TDLA1NU06E6FBE03	TDLA1NU06E7FBE03
	Yes	NON-ISG	4WD ·	39121 2MKVO	TDLA1NU06F026K03 TDLA1NU06F126K03 TDLA1NU06F12FK03 TDLA1NU06F2FBK03	TDLA1NU06F3FBK03
	No			39123 2MKVO	TDLA1NU06E026K03 TDLA1NU06E126K03 TDLA1NU06E12FK03 TDLA1NU06E2FBK03	TDLA1NU06E3FBK03

Continued on page 10.

To verify the vehicle is affected, be sure to check the Calibration Identification of the vehicle's ECM ROM ID and reference the Information Table as necessary.



# FUEL TANK AND/OR PCSV CHECK VALVE INSPECTION/REPLACEMENT + ECU SW UPGRADE (SC288)

#### **ROM ID INFORMATION TABLE:**

**Upgrade Event #792** 

MY	IMMO	ISG	T. (10.0	FCLLD/No	ROM ID		
IVI Y	IIVIIVIO	13G	Туре	ECU P/No.	Previous	New	
	Yes	ISG	2WD	39121 2MKK1	TDLA2NUO6F02EE0K TDLA2NUO6F12FE0K TDLA2NUO6F22FE0K TDLA2NUO6F3FBE0K	TDLA2NU06F4FBE0K	
	No	130	ZWD	39123 2MKK1	TDLA2NU06E02EE0K TDLA2NU06E12FE0K TDLA2NU06E22FE0K TDLA2NU06E3FBE0K	TDLA2NU06E4FBE0K	
22MY	Yes	es NON-ISG	2WD	39121 2MKT1	TDLA2NU06F02EE03 TDLA2NU06F12FE03 TDLA2NU06F22FE03 TDLA2NU06F3FBE03	TDLA2NU06F4FBE03	
221411	No	NONBO	2000	39123 2MKT1	Previous         New           TDLA2NU06F02EE0K TDLA2NU06F12FE0K TDLA2NU06F12FE0K TDLA2NU06F3FBE0K         TDLA2NU06F4FBE0K           TDLA2NU06E3FBE0K         TDLA2NU06E4FBE0K           TDLA2NU06E12FE0K TDLA2NU06E3FBE0K         TDLA2NU06E4FBE0K           TDLA2NU06F02EE03 TDLA2NU06F12FE03 TDLA2NU06F22FE03         TDLA2NU06F4FBE03		
	Yes	Yes NON-ISG	4WD	39121 2MKV1	TDLA2NU06F12FK03 TDLA2NU06F22FK03	TDLA2NU06F4FBK03	
	No			, 4440	39123 2MKV1	TDLA2NU06E12FK03 TDLA2NU06E22FK03	TDLA2NU06E4FBK03

Continued on page 11.

To verify the vehicle is affected, be sure to check the Calibration Identification of the vehicle's ECM ROM ID and reference the Information Table as necessary.



# FUEL TANK AND/OR PCSV CHECK VALVE INSPECTION/REPLACEMENT + ECU SW UPGRADE (SC288)

#### **ROM ID INFORMATION TABLE:**

# **Upgrade Event #792**

NAV	MY IMMO ISG		Type ECU P/No.		ROM ID		
IVI Y	IIVIIVIO	13G	Type	ECU P/NO.	Previous	New	
	Yes	ISG	2WD	39121 2MKK2	TDLA3NUO6F02NEOK TDLA3NUO6F1NAEOK TDLA3NUO6F2NBEOK	TDLA3NU06F3NBEOK	
	No	130	ZWD	39123 2MKK2	TDLA3NU06E02NE0K TDLA3NU06E1NAE0K TDLA3NU06E2NBE0K	TDLA3NU06E3NBEOK	
221417	Yes NON-	NONJISC	211112	39121 2MKT2	TDLA3NU06F02NE03 TDLA3NU06F1NAE03 TDLA3NU06F2NBE03	TDLA3NU06F3NBE03	
23MY	No	NON-ISG	2WD	39123 2MKT2	TDLA3NU06E02NE03 TDLA3NU06E1NAE03 TDLA3NU06E2NBE03	TDLA3NU06E3NBE03	
	Yes	- NON-ISG	4WD	39121 2MKV2	TDLA3NU06F02NK03 TDLA3NU06F1NAK03 TDLA3NU06F2NBK03	TDLA3NU06F3NBK03	
	No			39123 2MKV2	TDLA3NU06E02NK03 TDLA3NU06E1NAK03 TDLA3NU06E2NBK03	TDLA3NU06E3NBK03	
	Yes	100	0=	39121 2MKK3	TDLA4NU06F02YE0K TDLA4NU06F1YAE0K	TDLA4NU06F2YAEOK	
	No	ISG	2WD	39123 2MKK3	TDLA4NU06E02YE0K TDLA4NU06E1YAE0K	TDLA4NU06E2YAE0K	
24MY	Yes	NON-ISG	3WD	39121 2MKT3	TDLA4NU06F02YE03 TDLA4NU06F1YAE03	TDLA4NU06F2YAE03	
Z+1VI I	No	11011-130	2WD -	39123 2MKT3	TDLA4NU06E02YE03 TDLA4NU06E1YAE03	TDLA4NU06E2YAE03	
	Yes	NON-ISG	4WD	39121 2MKV3	TDLA4NU06F02YK03 TDLA4NU06F1YAK03	TDLA4NU06F2YAK03	
	No	11011-130	4WD	39123 2MKV3	TDLA4NU06E02YK03 TDLA4NU06E1YAK03	TDLA4NU06E2YAK03	

To verify the vehicle is affected, be sure to check the Calibration Identification of the vehicle's ECM ROM ID and reference the Information Table as necessary.



# FUEL TANK AND/OR PCSV CHECK VALVE INSPECTION/REPLACEMENT + ECU SW UPGRADE (SC288)


### Refer to TSB SST081 for instructions to upgrade the 'ENGINE' system:

#### **UPGRADE EVENT:**

 792.DL3a Gamma 1.6TGDI ECU Logic Improvement for Preventing Fuel Tank Pressure Increase\_2nd

### **NOTICE**

Prior to performing the ECU upgrade, be sure to check that the KDS is fully charged.



#### Manual Mode:

### **NOTICE**

The manual upgrade should ONLY be performed if the automatic upgrade fails.

If the automatic upgrade fails, turn the ignition 'OFF' for about 10 seconds then place it back in the 'ON' position to reset the control unit BEFORE performing manual upgrade.

See table below for 'Manual Mode' passwords and refer to TSB SST081 for instructions.

### Manual Mode ECU Upgrade Passwords

Menu	Password
DL3a -IMMO +ISG (21MY): 39123-2MKK0	1601
DL3a +IMMO/SMK +ISG (21MY): 39121-2MKK0	1602
DL3a -IMMO (21MY): 39123-2MKTO	1603
DL3a +IMMO/SMK (21MY): 39121-2MKT0	1604
DL3a -IMMO 4WD (21MY): 39123-2MKV0	1605
DL3a +IMMO/SMK 4WD (21MY): 39121-2MKV0	1606
DL3a -IMMO +ISG (22MY): 39123-2MKK1	1607
DL3a +IMMO/SMK +ISG (22MY): 39121-2MKK1	1608
DL3a -IMMO (22MY): 39123-2MKT1	1609
DL3a +IMMO/SMK (22MY): 39121-2MKT1	1610
DL3a -IMMO 4WD (22MY): 39123-2MKV1	1611
DL3a +IMMO/SMK 4WD (22MY): 39121-2MKV1	1612
DL3a -IMMO +ISG (23MY): 39123-2MKK2	1613
DL3a +IMMO/SMK +ISG (23MY) : 39121-2MKK2	1614
DL3a -IMMO 4WD (23MY) : 39123-2MKT2	1615
DL3a +IMMO/SMK (23MY) : 39121-2MKT2	1616
DL3a -IMMO (23MY) : 39123-2MKV2	1617
DL3a +IMMO/SMK 4WD (23MY) : 39121-2MKV2	1618
DL3a -IMMO +ISG (24MY) : 39123-2MKK3	1619
DL3a +IMMO/SMK +ISG (24MY) : 39121-2MKK3	1620
DL3a -IMMO (24MY) : 39123-2MKT3	1621
DL3a +IMMO/SMK (24MY) : 39121-2MKT3	1622
DL3a -IMMO 4WD (24MY) : 39123-2MKV3	1623
DL3a +IMMO/SMK 4WD (24MY) : 39121-2MKV3	1624

M

# FUEL TANK AND/OR PCSV CHECK VALVE INSPECTION/REPLACEMENT + ECU SW UPGRADE (SC288)

### Replacement Procedure: Fuel Tank


 Replace the fuel tank (A) by referring to "Engine Control / Fuel System → Fuel Delivery System → Fuel Tank → Repair procedures" in the applicable Shop Manual on KGIS.

<u>Note</u>: Be sure to replace all fuel tank related parts such as:

- 1. Fuel Tank (15 Gal. or 16 Gal.)
- 2. Fuel Tank Pads
- 3. Fuel Tank Heat Protector
- 4. Fuel Tank Bands
- 5. Ring Lock (AWD)

#### In addition, replace the non-reusable parts:

- 1. Rear Muffler Gasket
- 2. Fuel Pump Service Cover (if damaged)
- 3. Fuel Pump Packing (if damaged)
- 4. Propeller Shaft Bolts (AWD only)



- 2. Reinstall all removed parts in reverse order of removal.
- 3. Replace the PCSV Check Valve.
- 4. Perform the ECU SW Upgrade (Pages 8-11).
- 5. Confirm normal vehicle operation.



# FUEL TANK AND/OR PCSV CHECK VALVE INSPECTION/REPLACEMENT + ECU SW UPGRADE (SC288)

# ATTENTION: THE PROOF OF CORRECTION CARD AND CAMPAIGN COMPLETION LABEL ARE RESTRICTED ONLY TO DEALERS IN THE FOLLOWING STATES:

California, Connecticut, Delaware, Massachusetts, Maine, Maryland, New Jersey, New York, Oregon, Pennsylvania, Rhode Island, Vermont, and Washington. See Parts Information below to order the Proof of Correction Card and Campaign Completion Label from the PDC.

#### **VEHICLE EMISSION RECALL - PROOF OF CORRECTION CARD**


A Vehicle Emission Recall - Proof of Correction card must be filled out for all vehicles registered in California, Connecticut, Delaware, Massachusetts, Maine, Maryland, New Jersey, New York, Oregon, Pennsylvania, Rhode Island, Vermont, and Washington. Residents of these states, who own an affected vehicle, will be required to possess a Vehicle Emission Recall - Proof of Correction card as evidence of voluntary service campaign completion, when they apply for vehicle registration renewal.

#### WHAT TO DO WITH THE CARD:

The Vehicle Emission Recall - Proof of Correction card <u>must be completed by the Dealership's Service Manager using a permanent ink pen</u>. A fine point pen is recommended. When filling in the information, copy the information directly from the vehicle, not the repair order. **ALL INFORMATION MUST BE PRINTED AND NEAT.** 

#### NOTE: DO NOT COMPLETE THE CARD UNLESS THE SERVICE CAMPAIGN WORK IS COMPLETED.

The copy of the card shown below indicates the areas to be filled in. Each area must be filled in. The completed card should be given to the owner of the vehicle upon completion of the Campaign and placement of the Campaign Completion Label outlined below.



#### FILLING OUT AND APPLYING THE CAMPAIGN COMPLETION LABEL (CA and S.177 STATES ONLY):

The dealer must fill in the Dealer Code and Date information fields on the Campaign Completion Label. Once complete, affix the campaign completion label under the hood of the vehicle, as shown below.

CA and S.177 States Only: Apply <u>SC288</u> Campaign Completion Label onto the body in the area next to the shock tower, as shown. NOTE: Be sure to clean the mounting surface to ensure proper label adhesion.





# FUEL TANK AND/OR PCSV CHECK VALVE INSPECTION/REPLACEMENT + ECU SW UPGRADE (SC288)

### **AFFECTED VEHICLE RANGE:**

Model	Production Date Range
K5 (DL3a)	March 27, 2020 to October 17, 2023

### **REQUIRED TOOL:**

Tool Name	Part Number	Figure	Comments
KDS	N/A	Company   Comp	Kia Diagnostic System
Air Bleeding Tool	Tool 09580 3D100		Located Toolbox 2 Drawer #16
Pressurization Adapter	KQ234 C6104FFF		Part of KQ234 C6200FFF Cleaning Kit Per ENG222 Located 'SHOP'



# FUEL TANK AND/OR PCSV CHECK VALVE INSPECTION/REPLACEMENT + ECU SW UPGRADE (SC288)

#### **REQUIRED PART:**

Part Name	Part Number	Figure	Qty.
Campaign Completion Label	UT160 SC288	Section for the Control of the Contr	1
Vehicle Emissions Recall Proof of Correction Card	UT161 SC288	SC288 Dealer Code: Date:	1
PCSV Check Valve Assy	28918 2M431QQK		1

<u>Note</u>: The replacement part number 28918 2M431QQK will require a VIN entry for parts ordering. DO NOT order this part for stocking purposes, related to this Campaign. Supply is very limited. Until supply stabilizes, please confirm part availability before scheduling customers. Please be sure to expedite warranty claim filing.

Part Name	Part Number <mark>(FWD)</mark>	Part Number (FWD) Part number (AWD)	
Fuel Tank	31150 L0600 (56L/15 Gal.) 31150 L0000 (60L/16 Gal.)		1
Fuel Tank Heat Protector	31220 L1000 31220 L3600		1
Fuel Tank Band (LH)	31210 L1000	31210 L3600	1
Fuel Tank Band (RH)	31211 L1000	31211 L3600	1
Rear Muffler Gasket	28751	2T000	1
Fuel Pump Service Cover	31107	1	
Fuel Pump Packing	31115 C	1	
	31101 L1100	31101 L3600	2
	31101 C1000		5
Fuel Tank Pads	31101 L1000	31101 L1000	2
	31101 3X000		1
		31101 C8000	8
Ring Lock		31152 OW000	1
Propeller Shaft Bolts		11435 10256K	1



# FUEL TANK AND/OR PCSV CHECK VALVE INSPECTION/REPLACEMENT + ECU SW UPGRADE (SC288)

#### **WARRANTY INFORMATION:**

N Code: N99 C Code: C99

Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
			(SC288) PCSV Inspection <b>(OK)</b> + ECU SW Upgrade	240A03l2	0.5 M/H	N/A	1
R	59133 2H000	0	(SC288)  PCSV Inspection (NG) +  PCSV Replacement +  Fuel Tank Band Inspection (OK) +  ECU SW Upgrade  (FWD)	240A03RG	G 0.9 28918 2M431QQK	28918 2M431QQK	1
			(SC288) PCSV Inspection (NG) + PCSV Replacement + Fuel Tank Band Inspection (OK) + ECU SW Upgrade (AWD)	240A03RH	1.0 M/H	28918 2M431QQK	1

Continued on page 18.



VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference SC288 when accessing the KDealer+ system.



# FUEL TANK AND/OR PCSV CHECK VALVE INSPECTION/REPLACEMENT + ECU SW UPGRADE (SC288)

	Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.	
							28918 2M431QQK	1	
							31150 L0600		
							or	1	
				(SC288)			31150 L0000		
				PCSV Inspection (NG) +			31220 L1000	1	
				PSCV Replacement +			31210 L1000	1	
				Fuel Tank Band Inspection (NG) +	24040201*	2.1	31211 L1000	1	
				Service Cover Inspection (OK)+	240A03RJ*	M/H	28751 2T000	1	
				Tank Replacement +			31107 L1000	1	
				ECU SW Upgrade			31115 OWOOO	1	
				(FWD)			31101 L1100	2	
							31101 C1000	5	
							31101 L1000	2	
						-	31101 3X000	1	
						28918 2M431QQK	1		
							31150 L3600	1	
				(0.0000)			31220 L3600	1	
				(SC288)			31210 L3600	1	
			133 2H000 0 PSCV Fuel Tank B	PCSV Inspection (NG) +	1 740A03RK" 1	2.3 M/H	31211 L3600	1	
	R	59133 2H000		PSCV Replacement +			28751 2T000	1	
				Fuel Tank Band Inspection (NG) + Service Cover Inspection (OK)+			31107 L1000	1	
				Tank Replacement +			31115 OW000	1	
				ECU SW Upgrade			31101 L3600	2	
				(AWD)			31101 L1000	2	
				( (Mo)			31101 C8000	8	
							31152 OWOOO	1	
			Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι Ι		11435 10256K	1			
				0.6 M/H	N/A	0			
					(SC PCSV Insp Fuel Tank Band Inspec (Techline RA	(SC288) PCSV Inspection (NG) + Fuel Tank Band & Service Cover Inspection (NG) (Techline RA Open Required) (AWD)	240A03RM*	0.7 M/H	N/A

Note: Refer to Warranty Bulletin 2024-27 for claim submission procedures. Manually enter sublet code 'X2' for reimbursement of one roundtrip rideshare expense or up to three (3) days of rental expense, with supporting documentation. \*A photo of the 'NG' condition, as described in this TSB MUST be attached to the claim using Warranty Claim Attachment Type 'XX - Other' for LOP 240A03RJ, 240A03RK, 240A03RL and 240A03RM.

### **NOTICE**

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference SC288 when accessing the KDealer+ system.

