

Technical Service Bulletin

| | |
|------------------------|---|
| Topic | Engine light in the DIP - Various oxygen sensor / Fuel ratio DTC's logged within the Engine Control Module(s) |
| Market area | Bentley: worldwide (2WBE),China 796 VW Import Comp. Ltd (Vico), Beijing (6796) |
| Brand | Bentley |
| Transaction No. | 2075331/2 |
| Level | EH |
| Status | Released for publishing |
| Release date | Mar 4, 2025 |

Diagnostic trouble codes

| Diagnostic address | Diagnostic trouble code | Fault symptom | Storage state |
|-----------------------------|---|---------------|---------------|
| 0001 - Engine electronics | P003100: O2 Sensor Heater Contr. Circ.(Bank1(1)Sensor 1) Low | | static |
| 0001 - Engine electronics | P003000: O2 Sensor Heater Contr. Circ.(Bank1(1)Sensor 1) | | static |
| 0001 - Engine electronics | P005100: O2 Sensor Heater Contr. Circ.(Bank2 Sensor 1) Low | | static |
| 0001 - Engine electronics | P005000: O2 Sensor Heater Contr. Circ.(Bank2 Sensor 1) | | static |
| 0001 - Engine electronics | P016A00: Excessive Time To Enter Closed Loop Air/Fuel Ratio Control | | static |
| 0011 - Engine electronics 2 | P003100: O2 Sensor Heater Contr. Circ.(Bank1(1)Sensor 1) Low | | static |
| 0011 - Engine electronics 2 | P003000: O2 Sensor Heater Contr. Circ.(Bank1(1)Sensor 1) | | static |
| 0011 - Engine electronics 2 | P005100: O2 Sensor Heater Contr. Circ.(Bank2 Sensor 1) Low | | static |
| 0011 - Engine electronics 2 | P005000: O2 Sensor Heater Contr. Circ.(Bank2 Sensor 1) | | static |
| 0011 - Engine electronics 2 | P016A00: Excessive Time To Enter Closed Loop Air/Fuel Ratio Control | | static |

New customer code

| Object of complaint | Complaint type | Position |
|--|--|----------|
| power, vehicle electrical system, data transfer -> databus systems | component, automotive fluids | |
| vehicle service -> vehicle diagnosis -> Guided Fault Finding (GFF) | control modules, services -> with fault stored in the DTC memory | |
| transmission -> power distribution, transmission of power -> transmission of power | functionality -> no function | |
| power, vehicle electrical system, data transfer -> power supply | functionality | |

Vehicle data

Continental GT/C - Flying Spur - Bentayga Series

Sales types

| Type | MY | Brand | Designation | Engine code | Gearbox code | Final drive code |
|------|------|-------|-------------|-------------|--------------|------------------|
| 3S3* | 2018 | E | | * | * | * |
| 3S3* | 2019 | E | | * | * | * |
| 3S3* | 2020 | E | | * | * | * |
| 3S3* | 2021 | E | | * | * | * |
| 3S3* | 2022 | E | | * | * | * |
| 3S3* | 2023 | E | | * | * | * |
| 3S3* | 2024 | E | | * | * | * |
| 3S4* | 2019 | E | | * | * | * |
| 3S4* | 2020 | E | | * | * | * |
| 3S4* | 2021 | E | | * | * | * |
| 3S4* | 2022 | E | | * | * | * |
| 3S4* | 2023 | E | | * | * | * |
| 3S4* | 2024 | E | | * | * | * |
| 4V1* | 2017 | E | | * | * | * |
| 4V1* | 2018 | E | | * | * | * |
| 4V1* | 2019 | E | | * | * | * |
| 4V1* | 2020 | E | | * | * | * |
| 4V1* | 2021 | E | | * | * | * |
| 4V1* | 2022 | E | | * | * | * |
| 4V1* | 2023 | E | | * | * | * |
| 4V1* | 2024 | E | | * | * | * |

| | | | | | | |
|------|------|---|--|---|---|---|
| 4V1* | 2025 | E | | * | * | * |
| Z23* | 2025 | E | | * | * | * |
| Z24* | 2025 | E | | * | * | * |
| Z32* | 2025 | E | | * | * | * |
| ZG2* | 2020 | E | | * | * | * |
| ZG2* | 2021 | E | | * | * | * |
| ZG2* | 2022 | E | | * | * | * |
| ZG2* | 2023 | E | | * | * | * |
| ZG2* | 2024 | E | | * | * | * |
| ZV1* | 2023 | E | | * | * | * |
| ZV1* | 2024 | E | | * | * | * |
| ZV1* | 2025 | E | | * | * | * |

Documents

| |
|----------------------------|
| Document name |
| master.xml |

Condition

Engine light in the DIP - Various oxygen sensor / Fuel ratio DTC's logged within the Engine Control Module(s)

Technical Background

In the event that one or a combination of DTC's shown below are evident within the engine control module(s) the operative should carry out the instructions within the Measure section of this TPI

Production Solution

-

Service

- 1) Referring to the VIN applicable wiring diagram within Elsa pro - Conduct a wiring integrity check of the oxygen sensor circuits
- 2) Locate the fuse(s) which are assigned to the oxygen sensor circuits
- 3) Conduct a visual inspection of the following:

- Fuse holder terminals - Check for damage / misalignment of terminals

Hint: In this scenario the terminals must be repaired / replaced (depending on damage) once repaired / replaced the fuse must be renewed, ensure both fuse blades are aligned to both terminals before fitting the fuse

- Fuse - Check for damage / bent fuse blade(s)

Hint: The fuse blades shown in Figure 1 are damaged / bent, in this scenario the fuse must be renewed, ensure both blades are aligned to both terminals before fitting the fuse




Figure 1

NOTICE

In the event the issue is still evident after conducting the previous steps, the operative must raise a to raise technical DISS query and await feedback before conducting any further work

Warranty

Warranty type: 110 or 910

Service ID number: 24 70

Damage type: 00 55

Diagnosis time

Labour operation code: 01 51 00 00

Time: As per ODIS log must not exceed 50 TU

Time to conduct wiring integrity checks

Labour operation code: 97 09 01 00

Time: 50 TU

