Technical Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



Subject:		
OIL SEEPAGE OR LEAKS AT ENGINE FRONT COVER	Bulletin No.: 01-002/25	
	Last Issued : 03/06/2025	

BULLETIN NOTES

This bulletin supersedes the previously issued bulletin(s) listed below. The changes are noted in Red text.

Previous TSBs:	Date(s) Issued:
01-008/24	06/21/24
01-006/23	04/26/23

APPLICABLE MODEL(S)/VINS

2020-2021 CX-30 2.5L with cylinder deactivation with VINs lower than 3MV DM**** ** 239819 (Produced before Dec. 23, 2020)

2018-2020 CX-5 2.5L with cylinder deactivation with VINs lower than JM3 KF**** ** 869654 (Produced before Aug. 24, 2020)

2021-2022 CX-5 2.5L with cylinder deactivation with VINs lower than JM3 KF**** ** 649502 (Produced before Aug. 1, 2022)

2023 CX-5 2.5L with cylinder deactivation with VINs lower than JM3 KF**** ** 292784 (Produced before Sep. 21, 2023) 2019-2020 Mazda3 (Japan built) 2.5L with cylinder deactivation with VINs lower than JM1 BP**** ** 176405 (Produced before Apr. 2, 2020)

2019-2021 Mazda3 (Mexico built) 2.5L with cylinder deactivation with VINs lower than 3MZ BP**** ** 210133 (Produced before Dec. 23, 2020)

2018-2021 Mazda6 2.5L with cylinder deactivation with VINs lower than JM1 GL**** ** 620105 (Produced before Nov. 12, 2021)


NOTE: To identify vehicles with cylinder deactivation, check the 8th digit of the VIN.


- L: 2.5L without cylinder deactivation
- M: 2.5L with cylinder deactivation

DESCRIPTION

Some vehicles may exhibit oil seepage or oil leak onto the engine front cover, which becomes more apparent with dust adhesion.

Page 1 of 15





Customers experiencing this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

1. Verify the customer concern.

Situation1:

When you receive a customer complaint for this concern, confirm the oil seepage or leak and repair it according to the procedure below.

Situation2:

When you find an oil leak or seepage during vehicle inspection, refer to "Repair Standards for Resealing" below, and repair it according to the procedure below.

Repair Standards for Resealing

	Front cover	Under cover
Need to repair	□The area around the cover is heavily soiled with oil	□Oil accumulation on cover. □Oil adheres to the oil leakage marks by touching it.


Page 2 of 15

Last Issued : 03/06/2025

Bulletin No.: 01-002/25







No need to repair

The oil is completely dry by touching the oil seepage area.

No oil accumulation on cover.

Procedure for Oil Seepage or Leak

Correctly follow the cleaning process and appropriate amount of sealant to eliminate any future requirement to reseal. Failure to follow the cleaning and sealant application as outlined in the steps below will impact repair effectiveness and may lead to a second repair 1-3 years later, which would not be covered under warranty.

1. Remove the engine front cover according to the MGSS online instructions TIMING CHAIN REMOVAL/INSTALLATION [SKYACTIV-G (WITH EGR COOLER)].

CAUTION: When removing the front cover, be sure to remove the oil pan at the same time. Insufficient cleaning of the mating face of the oil pan may cause oil leakage.

2. Completely clean and remove oil, dirt, sealant or other foreign matter that may be adhering to the engine front cover, cylinder head, or engine block.

Page 3 of 15


Bulletin No.: 01-002/25	Last Issued : 03/06/2025
· · · · · · · · · · · · · · · · · · ·	


CAUTION: If oil, dirt and sealant remains on the sealant application area, the silicone sealant will not seal properly, which will cause oil leakage.

Page 4 of 15

3. When reusing the engine front cover installation bolts, remove sealant from the bolts.

CAUTION: If a bolt with sealant (1) on it is used, it could result in cracks (2) in the cylinder head and engine block.






4. Install new O-rings to the engine front cover.

CAUTION:


- Install the O-rings so that the tabs of the O-rings recede into the notches.
- DO NOT use any sealant on the O-rings.



Page 5 of 15

5. Apply silicone sealant (TB1217D or equivalent) to the engine front cover, as shown below.


CAUTION: Apply the silicone sealant to the area (A) between the cylinder block (B) and head (C) so that it goes into the cylinder head gasket (D).



CAUTION:

- Apply the silicon sealant in a single, unbroken line.
- To prevent silicone sealant from hardening, adhere the engine front cover and engine block firmly within 10 minutes after applying silicone sealant. After adhering them, tighten the installation bolts immediately.
- Mazda Sealant has an expiration date, check the tube to be sure it has not been opened and it has not expired.

Page 6 of 15



Bead thickness

A: 2—6 mm {0.1—0.2 in}

B: 4—6 mm {0.16—0.23 in}


C: 4—8 mm {0.2—0.3 in}

Page 7 of 15

Reference information: Sealing Mechanism


Bulletin No.: 01-002/25

Sealant (2) spreads to the step bead (1) and sealing performance is ensured.



1	Step bead
2	Sealant (TB1217D or equivalent)
3	Front cover
4	Engine

Page 8 of 15





Notes on resealing the front cover:

Bulletin No.: 01-002/25

The following areas (1) have a smaller step bead (2), so be careful about the amount and location of sealant application.

Page **9** of **15**






6. Install the front seal with SST and engine front cover according to the MGSS online instructions TIMING CHAIN REMOVAL/INSTALLATION [SKYACTIV-G (WITH EGR COOLER)].

Engine Front Cover Installation Note:


NOTE: For a new engine front cover, the positioning pins in the two locations shown below project to the outside of the engine.



NOTE: If the engine front cover is newly replaced, tap the positioning pins in the two (2) locations to the seal surface side.

Page 10 of 15

Bulletin No.: 01-002/25




Page **11** of **15**

NOTE: Temporarily install a M8 \times 1.25 bolt (length 40 mm {1.6 in} to the drive belt auto tensioner installation bolt hole (1) to prevent the following:


- A silicone sealant adhesion malfunction in the drive belt auto tensioner installation bolt hole.
- · A bolt mis-installation due to silicone sealant hardening.

Bulletin No.: 01-002/25



7. Tighten the engine front cover installation bolts in the order shown below.

CAUTION: For the number 10 bolt of the tightening order, install the bolt with a new washer.



Tightening torque 20—26 N·m {2.1—2.6 kgf·m, 15—19 ft·lbf}

8. Remove the bolt installed to the drive belt auto tensioner installation bolt hole when installing the drive belt auto

Page 12 of 15

Bulletin No.: 01-002/25 Last Issued : 03/06/2025

tensioner.

- 9. Re-install the other removed parts.
- 10. Verify the repair.

Page 13 of 15

Bulletin No.: 01-002/25 Last Issued : 03/06/2025


PARTS INFORMATION

Parts Number	Description	Qty.	Notes
PYFA-10-235	GASKET, HEAD COVER	1	[R]
PE01-12-257	RING,'O'	1	[R] for electric variable valve timing motor/driver
ZJ01-10-243	WASHER, SEALING	1	[R] for front cover
PE01-10-602	SEAL, OIL	1	[R] for front oil seal
PYFA-10-673	RING,'O'	3	[R] for front cover
9956-41-400	GASKET	1	[R] for oil pan drain plug
0000-77-1217-ES	SILICONE	1	


[R]: Replacement parts


Replacement parts location

· Gasket for cylinder head cover



- O-ring for electric variable valve timing motor/driver
- · Other parts for front cover
- · Gasket for oil pan drain plug





Page 14 of 15

Bulletin No.: 01-002/25	Last Issued : 03/06/2025
-------------------------	--------------------------

WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Powertrain Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	А
Symptom Code	76
Damage Code	99
Part Number Main Cause	7777-SP-X26
Quantity	0
Operation Number / Labor Hours:	XXWBKXAX / 3.6 Hrs. (CX-5 / Mazda6) XXWBKXAX / 3.8 Hrs. (CX-30 / Mazda3)

NOTE: Claim the engine oil (Max. 4.3 L {4.5 US qt, 3.8 lmp qt}) as related parts.

Page **15** of **15**