# Check engine light or Adblue warning with fault codes P206B31, P203B31, or P300494 when outside temperatures are below 32 degrees Fahrenheit. SCR Gen4 (KP7)

Topic number LI49.20-N-078838

Version 7

Function group 49.20 - Exhaust gas aftertreatment

Date 3/18/25

Validity Model 907 with SCR Gen4 (KP7)

Reason for change Validity Update

### Complaint

The check engine light or AdBlue warning is activated, accompanied by one or more of the following fault codes related to the AdBlue tank:

P206B31: Malfunction of the concentration sensor for AdBlue; the signal is absent.

P203B31: Malfunction of the AdBlue fill level sensor; the signal is absent.

P300494: The quality of the AdBlue is insufficient.


#### Cause


- A. The software for the AdBlue (SCR) control unit (N118/5) is outdated.
- B. The concentration of AdBlue is either above or below the Mercedes-Benz specifications, which can lead to premature freezing.
- C. Frozen or partially frozen AdBlue can cause the AdBlue level sensor to misread levels.
- D. The AdBlue level sensor is damaged.

### Remedy

- A. Software
- 1. Verify no newer software in AdBlue® SCR control unit (N118/5).
- 2. Complete LI49.20-N-075995 for Adblue warning reset.
- --NOTE-- If there is no updated software available, print the XENTRY screen indicating this and proceed to step B.
- B. Adblue Concentration
- 1. Verify the AdBlue concentration
- a. According to WIS AR49.20-D-9264TS Check the concentration of AdBlue
- b. Per the freeze frame data 'Development data (Urea Qualitaet Rohwert)', see attachment 'Urea Quality'.
- --NOTE-- If the AdBlue concentration is below 31.8% or above 33.2%, it must be replaced. Please note that this will be at the customer's expense.
- 2. If the AdBlue concentration is within the approved specifications, please proceed to step C.

- C. Frozen Adblue or the SCR Actual Values state 'Frozen Adblue'
- 1. Check if the AdBlue is frozen. If it is, let the vehicle sit in a warm place overnight and recheck.
- 2. Have the vehicle running and XENTRY hooked up displaying Adblue level values
- 3. Drain the Adblue Tank and verify fill level reflects the change in the Adblue level
- 4. Fill the Adblue Tank SLOWLY and do not overfill, verify fill level reflects the change in the Adblue level. Print the Actual Values page of the XENTRY with the AdBlue tank showing Full, Empty, and Full states.
- --NOTE-- The Fill Level Sensor 1 functions as the "empty sensor." It accurately measures the bottom 60 mm (2.3 inches) of the AdBlue tank. Once the tank is filled beyond the 60 mm (2.3 inch) mark, the sensor may not read accurately, and you might notice the displayed value fluctuating. This behavior is normal, see attachment 'Fill Level 1'.
- 5. Reset the Adblue Tank fill level via XENTRY. Please print the XENTRY pages that indicate the AdBlue tank fill-up was completed successfully.
- --NOTE-- If the XENTRY still shows that there is frozen Adblue or the concentration is still inaccurate after draining and filling, please refer to the attachments 'Adblue Frozen' and 'Adblue Concentration' and proceed to step D.
- 6. Complete LI49.20-N-075995 for Adblue warning reset. Please print the XENTRY pages that indicate the AdBlue warning reset was completed successfully.
- --NOTE-- If the steps above do not fix the vehicle, please proceed to step D.
- D. Damaged Adblue Level Sensor/Concentration Sensor
- 1. Replace the Adblue Tank
- 2. With the vehicle running and XENTRY hooked up displaying Adblue level values
- 3. Fill the Adblue Tank SLOWLY and do not overfill, verify fill level reflects the change in the Adblue level
- 3. Reset the Adblue Tank fill level via XENTRY
- 4. Complete LI49.20-N-075995 for Adblue warning reset.
- --NOTE-- During LI49.20-N-075995 for Adblue warning reset, please ensure that the outside temperature sensor is reading above 10 degrees Fahrenheit. If it is not, keep the vehicle inside the shop overnight. Complete LI49.20-N-075995 again. Additionally, please note that the vehicle may need to be driven to allow the NOx sensors and SCR system to complete their self-test. Once this is finished, the P13DF00 code should be stored and can then be cleared.
- --NOTE-- During cold weather, when temperatures are below 32 degrees Fahrenheit, please advise the client to keep the AdBlue tank fill level between 50% and 85%. This will allow for proper fluid expansion and help prevent damage to the level/concentration sensor.





WIS-References					
Document number	Title	Note			
AP49.20-D-0101TS	AdBlue(R) tank - Check/correct fluid level				
AR49.20-D-2015TS	Empty/fill AdBlue(R) tank				
AR49.20-D-2014TSF	Remove/install AdBlue(R) tank				

#### Disclaimer

NOTE: The information contained in this document is intended for use by trained, professional technicians with the knowledge to properly and safely perform diagnosis and repairs on Mercedes-Benz vehicles, using Mercedes-Benz approved tools and equipment. It informs service technicians about conditions that could occur in certain vehicles and provides information that could assist in proper vehicle diagnosis, service, or repair. It does not indicate that a defect is present in any vehicle referenced in this document nor does it imply warranty coverage. DO NOT assume that a symptom or condition, or a described cause of a symptom or condition, affects any particular vehicle or groups of vehicles, or that a described repair applies to any particular vehicle or groups of vehicles. There can be multiple causes resulting in the same or similar symptoms or conditions described in this document, and trained professional service

## **XENTRY Tips**

technicians must use their diagnostic skills to make evaluations on a case-by-case basis. The information contained in this document does not guarantee warranty coverage nor does it extend the vehicle's warranty in any way.

Symptoms				
Power generation > Fuel system > Fuel tank > Function > Different level				
Power generation > Exhaust system > AdBlue > AdBlue consumption > Too high				

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A9104702401			NOX REDUCING AGENT TANK	1		Х

Control unit/fault code					
Control unit	Fault text				
N3/40 - Motor electronics 'MRD1' for combustion engine 'OM654' (CDI) (MRD1NFZ)	P300494 - The AdBlue® quality is insufficient.				
N118/5   N141 - Selective catalytic reduction (SCR GEN4) (UDCM2)	P203B31 - The AdBlue® fill level sensor has a malfunction. The signal is not present.				
	P206B31 - Concentration sensor 'AdBlue®' has a malfunction. The signal is not present.				

Operation numbers/damage codes					
Op. no.	Operation text	Time	Damage code	Note	
470643	Check separate parts of AdBlue(R) system: as per fault code	07		This Operation item is used for completing LI49.20-N-075995.	
499264	Check AdBlue(R) concentration (After quick test)				
499290	Empty/fill AdBlue(R) tank				
499292	Replace AdBlue(R) tank		4707250		
540650	On-board power supply voltage Maintain (when checking/testing and troubleshooting)				
540990	Program, code control unit (After quick test)			If newer software is available	
541011	Perform quick test				