

Vehicle-specific service

Topic	91 PSS MMI system: time does not automatically change to daylight saving time or back again
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Audi
Transaction No.	2077132/1
Level	EH
Status	Released for publishing
Release date	Mar 7, 2025

Vehicle data

Q6 e-tron

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
GF*	2025	A		*	*	*

Chassis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
WA1	*	GF	*	S	*	000001	999999		

Documents

Document name
master.xml



Connection offline

Vehicle-specific service

Transaction No.: **2077132/1**

91 PSS MMI system: time does not automatically change to daylight saving time or back again

Release date: Mar 7, 2025

Condition

Customer states:

The time in the MMI does not automatically change to daylight saving time or back, even when automatic time adjustment has been set in the MMI.

This behavior is consistent wherever the time is shown on all displays. The behavior is rectified after one or more bus sleep cycles.

Workshop findings:

The complaint can be reproduced in the workshop.

Technical Background

Software issue.

Production Solution

This concern will no longer occur in vehicles manufactured in week 48/25 or later.

Service

1. Explain to the customer that a solution is expected to be available by the end of the 3rd quarter of 2025 (subject to change) and that no repairs are necessary at this point.
2. Do not replace any components for this condition since this will not resolve the customer's concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*).

Workaround:

The issue may resolve itself after a few minutes. It can also be remedied by performing a soft reset (pressing and holding the volume control) or a bus sleep cycle. Optimized software which stops the issue described from occurring is being developed. It is currently being checked when this software will be made available.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2077132**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2025 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.