

Vehicle-specific service

Topic	91 PSS MMI entertainment: occasionally no audio output for entertainment when vehicle is started
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Audi
Transaction No.	2077164/1
Level	EH
Status	Released for publishing
Release date	Mar 7, 2025

Vehicle data

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
GF*	2025	A		*	*	*

Chassis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
WA1	*	GF	*	S	A	000001	999999		

PR numbers

PR numbers
?:with 8RT
?:or ??:with 9VS

Documents

Document name
master.xml



Connection offline

Vehicle-specific service

Transaction No.: **2077164/1**

91 PSS MMI entertainment: occasionally no audio output for entertainment when vehicle is started

Release date: Mar 7, 2025

Condition

Customer States:

When the vehicle is started, there is occasionally no audio output for radio or media on the MMI. The issue occurs consistently across all radio and media sources.

Audio output can also not be restored by pressing or turning the volume control or by pressing the play/pause button in the MMI's entertainment menu. However, the MMI screen gives the impression that audio output is available: the volume bar appears and shows the set volume when the volume control is turned, and playback of the selected media source is indicated when the play button is pressed.

The complaint only affects audio output for radio and media. Other audio output is available, such as for the following instructions:

- Turn signals
- Parking aid
- Warning tones
- Voice guidance
- Phone calls
- Spoken dialogues with the Audi assistant

Workshop Findings:

The concern can be duplicated.

Technical Background

Software issue.

This specific complaint only occurs in vehicles with one of the following equipment combinations:

PR number	Description
9VS	Bang & Olufsen premium sound system with 3D sound
8RT	Bang & Olufsen premium sound system with 3D sound and loudspeakers in head restraints

Production Solution

The complaint will no longer occur in vehicles manufactured in CW 48/25 or later.

Service

1. Explain to the customer that a solution is expected to be available by the end of the 3rd quarter of 2025 (subject to change) and that no repairs are necessary at this point.
2. Do not replace any components for this condition since this will not resolve the customer's concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*).

Workaround:

The complaint can be rectified by a bus sleep cycle.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2077164**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2025 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.