

Warning Message "Chassis Failed" / Fault Memory Entry "C12EF00" in the Control Unit for Chassis Control (PASM) as Part of the Sales Review (06/25)

Model Line: **911 (992)**

Model Year: **As of 2025**

Concerns: **Control unit for chassis control (PASM)**

Cause: **During the sales review, the lit yellow or red warning message 'Chassis failed' is detected in the instrument cluster.**

The following fault memory entry is stored in the fault memory of the control unit for chassis control (PASM):

- **C12EF00** – New installation detected (030002)



Information

Replacing the control unit for chassis control (PASM) is not expedient for this complaint and does not provide any remedy.

Action: If there is a complaint, re-code the control unit for chassis control (PASM) using the PIWIS tester.



Information

The minimum requirement for coding is the PIWIS Tester software release **43.200.031** (or higher)

Required tools

- Tools:
- **P90999 - PIWIS Tester 4**
 - Battery charger with a current rating of **at least 90 A** and a **current and voltage-controlled charge map** for lithium starter batteries, e.g. **VAS 5908 - battery charger 90 A**. For further information about the battery chargers to be used, see the corresponding Workshop Manual. ⇒ *Workshop Manual '270689 Charge battery and vehicle electrical system'*

Re-coding control unit for chassis control (PASM)

Work Procedure: 1 Re-code the control unit for chassis control (PASM).

The basic procedure to follow for control unit coding is described in the Workshop Manual. ⇒ *Workshop Manual '270689 Basic instructions and procedure for control unit programming using the PIWIS Tester'*

Specific information on control unit coding in the context of this Technical Information:

Required PIWIS Tester software release:	43.200.031 (or higher)
---	-------------------------------

Type of control unit coding:	Control unit coding using the ' Automatic coding ' function in the instrument cluster control unit. (PASM).
Coding sequence:	Read and follow the information and instructions on the PIWIS Tester during the guided coding sequence. Do not interrupt the coding process. When coding is complete, the message "Coding has been completed successfully" is displayed and a tick appears in the "Status" box.
Procedure if control unit coding is not successful :	Repeat control unit coding.

- 2 Read out and delete all control unit fault memories.
- 3 Exit the diagnostic application, switch off the ignition and disconnect **P90999 - PIWIS Tester 4** from the vehicle.
- 4 Switch off and disconnect the battery charger.
⇒ *Workshop Manual '270689 Charging vehicle electrical system battery'*

Labor position and PCSS encryption

Labor position:

APOS	Labor operation	I No.
43162540	Re-coding control unit for chassis control (PASM)	

PCSS encryption:

Location (FES5)		
	43160	Control unit for chassis control
Damage type (SA4)		
	1134	Programming error

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2025 Porsche Cars North America, Inc.