

Countries:		Document ID:	IK2200158
Availability:	ISIS, FleetISIS, NotSIR	Revision:	0
Major System:	BUS BODY	Created:	3/18/2025
Current Language:	English	Last Modified:	3/26/2025
Other Languages:	NONE	Author:	Aaron Aguilera
Viewed:	30		

Less Info

Hide Details Coding Information									
Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful		
GO		View My Bookmarks			F				

Title: Electrical Door Calibration Confirmation

Applies To: E79 Next Gen Bus

CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

03/26/2025 - Initial Article Release	1
	1
	i
	- i
	//

DESCRIPTION

This document will guide the user through updating the electric entrance door BCM software on vehicles equipped with electric doors. The new software enables a new method of calibrating the door motor modules. The electric door calibration procedure includes new steps and will now honk the horn when the door calibration process is initiated, providing feedback to the user that the procedure was done successfully.

SYMPTOM(s)

Diagnostic Trouble Code(s) & Dashboard Indicator Light(s): Not Applicable

DTC/Light	Description				
N/A					

Customer Observations or Concerns: Not Applicable

SPECIAL TOOL(s) / SOFTWARE

N/A		

SERVICE PARTS INFORMATION

Kit Description	Part Number	Quantity Required	Notes	
N/A				

DIAGNOSTIC STEP(s)

Not Applicable

REPAIR STEP(s)

WARNING! To prevent property damage, personal injury, and / or death, park vehicle on a hard, flat surface, turn the engine off, set the parking brake, and install wheel chocks to prevent the vehicle from moving in either direction.

WARNING! To prevent property damage, personal injury, and / or death, if the vehicle must be raised, do not work under the vehicle supported only by jacks. Jacks can slip or fall over.

WARNING! To prevent personal injury and / or death, always wear safe eye protection when performing vehicle maintenance.

WARNING! To prevent property damage, personal injury, and / or death, keep flames or sparks away from vehicle and do not smoke while servicing the vehicle's batteries. Batteries expel explosive gases.

WARNING! To prevent property damage, personal injury, and / or death, remove the ground cable from the negative terminal of the battery box before disconnecting any electrical components. Always connect the ground cable last.

REPAIR PROCEDURE:

- 1. Bring vehicle into shop and park on a flat surface.
- 2. Shift transmission into park or neutral, set parking brake and install wheel chocks.
- 3. Connect to the vehicle using DLB and an applicable data link cable with ignition key on.
- 4. Click on the select tab in DLB and verify the BCM (labelled as ESC in DLB) has at least Kernel 747 and Data Version 446 or later. If not, use the update all button to load the latest software for the modules on the vehicle. Then use the program button to flash the updates to the vehicle.

											-	~
2 International® Diamond Lo	gic® Builde	r								-	U	×
File Edit View Advanced Logis	c Tools Dia	groups H	eip 4						Edi	ting - 3HSC	ZTZRIL	N864780
🗅 🖬 한 의 🔁 🖬 💁 💁	නිස්" Get Data	Prog	am - 📄 🎟 🕈	1 海 川	🗣 🚺 Progra	am Test Be	ndh +					
Select Advanced Line de laters	ational coffs	<u> </u>	hider Fac	the ESC shield	a sufficient of the sufficient	en makin	n other chan	-				
W UTU Name	Terr	Cost 1	the rest of the second s	the coc this i	Description	en maion	g other chan	ges.	Palasted Vahida	Detected		
	remain	Corm S			Description		-		acteures remote	GREAT AND		
SHAESIZIUKL/S6993	_	2002	soullied				^	V2N	3HSDZTZR1LN864780			
JRAESICI 2REIGUG2/		1 1	ending Confin	mation								
SHAESTET /PLST6104		23	ending Confin	mation			_					
STALVIANDALU70240		100										
38486308121439557		4092	logitied									
SHCEUTANOFES24500		3					_					
3d5UCATESV86735V5	_						_					
387007276200484682		300	anding Confin	mation								
ADDRIVONADR111646		38	enoting Contin	1001200					CATERNATION.			
4DRB0C0N4PD111949		3	and in Confin				_		INTERNATION	22		
4DRDV-ONDEDVVD065	_	4 6	enoing contin	100 0100			_			/		
4DRDUCONOPDIIIP44	_	9	andina Candia				_			r		
eDRDUCONDFD100441		28	ending Confil	mation			_		V.			
4DRB0C8N8PB490910		13							- +			
4DKBOCON9PBI1/300		4					_					
4DRBOCSNXPS111941		5					_					
AIC_ISI_AI_I												
Detected Modules Inferred Modu	les Data Log						1.4	_	Selected Module	Detected		
T Module			Address	Data Link			Kernel	Description	ESC			
Stalk Shifter						×	56	Carriel	663010			
Switch Pack 2						×	25	Diama -	902010			
Switch Pack 1						×	25	Hardware	504			
Lighting Control Module						×	18					
Instrument Cluster						×	40449	Configuration	56			
Passenger Door Pod						×	202	Varial	246	11		
Front HVAC Control Modul	e					×	1945001	Normo	/35			
ESC				33 Drivetra	in J1939	×	735	Data Version	394	2		
								State	1			_
				You are	naw working only	w.		1	L			-44
Elours 2: Chack Current BC	MECC CA	dhunne I e	lasi	100 0 0								
Ham 1: Kernel Vertice		it ware Le										_
Item 2: Data Version												
Item 3: Update All Button												
Item 4: Program Button												
non a riogram pouoli												

5. Once updating is complete turn the ignition key off.

Door Motor Calibration Procedure

Note: Whenever a door motor is replaced or removed calibration should be performed.

- 1. Turn the key to the OFF position.
- 2. Manually close both fore and aft doors ensuring they are in the latched position.
- 3. Activate hazard
- 4. Hold high beam stalk shifter (hold stalk on)
- 5. Turn the key to the ON position.
- 6. Horn Beeps once sending request to the motor to recalibrate.
- 7. To confirm that the doors are calibrated, select DOOR OPEN and ensure the doors open fully. Select DOOR CLOSE and ensure doors completely close and latch.

WARRANTY INFORMATION

Warranty Claim Coding:

Refer to the Warranty Coding Manual for Group and Noun Codes.

Standard Repair Time(s):

Refer to the <u>SRT Manual</u> for Repair Times

OTHER RESOURCES

Master Service Information Site

Alide Details	Feedback Information	
	Viewed: 29	
	Helpful: 0	
	Not Helpful: 0	
No Feedback Found		

Copyright © 2025 Navistar, Inc.