

Technical Information Service 2025 ENU WSB4

WSB4 - Re-Programming External Communication Control Unit (Workshop Campaign)

Important: CRITICAL WARNING -This campaign includes steps where control unit(s) in the vehicle will be programmed

with the PIWIS Tester. The vehicle voltage must be maintained between 13.5 volts and 14.5 volts during this programming. Failure to maintain this voltage could result in damaged control unit(s). Damage caused by inadequate voltage during programming is not a warrantable defect. The technician must verify the actual vehicle voltage in the PIWIS Tester before starting the campaign and also document the actual voltage on the

repair order.

Model Year: As of 2019 up to 2021

Model Line: 911 (992)

Cayenne (9YA / 9YB)

Equipment: VTS preparation and Porsche Car Connect (PCC) (M-no. 7G9)

Oſ

Porsche Vehicle Tracking System Plus (PVTS Plus) (M-no. 712)

Concerns: External communication control unit

Cause: A software error in the external communication control unit can cause an increased closed-circuit current

under certain vehicle states and the 12V vehicle electrical system battery can therefore be discharged.

Action: Re-program the external communication control unit using the PIWIS Tester.



Information

The minimum programming requirement is the PIWIS Tester software release 43.200.040 (or higher).

Affected

Only vehicles assigned to the campaign (see also PCSS Vehicle Information).

Vehicles:

Required tools

Tools: P90999 - PIWIS Tester 4

Battery charger with a current rating of at least 90 A and a current and voltage-controlled charge map
for lithium starter batteries, e.g. VAS5908 battery charger 90 A. For further information about the
battery chargers to be used, see the corresponding Workshop Manual. ⇒ Workshop Manual '270689
Charging vehicle electrical system battery'

WSB4

Re-programming external communication control unit

Work Procedure: 1 Re-programme external communication control unit.

The basic procedure for control unit programming is described in the Workshop Manual ⇒ Workshop Manual '9X00IN Basic Instructions and Procedure for Control Unit Programming Using the PIWIS Tester'.

For specific information on control unit programming during this campaign, see the table below.

Required PIWIS Tester software release:	43.200.040 (or higher)
Type of control unit programming:	Control unit programming using the 'Campaign' function in the additional menu on the PIWIS Tester by entering a programming code.
Programming code:	АЗD7К
Programming sequence:	Read and follow the information and instructions on the PIWIS Tester during the guided programming sequence.
	During the programming sequence, the control unit is re-programmed and then re-codedautomatically.
	Do not interrupt programming and coding process.
	A backup documentation process for the re-programmed software releases starts once programming and coding is complete.
Programming time (approx.):	15 minutes
Software release of the Connect control unit to be programmed during this campaign:	Connect control unit Software release: 0423 (or higher)
	Upon completion of the control unit programming, the software release can be read out from the relevant control unit using the PIWIS Tester in the menu \Rightarrow 'Incremented identifications'.

Service

202

25	ENU	WSB4	

Procedure in the event of error messages appearing during the programming sequence:	⇒ Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester - section on "Troubleshooting".
Procedure in the event of a termination in the control unit programming:	Repeat control unit programming by re-entering the programming code.

Read out all **fault memories** process and delete existing faults if necessary.



Information

If control units are found to have faults that are not caused by control unit programming, these must first be located and corrected. This work cannot be invoiced under the workshop campaign number.

- Exit the diagnostic application. Switch off the ignition. Disconnect P90999 PIWIS Tester 4 from the vehicle.
- Switch off and disconnect the battery charger. ⇒ Workshop Manual '270689 Charging vehicle electrical system battery'
- Enter the campaign in the Warranty and Maintenance Logbook.

Warranty processing



Information

The specified labor times were determined specifically for carrying out this campaign and include all necessary preliminary and subsequent rework. The labor time may differ from the labor time published in the Labor Operation List in the PCSS.

Scope 1: Re-programming external communication control unit

911 (992)

Labor time:

Re-programming external communication control unit Includes: Connecting and disconnecting battery charger

Connecting and disconnecting PIWIS Tester Reading out and deleting fault memories

: ⇒ Damage code WSB4 066 000 1

Labor time: 49 TU

Technical Information

Labor time: 45 TU

Scope 2: Re-programming external communication control unit

Cayenne (9YA / 9YB)

Labor time:

Re-programming external communication control unit

Includes: Connecting and disconnecting battery charger

Connecting and disconnecting PIWIS Tester Reading out and deleting fault memories

⇒ Damage code WSB4 066 000 1

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.