

GENERAL MOTORS
DCS7191
URGENT - DISTRIBUTE IMMEDIATELY

Date: April 10, 2025

Subject: N242484500 - Service Update
Rear Door Latch Ajar Malfunction

Models: 2024 Chevrolet Silverado EV

General Motors is releasing Service Update N242484500 today.

What Should Dealers Do: Dealers should review IVH or the Dealer Maxis reports for open VINs in their inventory. Dealers can view the attached bulletin and it will also be displayed in Service Information tomorrow.

The Stock VIN list of vehicles in dealer inventory is attached to this message.
Note: this list is only accurate at the time of report creation and all VINs should be validated in IVH prior to repair.

END OF MESSAGE

Service Update

N242484500 Rear Door Latch Ajar Malfuction



Release Date: April 2025

Revision: 00

Attention: This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

For EV Involved Vehicles: The repairs outlined in this bulletin must only be completed at an authorized EV dealer and repairs must be performed by a technician who has successfully completed the applicable technical training required to perform this repair.

Make	Model	Model Year	
		From	To
Chevrolet	Silverado EV	2024	2024

Investigate Vehicle History (IVH) in the GM Global Warranty Management system should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	Certain 2024 Chevrolet Silverado EV WT vehicles may have a condition in which the left and right rear door wiring is defective and the rear door ajar warning will not function properly.
Correction	Dealers will replace the door harness.

Parts

Quantity	Part Name	Part No.
1	LH Rear Door Harness	85040674
1	RH Rear Door Harness	85040802

Reminder: Parts may be removed from SPRINT and Retail Inventory Management (RIM) and be non-returnable. Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect. There are a small number of vehicles anticipated that will need this fix. **Due to the limited initial parts availability, dealers are encouraged not to order these parts for use as shelf stock.**

Warranty Information

Labor Operation	Description	Labor Time	Trans. Type	Net Item
9107841	Inspect Only – No Further Action Required	0.2	ZFAT	N/A
9107842	Rear Side Door Wiring Harness Replacement (includes inspection)		ZFAT	N/A
	One Side	0.7		
	Both Sides	1.2		


Service Procedure

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

- Put the vehicle in service mode. To place the vehicle in service mode:
 - Ensure the vehicle is off, the driver door is open, and the brake pedal is not applied.
 - Press and release the accelerator pedal three times within five seconds, keeping the accelerator pressed on the third time.
 - The instrument cluster and infotainment systems will now turn on and operate normally, and you can release the accelerator pedal.

Service Update

N242484500 Rear Door Latch Ajar Malfunction



2. Open both rear doors, then check the instrument panel cluster (IPC) to see if the door ajar indicator is working for each of them.
 - If the IPC does NOT show both rear doors open, proceed to step 3.
 - If the IPC DOES show both rear doors open, no further action is required.
3. Vehicle off.
4. Replace the Rear Side Door Wiring Harness for whichever door(s) do NOT show as open. Refer to *Rear Side Door Wiring Harness Replacement* in SI.

Dealer Responsibility

Whenever a vehicle subject to this service update enters your vehicle inventory or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Pre-Owned (CPO), courtesy transportation vehicles, dealer shuttle vehicles, CarBravo, etc. in dealers' possession and subject to this field action must be held and inspected/repared per the service procedure of this bulletin before customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Pre-Owned (CPO) vehicles currently in the dealers' inventory within the SHIFT Digital system will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the SHIFT Digital system, or once again be used in the Courtesy Transportation Program.

Dealer Reports – For USA & Export

The Inventory tab of the Open Vehicle Report will contain Service Update Bulletin VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will not contain Service Update Bulletin VIN data because the intent of a Service Update Bulletin is to not inconvenience a customer with a special trip for service. Service Update Bulletins are to be completed when the customer is in for a regularly scheduled visit.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



**We Support
Voluntary Technician
Certification**