Bulletin No.: 24-NA-277

Date: March, 2025

TECHNICAL

Subject: Rear Seat False Latch Concerns

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox EV	2024	2025	-	-	All	All


Involved Region or Country	North America, Middle East, Israel, Palestine, Brazil (Mercosur), Chile (West), Colombia (West), Ecuador (West), Uruguay (West), Japan
Condition	Some customers may comment on the rear seat may become disengaged from striker without the function of the latch release handle.
Cause	The cause of the condition may be the red latch indication flag drops (not visible) prior to full engagement/latch function of seatback latch to striker. Thus, falsely indicating full latch function of seatback latch.
Correction	Technicians are to uniformly grind front face of metal striker to specified dimension to enable proper latching.

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Service Procedure

1. Verify Seat Latch Condition – A false latch condition exists when the red latch indication flag drops without full latch function of seatback latch to striker. When in a false latch condition, seatback latch can disengage from striker without functioning the seat latch release handle.

Page 2 March, 2025 Bulletin No.: 24-NA-277



6791542


- 1.1. Measure the striker with calipers or micrometer at three points (as seen in image above).
- 1.2. If striker is larger than 10.7mm, rework to body procedure (Begin Step 2).
- 1.3. If the striker is not larger than 10.7mm, Replace Seat, Contact TAC, and Submit FPR.



6791543

- 2. Fold the seats down and place a covering on the floor to catch the metal shavings.
- 3. Begin grinding the striker front surface using an appropriate cutting wheel with a safety guard affixed to it. **Note:** It is important to be wearing the appropriate PPE during this procedure.

Bulletin No.: 24-NA-277 March, 2025 Page 3



6791545

- 3.1. Rework the striker to a uniform dimension of 10.35-10.6 (target 10.5 mm).
- 3.2. Check dimension frequently while grinding. (Check at same three points as step 1)
- 4. Remove any sharp edges. Use touch-up paint to blend the reworked surface according to the body color. (May have to order touch-up paint to match body color)
 - 4.1. After paint blending, Re-measure striker (Check at same three points as step 1).
 - 4.2. Striker must be not larger than 10.7mm.



6791546

- 5. Verify false latch concern is resolved push seat back until red lock indication flag drops (not visible). Seatback latch must not be able disengage from striker without the function of the latch release handle.
 - 5.1. If not resolved, Replace Seat, Contact TAC, and Submit FPR.
 - 5.1.1. Once seat is replaced, Verify false latch concern is resolved (Repeat step 5).

Page 4 March, 2025 Bulletin No.: 24-NA-277

Parts Information

No parts are required for this repair.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time			
*7086098	Rear Seat Striker Rework	0.2 hr			
*This is a unique Labor Operation for Bulletin use only.					

Version	2
Modified	Released December 20, 2024
	Revised March 11, 2025 – Updated Step 3 to inform to use proper safety measures.