



Service Bulletin

Bulletin No.: 25-NA-051
Date: March, 2025

TECHNICAL

Subject: Tire Pressure Monitoring Sensor (TPMS) Intermittent Signal Loss

Brand:	Model:	Model Year:		Build Date:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Blazer EV	2025	2025	SOP	October 17, 2024		
	Equinox EV			September 19, 2024	November 28, 2024		

Involved Region or Country	North America, Middle East, Israel, Palestine, Brazil (Mercosur), Chile (West), Colombia (West), Ecuador (West), Uruguay (West)
Condition	Some customers may comment on the TPMS light is on. - Some customers may notice that one out of the four tire pressure sensors are not reading a PSI status.
Cause	This condition may be caused by a parts quality issue found with the TPMS sensors.
Correction	Customer may be returning for a repeat visit with the same issue on the other sensors. Dealers are to replace all four TPMS sensors instead of just the one inoperative sensor.

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Service Procedure


Refer to *Tire Pressure Indicator Sensor Replacement*.

TPMS Information



6857497

The TPMS sensor p/n location is shown in the graphic above.



6857495

Remove the sensor that is exhibiting the above concern and check the p/n on the sensor.

- If the p/n is 13542674, replace the sensor and all other sensors with p/n 13556202.
- If the p/n is 13556202, refer to normal SI diagnostics.

The graphic above shows one other way to identify if the TPMS sensor, the old part is stamped with a 40 (1) and the new part is stamped with a 4 (2).

Parts Information

Note: Follow the procedure in SI for additional parts that may be required for the repair.

Causal Part	Description	Part Number	Qty
X	SENSOR ASM-TIRE PRESS IND	13556202	4

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
8050190	Tire Pressure Indicator Sensor Replacement	Use the Published Labor Operations Time

Version	1
Modified	Released March 12, 2025

