

Technical Service Bulletin (TSB)

Right Front Heated Seat Inoperative

REFERENCE:	TSB: 08-111-25 GROUP: 08 - Electrical	Date:	April 9, 2025	REVISION:	_	
VEHICLES AFFECTED:	2025 (WL) Jeep Grand Cherokee/ Grand Cherokee L This bulletin applies to vehicles built on or after October 17, 2024 (MDH 1017XX) and on and before October 25, 2024 (MDH 1025XX) equipped with Heated Front Seats (Sales Code JPM).			MARKET AP	PLICABILITY: MEA IAP CH	
CUSTOMER SYMPTOM:	 Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must exhibit/set the following Diagnostic Trouble Code (DTC): B1E9A - Front Right Heater Control 1 – Circuit Open. Customers may experience the following: Right front heated seat will not activate or will shut off after a few seconds. 					
CAUSE:	Damaged harness connector					

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 25-059, date of issue April 09, 2025. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin involves inspecting and possibly repairing the heated seat harness connector.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
23-20-38-9A	Inspect Harness Connector (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.2 Hrs.
23-20-38-9B	Inspect And Repair Harness Connector (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.6 Hrs.
Failure Code	ZY	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1 (AR)	68502132AA	24 Way - Female Wiring	
		Kit	

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If Diagnostic Trouble Codes (DTCs) or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTech or equivalent		Essential Tool

REPAIR PROCEDURE:

- 1. With the vehicle ignition on, open the right rear door.
- 2. Under the front passenger seat, disconnect inline connector XY444A and inspect pin 18 for a spreading condition Fig 1, Fig. 2.




Fig. 1 XY444A Harness Connector Location



0-0-	Circuit	Color	Spec	Cavity Plug	Town Start	Out-
Cavey	-					
1			5ABT-0.35			LBW && 58
2	P8590_1	-	5ABT-0.35		SN	CAJ && (JWA JWG)
2	P8590_2	GY/GN	5ABT-0.35		SN	CAJ && JNJ
3	P857F	GN	5ABT-0.35		SN	JPM
4	P158D	06/06	SABT-0.75		SN	LES [SJH
5	G504D	BNYE	5ABT-0.35	-	SN	LE5
6	P988M	GNBG	SABT-0.35		SN	LES
7	P856D	BG/GN	5ABT-0.35		SN	JPM
8	D367CP	WH	SABT-0.35		SN	CES
9	D368CQ	DB/WH	5ABT-0.35		SN	CES
10	P7508	GN	5ABT-0.35		SN	CES
11	P1718	GNVT	5A8T-0.35		SN	(1 CE5 && JWG && 58) (1 CE5 && JWG && 59) (1 CE5 && JWJ && 58) (1 CE5 && JWJ && 59
12	P1738	GNYE	5ABT-0.35	-	SN	(1 CE5 && JWG && 58) (1 CE5 && JWG && 59) (1 CE5 && JWJ && 58) (1 CE5 && JWJ && 59
13	A356L	RDIYE	CABT-0.5		SN	CES
14	P42C	GNIGY	5A8T-0.75	-	SN	(1 LE5 && 1 SJH && JWG && 58) (1 LE5 && JWG && 59)
15	F521CQ	YE/PK	SABT-0.35		SN	LBW && 58
16	P2308_1	GNBK	5ABT-0.35		SN	CAJ && (JWA JWG)
16	P2308_2	GNBK	SABT-0.35		SN	CAJ 86 JWJ
17	P1560	GNDG	5AUT.0.75		SN	LES I SJH
18	P853D	GNYE	SABT-0.75	-	SN	LEAN CONTRACT
19	UB32AJ	W75874	5481-0.35		SN	LBW && LBZ && 58
20	P854D	GN/OG	SABT-0.75		SN	JPM
21	P44C	GNVT	5ABT-0.75	-	SN	(1LE5 88 1 SJH 88 JWG 88 58) (1LE5 88 JWG 88 59)
22	2920BC	BK	CABT-10		5N	CAUAA URW AA SELUCCAUAA URW AA SELUCES

Fig. 2

- 3. Is Terminal 18 spread?
 - YES>>> Proceed to Step 6.
 - NO>>> Proceed to Step 4.
- 4. Reconnect XY444A and wiggle test and push-pull-push the connector while monitoring for DTC B1E9A to set.
- 5. Did DTC B1E9A set?
 - YES>>> Proceed to Step 6.
 - NO>>> This bulletin does not apply. Use Inspect LOP (23-20-38-9A) to close this active RSU.
- 6. Repair terminal 18 using kit 68502132AA.
- 7. Clear any DTC's.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.