

Technical Journal

TITLE:

Coolant System Filling

REF NO: TJ 37301.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7515 Polestar		ISSUE DATE: 2025-03-13	STATUS DATE: 2025-03-19
FUNC GROUP: 2600	FUNC DESC: Cooling system	Page 1 of 2	

DESCRIPTION:

If filling of coolant is required or the coolant system is drained during a repair, follow advice under "Service".

CSC Customer Symptom Codes

Code	Description
53	Driving, Twin Engine/Propulsion using electric motor not possible
AJ	Driving/Poor performance/lacks power
AP	Idling/Engine stalls/Unsure when/at all times
AU	Engine cooling/Engine overheats/runs hot
DL	Warning lights and chimes/Malfunction Indicator Light ("Check engine" light) indication/no indication
Q8	Engine cooling/Coolant leakage

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
FIOC	P2BE017	Permanent

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
359							2025-9999		-	202402-999952

Technical Journal 37301.1.0

SERVICE:

If for any reason the coolant system is drained and needs to be topped off, follow VIDA instructions when doing so:

Cleaning, inspection and adjustment >> 261: Radiator and connections >> Cooling system, electric powertrain, filling, and bleeding

For *Polestar 3* vehicles, there is currently no DIM message displayed for low coolant level. Hence, it is of utmost importance to use the correct filling equipment when needed to ensure that the amount of coolant is correct and to avoid any issues related to low coolant levels.

A solution for this is planned for Quarter 4, 2025.

Warranty claim info:

No warranty claim is accepted for this TJ.

LABOR TIME:

Labor time subject to change without notice.

VEHICLE REPORT:

N/A