

#### SIB 64 04 25

2025-04-01

# HARNESS DAMAGE POSSIBLE WHILE CHANGING CABIN NANOFILTER

This Service Information Bulletin (Revision 1) replaces SI B64 04 25 dated March 2025.

What's New (Specific text highlighted):

- M5 models added
- Pictures added to Procedure

$\boxtimes$	THIS REPAIR IS MOBILE FRIENDLY
	THIS REPAIR IS REMOTE SOFTWARE UPGRADE (RSU) FRIENDLY

## **MODEL**

E-Series	Model Description
G60	5 Series Sedan
G70	7 Series Sedan
G90	M5 Sedan
G99	M5 Touring

# **SITUATION**

The following air flap and/or air temperature sensor faults are stored in the BCP.

- 80114D Stepper motor: Unexpected error in Driving Cycle
- 801168 Temperature sensor ventilation left or ventilation: short to ground
- 80116A Temperature sensor ventilation right: short to ground
- 80116B Temperature sensor ventilation right: short to plus or open circuit
- 80116C Temperature sensor footwell left or footwell: short to ground
- 80116D Temperature sensor footwell left or footwell: short to plus or open circuit
- 80116E Temperature sensor footwell right: short to ground
- 80116F Temperature sensor footwell right: short to plus or open circuit
- 80435B Stepper motors: short-circuit by mass


#### CAUSE

When servicing the cabin air microparticle nanofilter, it is possible to damage the vehicle's wiring harness while re-installing the retaining screws for the cabin air nanofilter's plastic cover.

### CORRECTION

Use caution when re-installing the plastic cover for the cabin air filter to ensure no damage is done to the vehicle's wiring harness.

## **PROCEDURE**



When following Repair Instructions REP **64 31 010** to change the cabin air nanofilter, check the vehicle wiring harness routing (circled) before fastening the plastic cover over the filter.




This is where the harness can be damaged when installing the cabin air filter cover screw.



This shows the harness damage; the sheathing has been abraded.



With the harness pulled out of the way, you can see the screw mounting hole for the cabin air filter cover



Double check the routing of the harness prior to installing the screws for the cabin air filter cover.

If the wiring harness has already been damaged during the installation of the cabin air filter cover, the damaged section of the wiring harness must be repaired.

## **CLAIM INFORMATION**

This Service Information Bulletin provides technical, and repair procedure-related information.

Damage and/or issues caused by outside influences are not covered under the BMW limited warranties.

## FEEDBACK REGARDING THIS BULLETIN

Technical Feedback	To submit feedback for the technical topic of this bulletin: Submit your		
recillical reeuback	feedback in the rating box at the top of this bulletin		
	To submit feedback for the CLAIMS section of this bulletin: Submit an IDS		
Warranty Feedback	ticket to the Warranty Department, or use the chat available in the		
	Warranty Documentation Portal		
Dorto Foodbook	To submit feedback for the PARTS section of this bulletin: Submit an IDS		
Parts Feedback	ticket to the Parts Department		