

**RAPID UPDATE**

FROM: Maserati TSO

TO: Maserati Network



**Maserati**

PERSONAL SERVICE LAB

MASTERS OF CARE

# Rapid Update 735

## Grecale – Electric Absorption Improvement

### BCM – RFHM – SLML – SLMR Software Updates



DATE: April 9, 2025

Certain Maserati Grecale (M182) MY23 MY24 MY25 listed in MODISCS+ are involved in a Rapid Update to update the software in several modules to improve electrical absorption.

This electric absorption improvement can be reached by updating the following modules all in one shot:

- BCM (Body Control Module)
- RFHM (Radio Frequency HUB Module)
- SLML (Smart Lighting Module Right)
- SLMR (Smart Lighting Module Left)

We remind you that all the Rapid Updates must be performed within the first workshop visit, regardless of the Mandatory setting set in Modis, as required by Maserati policies.

Also, for vehicles in Stock Dealer / PDI, it is necessary to carry out all action operations before delivery to the end customer, as required by the White Book and explicitly reported in the Pre-delivery checklist.

**Please read and review this bulletin first before ordering parts and/or starting the procedure.**

Contact your Regional AfterSales Manager (RAM) or the Technical Support Helpdesk if you have any questions.

Thank You for your continued support and cooperation.

Maserati North America  
Aftersales Dept.

# Overview

Software version to be installed (or newer).

ECU	Market	F188 Target
BCM	ROW	670354211
RFHM	ROW	670353736
SLML + SLMR	ROW	670355878

**NOTE: the claim submission is a self-declaration that all the 4 modules listed are updated at the SE closure.**

## Technical Procedure



All images shown in this bulletin are for illustrative purposes only

1. Always check ModisCS+ to see if the vehicle is involved in this action and if it has not been previously performed.
2. Please ensure the following preconditions are met before starting:
  - a. **Battery voltage > 12.5V (It is recommended to always use the E-XTEQ MAXIMUS to maintain minimum voltage and current draw requirements).**
  - b. **Key ON and Engine OFF**
  - c. **Vehicle parked.**
3. Using MD-EVO, perform software updates on the 4 ECUs below:
  - From ECU View, select the **BCM – ECU programming**
  - From ECU View, select the **RFHM – ECU programming**
  - From ECU View, select the **SLML – ECU programming**
  - From ECU View, select the **SLMR – ECU programming**
4. After completing the software updates on all ECUs, perform **BCM – Procedures – PROXI Alignment**.
5. **After the PROXI alignment, only for BEV vehicles, please follow the following procedures:**
  - **Close the MDEVO application and disconnect the MDVCI2**
  - **Disconnect the 12V Battery Maintainer from the 12V Battery**
  - **Perform the Key OFF**
  - **Make sure that the hood, the trunk and all the doors are properly closed**
  - **Wait for the power latch (wait until the dashboard clock turns off)**
  - **NOTE: allow the car to sleep for ten minutes**
  - **Reconnect the 12V Battery Maintainer to the 12V Battery**
  - **Perform the Key ON**
  - **Reconnect the MDVCI2, restart the MDEVO application and clear DTCs from the ECU View**
  - **Perform the Ignition Cycle (Key OFF and Key ON)**
6. Procedure complete.

Warranty Claim

Fill in the relative Warranty Claims as follows:

Description	Code
Number	735
Warranty Code	23
Fault Code	063
Component Code	9.99.000
Operation Code	9.99.000.A (0,40h)