



SIB 12 04 25

2025-04-25

DELIVERY STOP: PROGRAM CONTROL UNITS

This Service Information Bulletin (Revision 1) replaces SI B12 04 25 dated April 2025.

What's New:

- Situation revised
- Cause added
- Correction added
- Procedure added
- Claim Information added

MODEL

E-Series	Model Description	Production Date
F95	X5 M Sports Activity Vehicle	June 13, 2022 – November 29, 2023
F96	X6 M Sports Activity Coupe	February 28, 2022 – November 30, 2023
G05	X5 Sports Activity Vehicle	February 16, 2022 – March 29, 2025
G06	X5 Sports Activity Coupe	March 24, 2022 – November 30, 2023
G07	X7 Sports Activity Vehicle	July 21, 2021 – November 30, 2023
G09	XM Sports Activity Vehicle	September 30, 2021 – April 11, 2025
G60	5 Series Sedan	July 26, 2022 – February 25, 2025
G70	7 Series Sedan	July 23, 2021 – April 11, 2025
G90	M5 Sedan	January 18, 2023 – February 25, 2025
G99	M5 Touring	July 4, 2023 – April 10, 2025
U10	X2 Sports Activity Coupe	August 14, 2023
U11	X1 Sports Activity Vehicle	July 12, 2021 – January 19, 2023

AFFECTED VEHICLES

Vehicles which require this campaign to be completed will show it as “Open” when checked either in AIR, AWP, Campaign Summary or Warranty Vehicle Inquiry.

Please make sure you check your dealer inventory as soon as possible. As of April 25, 2025, you can see a list of affected vehicles in Inventory Campaign Details (ICD) under ROSS.

SITUATION

BMW AG has issued a Delivery Stop (effective April 24, 2025) on certain Model Year 2023 - 2025 BMW vehicles that were produced between July 12, 2021, and April 11, 2025.

Do not deliver to a customer, a New, Certified Pre-Owned or Used vehicle subject to a Delivery Stop, until the vehicle is repaired. Do not use or sell replacement equipment/parts subject to a Delivery Stop.

As a result of a data input error, certain fault memories are permanently stored. The permanent storage of fault memories does not comply with the legal specifications of the authority (California Air Resources Board – CARB).

The fault has no effect on the use of the vehicle by the customer.

CAUSE

Software error.

CORRECTION

Program the control units.

PROCEDURE

Determine what is the vehicle's current I-level by either using AIR or the Key Reader/Aftersales Workplace (AWP) application.

RSU and programming procedure:

It must be checked whether the customer has already downloaded the required software in the vehicle via Remote Software Upgrade (**RSU**) but has not yet installed it. In this case, programming must be carried out via **RSU** as described under **point A**.

A detailed description of the procedure can be found in the dealer portal (**COMPASS article 80383**).

A. Check whether programming via RSU is possible

If the requirements listed below are met, the processing of the technical campaign must be carried out via RSU.

Check the available RSU offering either via ConnectedDrive Dealer Cockpit or directly in the vehicle in the app.

I. Check the available RSU offering in the vehicle app

1. Open the "System Settings" vehicle app and select "Remote Software Upgrade".
2. The version of the software that is currently installed in the vehicle is shown in the upper area. The version of the software that will be installed in the vehicle via Remote Software Upgrade is also displayed.
3. If the **software version to be installed is 03/2025.47** or higher, start the RSU installation in the vehicle and follow the instructions in the vehicle. If the software version to be installed is lower, proceed with point B "Programming via ISTA".
4. After approx. 30 minutes, you must check in the vehicle whether the RSU installation has been carried out successfully and that at least **software version 03/2025.47** has been installed.
5. Activate the drive-ready state. To do this, actuate the Start/Stop knob while applying the brake pedal.

II. Check the available RSU offering via the ConnectedDrive Dealer Cockpit

1. Select the vehicle in the ConnectedDrive Dealer Cockpit by entering the 17-digit vehicle identification number.
2. In the **Standard Connectivity** menu, select the "Remote Software Upgrade" item (scroll through the menu if necessary).
3. Open "Remote Software Upgrade".
4. Select the "Current Upgrade" tab.
5. Check whether the available I-level corresponds to the I levels specified under point B or higher I levels.
6. Check whether this I-level is ready for installation.
7. If the I-level to be installed is correct, start the RSU installation in the vehicle and follow the instructions in the vehicle. If the I-level to be installed is lower, proceed with point B "Programming via ISTA".
8. Exit and lock the vehicle.
9. After approx. 30 minutes, you must check in the vehicle whether the RSU installation has been carried out successfully and that at least **software version 03/2025.47** has been installed.
10. Activate the drive-ready state. To do this, actuate the Start/Stop knob while applying the brake pedal.

Notice:

If Check Control messages (CCM) are displayed in the vehicle after successful installation, let the vehicle go to sleep and then check whether the specified I-level or a higher I-level has been installed.

It is recommended to exit and lock the vehicle during installation. Make sure that no device is connected to the on-board diagnosis connector (e.g. ICOM). No further interaction is required during installation.

The vehicle requires no connectivity as the software has already been downloaded. This means that the vehicle can also be parked in an underground car park, for example.

B. Programming via ISTA

- Connect the battery charger to the vehicle
- Connect the programming system to the vehicle (ISTA 4)
- Determine the measures plan
- Accept or work through the entire measures plan with the control units to be programmed/encoded and, if necessary, activated
- Follow the rework list
- Depending on the rework list, carry out a vehicle test and delete the fault memory, if required

ISTA 4.53.1x with installed service data package is required for the programming/encoding.

The fault elimination is included from the following I-level versions:

- I level **S18A-25-03-547** or later (available from ISTA 4.53.1x, publication planned from 4-25-2025)
- I level **G070-25-03-547** or later (available from ISTA 4.53.1x, publication planned from 4-25-2025)
- I level **U006-25-03-547** or later (available from ISTA 4.53.1x, expected publication from 4-25-2025 onwards)

The programming must be carried out using the I levels given above or a later one! Please observe the information regarding programming in the workshop system and the corresponding notes in the user documentation.

CLAIM INFORMATION

During this workshop visit, the affected vehicle may also show one or more programming and encoding Technical Campaign repairs open. The programming and encoding procedure may only be invoiced one time.

Select this open Technical Campaign to perform and submit for updating the vehicle to the required I-level or higher instead when applicable (this includes 00 00 006 or 00 00 556, 61 21 528, and 61 00 730).

Please be sure to also perform any additional before and/or after work (including attaching labels) as required by the open campaigns on the vehicle. Close any other open programming and encoding Campaign repairs as outlined in the corresponding Service Information Bulletin.

As determined by the above, reimbursement for this Action will be via normal claim entry by selecting and submitting for the work package information below that applies.

Plusposition (+)	Completion before the first vehicle delivery to a customer (New in-stock/No in-service date), or the vehicle is already in the workshop for another reason and/or repair, identified by the “ (Plusposition) ” reference in the descriptions below.
Main work	The vehicle arrives for this Action, no other Main work will be performed/claimed during this workshop visit, identified by the “ (Main work) ” reference in the descriptions below.

Below are the special flat rate labor operation code choices for this action.

Repair Code:	0099770200	Gx F9x U1x Program control units
---------------------	-------------------	---

Remote Software Upgrade (RSU) Status - Ready to be Installed.

Work Package	Labor Operation	Description	Labor Allowance
# 1	00 78 573	Remote Software Upgrade performed (Plusposition)	2 FRU

Or:			
# 2	00 78 061	Remote Software Upgrade performed (Main work)	3 FRU

Or:

Vehicle Programming and Encoding

Work Package	Labor Operation	Description	Labor Allowance
# 3	00 78 572	Programming and encoding the vehicle control units, includes Carrying out vehicle test (00 00 556/61 21 528) (Plusposition)	As applicable
Or:			
# 4	00 78 060	Programming and encoding the vehicle control units, includes Carrying out vehicle test (00 00 006/61 21 528) (Main work)	As applicable

Or the:

Vehicle is already at the Specified Target Integration Level or Higher

Work Package	Labor Operation	Description	Labor Allowance
# 5	00 78 574	Either in conjunction with another campaign/repair prior to or during this workshop visit (The RSU is excluded) , the vehicle is already at the specified Target integration level or higher, no repair is necessary (Plusposition)	1 FRU
Or:			
# 6	00 78 062	Either in conjunction with another campaign/repair prior to or during this workshop visit (The RSU is excluded) , the vehicle is already at the specified Target integration level or higher, no repair is necessary (Main work)	1 FRU

Only one of the flat rate labor operation codes listed above can be used for claim submission/reimbursement purposes. Also, only one Main work flat rate labor operation code can be claimed per workshop visit.

Claim Repair Comments

Reference the SIB number, the issue (briefly), and the work package (WP) number performed in the technician's RO notes, and in the claim comments (For example: B12 04 25 SW update WP 3), unless otherwise required by State law.

BMW Group's AIR Application Resource for Flat Rate Labor Operation Codes

To obtain the corresponding flat rate unit (FRU) allowance information from the BMW Group AIR application resource, start by entering the Chassis Number (last seven (7) characters of the VIN), and click on the "Search" icon. If the "Vehicle Selection" window displays two or more model possible vehicle choices, select the applicable Model or enter the full VIN (17 characters) instead to proceed. Click on the "Flat Rate Units" link.

Copyright ©2025 BMW of North America, Inc.

button and enter a flat rate labor operation code number “without spaces” in the field to the right, click on the “Search” icon to display the corresponding listing of “Flat rate unit group details” that are available and their corresponding FRU allowances.

Programming and Encoding – Additional Work (RO and Claim Comments Required)

This procedure automatically reprograms and encodes any vehicle control modules that do not have the latest software I-level.

If one or more control modules fail during the reprogramming procedure, claim the required consequential repair work procedures to address this issue (including performing the IRAP Control Unit Recovery first as required, refer to the SIB in AIR) under the Repair Code in this bulletin together with the corresponding labor operation codes and their flat rate unit (FRU) allowance(s), including the diagnosis* that applies.

Please explain the additional work procedures that were performed (The why and the what) on the repair order and in the claim comments.

For covered repairs that addresses preexisting control module failures that occurred prior to performing this repair-related programming and encoding procedure, claim this work with the Repair Code listed in AIR together with the corresponding labor operation codes and their flat rate unit (FRU) allowance(s), including the diagnosis* that applies.

(*) Based on which one applies to your center, please refer to **SI B01 01 20** or **B01 07 20** for the applicable procedure for documenting, claiming, and explaining, on the RO and in the claim comments, your diagnosis work time (WT), job/repair work time (WT), and the vehicle repairs your center performed, unless otherwise required by State law.

FEEDBACK REGARDING THIS BULLETIN

Technical Feedback	To submit feedback for the technical topic of this bulletin: Submit your feedback in the rating box at the top of this bulletin
Warranty Feedback	To submit feedback for the CLAIMS section of this bulletin: Submit an IDS ticket to the Warranty Department, or use the chat available in the Warranty Documentation Portal
Parts Feedback	To submit feedback for the PARTS section of this bulletin: Submit an IDS ticket to the Parts Department

