

April 18, 2025

Version 4

## Warranty Extension: 2017–18 RDX 6AT Torque Converter – DTC P0741 Stored

Supersedes 23-029, dated February 26, 2024, to revise the information.

### AFFECTED VEHICLES

Year	Model	Trim Level	VIN Range
2017–18	RDX	ALL	Check iN VIN status for eligibility.

### REVISION SUMMARY

Under BACKGROUND INFORMATION, warranty extension changed to 10 years or 150,000 miles

### BACKGROUND

The lock-up clutch cannot provide adequate holding force due to pressure bleeding down through a crack in the lock up piston. The reduced lock-up clutch capacity results in the transmission indicator flashing “D” and set DTC P0741 Torque Converter Clutch Circuit Performance or Stuck OFF.

Acura is extending the warranty of the torque converter as a result of this issue for 10 years or 150,000 miles from the original date of purchase, whichever comes first.

### CLIENT NOTIFICATION

Owners of affected vehicles will be sent a notification of this campaign.

Do an iN VIN status inquiry to make sure the vehicle is shown as eligible

### CORRECTIVE ACTION

Check the vehicle for DTC P0741, if DTC P0741 is set, replace the torque converter.

**CLIENT INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by “do-it-yourselfers,” and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.

**PARTS INFORMATION**

<b>Part Name</b>	<b>Part Number</b>	<b>Quantity 2WD</b>	<b>Quantity AWD</b>
Torque Converter Kit	06260-R9R-000	1	1
Flange Bolt (10x30)	90163-SDB-A00	3	3
12 Point Bolt (8x21)	90113-S10-000	0	8
Flange Bolt (10x29)	90382-SH9-003	0	2
Flange Bolt (10x35)	90163-SDA-A01	2	2
Washer Bolt (10x25)	90167-SAA-010	2	2
Flange Nut (12mm)	90371-SEF-000	4	4
Flange Bolt (12x40)	90164-S5A-010	3	3
Flange Bolt (10x35)	90161-TP1-A00	3	3
Flange Bolt (12x18)	90018-SNA-010	2	2
Self Lock Nut (12mm) (Clinch) (Sato Rashi)	90215-SB0-003	4	4
Flange Bolt (10x20)	90163-S5A-000	2	2
Flange Bolt (14x130)	90175-SNA-A00	2	2
Flange Bolt (12x70)	90051-R97-000	2	2
Flange Bolt (14x150)	90177-SDA-A00	2	2
Flange Bolt (12x33)	90186-SDA-A00	2	2

**REQUIRED MATERIALS**

<b>Part Name</b>	<b>Part Number</b>	<b>Quantity 2WD</b>	<b>Quantity AWD</b>
ATF DW-1	08200-9008A	5	6

## WARRANTY CLAIM INFORMATION

### 2017-18 RDX (2WD)

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
2181BM	Replace the torque converter. (Includes DTC clear and alignment)	6.3 hr	6T800	OFM00	B23029A	26000-R9R-305

### RDX (AWD)

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
2181BM	Replace the torque converter. (Includes DTC clear and alignment)	6.6 hr	6T800	OFM00	B23029B	26000-R9R-315

Skill Level: Repair Technician

## INSPECTION PROCEDURE

1. Check the vehicle for DTC P0741.
  - If DTC P0741 is set, go to the REPAIR PROCEDURE.
  - If DTC P0741 is not set, this service bulletin does not apply; continue with normal troubleshooting.

## REPAIR PROCEDURE

1. Replace the torque converter assembly. Refer to the service information in the Search field, type in automatic transmission removal and installation, then select Automatic Transmission Removal and Installation.
2. After completing the torque converter replacement, check the automatic transmission fluid level.

Automatic Transmission Fluid capacity 2WD:

**4.5L (4.8 US qt)** at torque converter replacement.

Automatic Transmission Fluid capacity AWD:

**5.2L (5.5 US qt)** at torque converter replacement.

**COLD CHECK**



**HOT CHECK**



3. Check the ATF temperature when greater than or equal to **80 degrees C (176 degrees F)**.
  - If the fluid level is checked at a colder temperature, it will read low or on the bottom dot of the dipstick.
  - If the transmission fluid is filled to the top dot when cold, the transmission will be overfilled, increasing foaming and contributing to the overheating problem.