

GROUP	NUMBER
ENGINE ELECTRICAL	25-EE-002H
DATE	MODEL(S)
APRIL 2025	SONATA (DN8/DN8A)

SUBJECT: MULTI-FUSE REPLACEMENT & BLOWER WIRING REPAIR

Description: Certain Sonata (DN8) and Sonata (DN8A) vehicles may experience issues with the air conditioning due to damaged wiring in the engine room junction box. This bulletin provides instructions to replace the multi-fuse, reroute the damaged wiring using the blower wiring kit, and replace the fuse label.

Applicable Vehicles:

- 2021-2023MY Sonata (DN8) produced from 02/08/2021 09/15/2022 (VIN starts with 'KMH')
- 2020-2022MY Sonata (DN8A) produced from 10/22/2019 02/17/2022 (VIN starts with '5NP')

Parts Information:

Model	Part Name	Part Number	Figure	Remarks	
	Multi-fuse	18980-09910FFF		Qty: 1	
Comete			C. Retainer (relay unit) RBL04-02465		
Sonata (DN8/	Blower Wiring Kit 91200-L1000FFF			B. Wiring terminal	
DN8A)		91200-L1000FFF		(relay unit)	
				D. Fuse label 50A	

Required Equipment/Supplies:

Name	Equipment/Supply #	Figure	Remarks
Insulating Tape	N/A		Standard shop supply

Warranty Information:

Model	Op. Code	Operation	Op. Time	Causal Part	Nature Code	Cause Code
Sonata (DN8/DN8A)	91200F06	Multi-Fuse Replacement & Blower Wiring Repair	0.7 M/H	91215-L1020	l41	ZZ3

NOTE 1: Normal warranty applies.

NOTE 2: Submit claim on Claim Entry Screen as "Warranty" type.

NOTE 3: Take a picture of the warrantable defect. Op times include VIN, Mileage, and Repair validation photo(s) as outlined in the Digital Documentation Policy.

NOTE 4: The incident parts are subject to callback through the normal Warranty Technical Center (WTC) parts return process. **Claim is subject to debit if the part is not returned.**

NOTE 5: If a part is found in need of replacement while performing this TSB and the affected part is still under warranty, submit a separate claim using the same repair order. If the affected part is out of warranty, submit a Prior Approval request for goodwill consideration prior to performing the work.

TSB #: 25-EE-002H Page 2 of 10

Service Procedure:

DIGITAL DOCUMENTATION



This TSB includes Repair justification photos. Refer to the latest Warranty Digital Documentation Policy for requirements.

- Verify if the blower fuse and terminals are discolored.
 - If either the blower fuse and/or terminals are discolored, then proceed with the service procedure.
 - If the blower fuse and terminals are <u>NOT</u> discolored then this TSB does <u>NOT</u> apply. Continue with a normal diagnosis.




2.

DIGITAL DOCUMENTATION



Using STUI, take a photo of the discolored blower fuse and/or terminals with the last 6 digits of the VIN and the date of repair on a piece of paper.

Upload the photo to STUI.



TSB #: 25-EE-002H Page 3 of 10

- 3. To remove the air duct and air cleaner assembly, refer to the shop manual:
 - Engine Mechanical System >Intake and Exhaust System > Air Cleaner > Repair procedures

To remove the battery and battery tray, refer to the shop manual:

 Engine Electrical System > Charging System > Battery > Repair procedures


Remove the following parts:


- engine room junction box connector
- terminals
- 2 multi-fuse
- band cable (A)




Information

Modified fuses (18980-09910) are replaced with new ones, while reused fuses (18980-09920) remain in place.










TSB #: 25-EE-002H Page 4 of 10

4. Remove the mounting bolt (B) and nut (C) of the junction box.






5. Use the remover tool to remove the junction box (D).



TSB #: 25-EE-002H Page 5 of 10


6. Lift up and remove the junction box (E).



7. Cut two band cables (F) and remove the insulating tape (G).


Remove the back cover of the junction box.







TSB #: 25-EE-002H Page 6 of 10

8. Remove terminal 13 (H) from the blower motor relay (female terminal, 4 pins).






9. Cut the wiring from the removed terminal and wrap the remaining harness securely using insulating tape (I).




TSB #: 25-EE-002H Page 7 of 10


10. Install the supplied wiring terminal from the kit into the connector (J).



TSB #: 25-EE-002H Page 8 of 10

11. Install the multi-fuse air terminal with the other side of the supplied wire terminal, ensuring proper installation between the white and orange wires (K).









TSB #: 25-EE-002H Page 9 of 10

12. Place the Blank label over the existing 40A label in the red dotted area below in step 13. Place the 50A label in the blue dotted area (currently no label) below in step 13.



13. Reinstall parts in the reverse order of the removal. Current routing before cutting and rerouting after cutting (L).



- 14. Confirm air conditioning is working.
- 15. The service procedure is now complete.

TSB #: 25-EE-002H Page 10 of 10