# Technical Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



Subject:

DIFFICULT TO OPEN/CLOSE FUEL-FILLER LID

Bulletin No.: 09-017/25

Last Issued: 04/07/2025

#### **BULLETIN NOTES**

This bulletin supersedes the previously issued bulletin(s) listed below. The changes are noted in Red text.


| Previous TSBs: | Date(s) Issued: |
|----------------|-----------------|
| 09-032/21      | 11/05/21        |


# APPLICABLE MODEL(S)/VINS

2019-2021 Mazda3 (Japan built) with VINS lower than JM1 BP\*\*\*\*\*402988 (produced before August 24, 2021) 2019-2022 Mazda3 (Mexico built) with VINS starting with 3MZ BP\*\*\*\*\*300007 (produced before Jan. 12, 2022) 2020-2022 CX-30 (Mexico built) with VINS starting with 3MV DM\*\*\*\*\*\*402754 (produced before Jan. 12, 2022)

#### **DESCRIPTION**

Some customers may complain that it is difficult to open/close the fuel-filler lid when pressed. This is caused by production variances, where if there is an excess gap (3) between the fuel-filler lid panel (1) and the fuel-filler box hinge (2), the operation stroke may be larger than designed and result in a difficult to lock/unlock operation of the fuel-filler lid lock actuator.





To eliminate this concern, the operation stroke of the fuel-filler lid lock actuator rod has been changed to reduce the play of the actuator rod.

Customers having this concern should have their vehicle repaired using the following repair procedure.

## **REPAIR PROCEDURE**

1. Verify customer concern.

Page 1 of 3

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Last Issued : 04/07/2025

**NOTE:** If the subject vehicle has a deformed fuel-filler panel, perform TSB 09-007/25 (FUEL-FILLER LID PANEL IS DEFORMED), then retest it to see if the fuel-filler lid panel is still difficult to open. If the fuel-filler lid panel is still difficult to open, proceed to Step 2.

- 2. Measure the gap between the fuel-filler lid panel and the fuel-filler box hinge.
  - If the gap is less than 2 mm, proceed to Step 3.
  - If the gap is 2 mm or larger, the subject vehicle is not applicable to this service bulletin. Refer to TSB 09-007/25 (FUEL-FILLER LID PANEL IS DEFORMED).
- 3. Replace the fuel-filler lid box according to the instructions on MGSS.
  - Mazda3 (FUEL-FILLER LID LOCK ACTUATOR REMOVAL/INSTALLATION)
  - CX-30 (FUEL-FILLER LID LOCK ACTUATOR REMOVAL/INSTALLATION
- 4. Verify repair.

## PARTS INFORMATION

Bulletin No.: 09-017/25

| Parts Number | Description         | Qty. | Notes   |
|--------------|---------------------|------|---|
| BCJH-42-420L | Box, Filler         | 1    | Mazda3 4SD (Japan Built)  |
| BDMT-42-420L | Box, Filler         | 1    | Mazda3 5HB (Japan Built)  |
| BDTS-42-420J | Box, Filler         | 1    | Mazda3 (Mexico Built)   |
| DGH9-42-420E | Box, Filler         | 1    | CX-30 (Mexico Built)  |
| ****-69-***  | Label, Fuel Warning | 1    | The part name depends on the part number.<br>Refer to the "NOTE" below. |

**NOTE:** If the removed fuel-filler lid has a fuel warning label attached, check the part number using the GEPC and VIN and order it as a related part.

## **WARRANTY INFORMATION**

## NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

| Warranty Type | А  |
|---------------|----|
| Symptom Code  | 74 |
| Damage Code   | 99 |

Page 2 of 3

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

| Bulletin No.: 09-017/25 | Last Issued : 04/07/2025 |
|-------------------------|--------------------------|
|-------------------------|--------------------------|

| Part Number Main Cause          | 5555-SP-Z01                        |
|---------------------------------|------------------------------------|
| Quantity                        | 0                                  |
| Operation Number / Labor Hours: | (Mazda3 4SD 2WD / 4WD and 5HB 2WD) |
|                                 | XXT3SERX / 1.1 Hrs.                |
|                                 | (Mazda3 5HB 4WD)                   |
|                                 | XXT3SFRX / 1.2 Hrs.                |
|                                 | (CX-30 2WD / 4WD)                  |
|                                 | XXT3SGRX / 1.1 Hrs.                |

**NOTE:** Claim the fuel filler box and the fuel warning label as related parts if ordered.

Page 3 of 3

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.