

<b>REFERENCE:</b>	<b>TSB:</b> 08-142-25 <b>GROUP:</b> 08 - Electrical	<b>Date:</b>	May 3, 2025	<b>REVISION:</b>	08-112-24
<b>VEHICLES AFFECTED:</b>	<b>2024 (WS) Wagoneer / Grand Wagoneer</b> This bulletin applies to vehicles built on or before equipped with Hands Free Power Liftgate (Sales Code JK2).			<b>MARKET APPLICABILITY:</b> <input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH	
<b>CUSTOMER SYMPTOM:</b>	<b>Customers may experience one or more of the following symptoms:</b> <ul style="list-style-type: none"> <li>**Power Liftgate does not open or close the gate.**</li> <li>Liftgate latch releases after pressing exterior handle switch, but gate does not power open.</li> </ul>				
<b>CAUSE:</b>	PLGM Software				

This bulletin supersedes Technical Service Bulletin (TSB) 08-112-24, date of issue April 23, 2024, which should be removed from your files. All revisions are highlighted with **\*\*asterisks\*\*** and include removing build date (not highlighted with asterisks), new LOP, updated Customer Symptom, updated Repair Procedure step.

**REPAIR SUMMARY:**

This bulletin involves updating the PLGM with the latest software.

**CLAIMS DATA:**

Labor Operation No:	Labor Description	Skill Category	Labor Time
**18-19-31-9T	Module, Power Liftgate Module (PLGM) - Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.**
Failure Code	CC	Customer Concern	

**The dealer must use failure code CC with this Technical Service Bulletin.**

- If the customer's concern matches the SYMPTOM identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

**SPECIAL TOOLS/EQUIPMENT:**

Description	Ref. No.	Notes
wiTECH or Equivalent	-	-

## DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If Diagnostic Trouble Codes (DTCs) or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

## REPAIR PROCEDURE:

**NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.**

**NOTE: If this flash process is interrupted/aborted, the flash should be restarted.**

1. Does the PLGM module have the latest software already installed?
  - YES>>> This bulletin has been completed.
  - NO>>> Proceed to [Step 2](#).
2. Reprogram the PLGM with the latest software. **\*\*If issues arise when flashing a module using the wiTECH Diagnostic Application, please submit a ticket to the Helpdesk. The helpdesk can be found within the Help menu.\*\***
3. Perform a power liftgate calibration. Refer to the detailed service procedures available in DealerCONNECT/Service Library under>08 Electrical/8N Power Systems/Power Liftgate/Standard Procedure Power Liftgate Calibration.
4. Clear any DTCs that may have been set in any modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

## POLICY:

Reimbursable within the provisions of the warranty.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*