

Rattling or Squeaking Noises in the Area of the Rear Lid: Check Rear Lid Lock for Damage and Rework it (62 / 24)

Model Line: **Macan (XAB)**

Model Year: **As of 2024**

Concerns: **Upper part of rear lid lock (rear lid lock)**

Information: **Customers complain about rattling or squeaking noises from the lock area of the rear lid.**

Cause: Different pre-tensioning of the entire tailgate system can lead to movement between the catch bar and catch hook in the lock.

Action: If the noises can be clearly attributed to the rear lid lock and are not caused by other components, **check the rear lid lock and then rework the catch hook.**

Required parts and materials



Information

No parts are required for checking and cleaning the rear lid lock.

Parts Info:

Part No.	Designation	Number
95C827447A	⇒ Lid lock	1 piece
PAF912032	⇒ M8 x 22 countersunk screw with internal serration	2 pieces

Material: **Required materials** (usually already available in the Porsche Center)

Part No.	Designation	Quantity
95856490200	⇒ Grease	Quantity as required

Required Tools

Tool:

- Torque wrench, 6-50 Nm (4.5-37 ftlb.), e.g. **V.A.G 1331A - torque spanner, 6-50 Nm (4.5-37 ftlb.)**

Check rear lid lock

- Work Procedure: 1 Remove the trim panel for rear lid.
 ⇒ *Technical Information '70871900 Remove and install trim panel for rear lid'*
- 2 Check rear lid lock for dirt, damage and wear.

Result of check	Action
No abnormalities present on the rear lid lock.	Continue with: ⇒ <i>Technical Information '70871900 Rework rear lid lock'</i>
Contamination present on the rear lid lock.	Remove dirt, dust, or residue that is on the rear lid lock or catch hook using a suitable cleaning agent and a clean cloth. Then continue with: ⇒ <i>Technical Information '70871900 Rework rear lid lock'</i>
Damage / wear present on rear lid lock.	Replace rear lid lock ⇒ <i>Technical Information '558719 Remove and install upper part of rear lid lock'</i> and finally continue with: ⇒ <i>Technical Information '558719 Rework rear lid lock'</i>

Rework rear lid lock**WARNING****Moving components**


- **Crushing or severance of limbs**
- ⇒ **Do not reach into the danger area.**
- ⇒ **Secure the system against accidental activation.**
- ⇒ **Keep third parties away from the danger area.**

**Information**

For a better overview, the work procedure is shown on an uninstalled rear lid lock.
 The rear lid lock need **not** be uninstalled as part of this rework.


- Work Procedure: 1 Apply grease to catch hook.

- 1.1 Lock catch hook ⇒ Rear lid lock (example illustration) -1- in the **catching position** ⇒ Rear lid lock (example illustration) -Circle-shown.



Rear lid lock (example illustration)

- 1.2 Apply lubricating grease ⇒ Rework area -Circle- to the marked area ⇒ Rework area -green-.
- 1.3 Release rear lid lock.
- 1.4 Remove any leftover lubricating grease on the back panel or rear lid lock housing.



Rework area

- 2 **Only if the rear lid lock was replaced due to damage or wear:**
Check adjustment of rear lid and re-adjust if necessary.
⇒ Technical Information '559015 Adjusting rear lid'
- 3 Install the trim panel for rear lid.
⇒ Technical Information '70871900 Remove and install trim panel for rear lid'

Labor position and PCSS encryption

Labor position:

APOS	Labor operation	I No.
55870145	Check and rework rear lid lock	
55870146	Check, clean and rework rear lid lock	
55870147	Check, replace and rework rear lid lock	
55901550	Adjusting rear lid	

PCSS encryption:

Location (FES5)	55870	Upper part lid lock rear
Damage type (SA4)	1025	installed loosely

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2025 Porsche Cars North America, Inc.